



# MX-Sensor\_V4.00 Function List (Note:For reference only)

NOTES:  
 ● This function is supported.    ○ This function is not supported.    ▲ This function is a new feature in this version.    Mark explaining (Red:New, Yellow: Modify)

Special Declaration:  
 1).If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.  
 2).All the Automatic Relearn Procedure for MX-Sensor,the drive speed must be controled between 16 mph (25 km/h) and 64 mph (100 km/h).

| SN.   | Mark et | Make      | Model            | Year Range      | Feature | OBD-II Function | Programming Status | Tires | Relearn Type (A=Automatic, S=Stationary, O=OBD) | Frequenc y | Sensor Manufactuer | OE Part NO.               | Manufacturer Sensor #       | Number on Sensor#         |
|-------|---------|-----------|------------------|-----------------|---------|-----------------|--------------------|-------|-------------------------------------------------|------------|--------------------|---------------------------|-----------------------------|---------------------------|
| C1024 | EU      | Cadillac  | SRX              | 2007/01-2009/12 |         | ○               | ●                  | 4     | S                                               | 433Mhz     | Schrader           | 20922901                  | 90518390                    | 20922901                  |
| C1025 | EU      | Cadillac  | SRX              | 2010/01-2016/12 |         | ○               | ●                  | 4     | S                                               | 433Mhz     | Schrader           | 25789964                  | 90518185                    | 25789964                  |
| B0270 | EU      | Geely     | EC7              | 2014/01-2014/12 | 433Mhz  | ○               | ●                  | 4     |                                                 | 433Mhz     | TTE                | 06703309                  |                             | 6703309                   |
| B0532 | EU      | Peugeot   | Expert           | 2014/06-2016/06 |         | ●               | ●                  | 4     |                                                 | 433Mhz     | Schrader           | 9811764480/<br>9808859080 |                             | 9808859080                |
| B0535 | EU      | Peugeot   | Partner          | 2014/06-2016/06 |         | ○               | ●                  | 4     | Copy only                                       | 433Mhz     | Schrader           | 9811536380                |                             | 9811536380                |
| A0227 | EU      | Subaru    | C-Concept        | 2014/06-2016/06 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0228 | EU      | Subaru    | Forester         | 2014/01-2016/06 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0229 | EU      | Subaru    | Impreza          | 2014/01-2016/06 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0230 | EU      | Subaru    | Justy            | 2014/01-2015/12 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0231 | EU      | Subaru    | Legacy           | 2014/10-2016/06 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0232 | EU      | Subaru    | Outback          | 2014/01-2016/06 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ001/<br>28103FJ000 |                             |                           |
| A0233 | EU      | Subaru    | Trezia           | 2014/01-2016/06 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0234 | EU      | Subaru    | Tribeca          | 2014/01-2016/06 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0235 | EU      | Subaru    | WRX              | 2014/01-2014/12 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0236 | EU      | Subaru    | XV               | 2014/01-2016/06 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0253 | EU      | Toyota    | Proace           | 2014/06-2015/12 |         | ●               | ●                  | 4/5   |                                                 | 433Mhz     | Schrader           | 9808859080                |                             | 9808859080                |
| A0682 | EU      | Hyundai   | iMax             | 2015/01-2015/12 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Continental        | 529334H100                |                             | S180052072                |
| A0683 | EU      | Hyundai   | iLoad            | 2015/01-2015/12 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Continental        | 529334H100                |                             | S180052072                |
| A0686 | EU      | Hyundai   | Veracruz         | 2009/01-2013/12 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Lear               | 529333J000                | 701002                      | 52933-3J000               |
| A0692 | EU      | KIA       | Soul EV          | 2014/06-2016/06 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 52933B2100                |                             | 52933-B2100               |
| A0711 | EU      | Lexus     | RX 200T          | 2016/01-2016/12 |         | ●               | ●                  | 4/5   | O                                               | 433Mhz     | Pacific            | 4260748020                | PAXPMVC215                  | 42607-48020-VK            |
| A0712 | EU      | Toyota    | Land Cruiser 200 | 2015/01-2016/12 |         | ●               | ●                  | 4/5   | O                                               | 433Mhz     | Pacific            | 4260748020                | PAXPMVC215                  | 42607-48020-VK            |
| A0725 | EU      | Subaru    | Levorg           | 2015/09-2016/12 |         | ●               | ●                  | 4     | O                                               | 433Mhz     | Schrader           | 28103FJ000                |                             |                           |
| A0735 | US      | Toyota    | Land Cruiser     | 2016/01-2016/12 | 315MHz  | ○               | ●                  | 4/5   | Copy only                                       | 315MHz     | Pacific            | 4260748010                | PAXPMVC015                  | 42607-48010               |
| A0736 | US      | Toyota    | Tacoma           | 2016/01-2016/12 | 315MHz  | ●               | ●                  | 4/5   | O                                               | 315MHz     | Pacific            | 4260748010                | PAXPMVC015                  | 42607-48010               |
| A0737 | US      | Toyota    | Avalon           | 2016/01-2016/12 | 315MHz  | ○               | ●                  | 4/5   | Copy only                                       | 315MHz     | Pacific            | 4260748010                | PAXPMVC015                  | 42607-48010               |
| A0738 | EU      | Hyundai   | Mistra           | 2015/06-2016/06 | 433MHz  | ○               | ●                  | 4     | A/O                                             | 433Mhz     | Continental        | 529333N100/<br>529332M650 | S180052092C                 |                           |
| A0739 | EU      | Renault   | Talisman         | 2015/06-2016/06 |         | ○               | ●                  | 4     | A                                               | 433Mhz     | Continental        | 407004CB0A                | S180150006                  | S180150006D               |
| A0740 | EU      | Renault   | Spider           | 2010/03-2016/06 |         | ○               | ●                  | 4     | Copy only                                       | 433Mhz     | Continental        | 407003743R/<br>407000435R | S180052064A/<br>S180084700Z | S180052064/<br>S180052004 |
| A0741 | EU      | Renault   | Megane IV        | 2016/01-2016/12 |         | ○               | ●                  | 4     | A                                               | 433Mhz     | Continental        | 407004CB0A                | S180150006                  | S180150006D               |
| A0744 | EU      | Suzuki    | Carry Van        | 2015/04-2016/06 |         | ○               | ●                  | 4     | C                                               | 433Mhz     | Continental        | 4313961M00                | S180052024Z                 | S180052024                |
| A0745 | EU      | Suzuki    | Celerio          | 2014/03-2016/06 |         | ○               | ●                  | 4     | C                                               | 433Mhz     | Continental        | 4313961M00                | S180052024Z                 | S180052024                |
| A0746 | EU      | Suzuki    | Kizashi          | 2014/06-2016/06 |         | ○               | ●                  | 4     | C                                               | 433Mhz     | Continental        | 4313961M00                | S180052024Z                 | S180052024                |
| A0747 | EU      | Suzuki    | Splash           | 2013/09-2016/06 |         | ○               | ●                  | 4     | C                                               | 433Mhz     | Continental        | 4313961M00                | S180052024Z                 | S180052024                |
| A0748 | EU      | Ssangyong | Chairman         | 2014/06-2016/06 |         | ○               | ●                  | 4     | A                                               | 433Mhz     | Schrader           | 4199034000                |                             | 4199034000                |
| A0749 | EU      | Toyota    | GT86             | 2014/01-2016/06 |         | ●               | ●                  | 4/5   | O                                               | 433Mhz     | Pacific            | SU00305268                |                             |                           |
| A0750 | EU      | Infiniti  | Q30              | 2015/10-2016/12 |         | ●               | ●                  | 4     | O/A                                             | 433Mhz     | Pacific            | 407006WY0A                |                             | PMV-CA14                  |

|       |    |               |                     |                 |         |   |   |     |           |        |             |                           |             |                                          |
|-------|----|---------------|---------------------|-----------------|---------|---|---|-----|-----------|--------|-------------|---------------------------|-------------|------------------------------------------|
| A0751 | EU | Infiniti      | QX30                | 2016/01-2016/12 |         | ● | ● | 4   | 0/A       | 433Mhz | Pacific     | 407006WY0A                |             | PMV-CA14                                 |
| A0752 | EU | Hyundai       | i10                 | 2007/10-2013/10 |         | ● | ● | 4   | 0         | 433Mhz | Continental | 529332L600                | S180014820Z | S180030002                               |
| A0753 | EU | KIA           | Cee'd SW            | 2006/01-2012/08 |         | ● | ● | 4   | 0         | 433Mhz | Continental | 529332L600                | S180014820Z | S180030002                               |
| A0754 | EU | KIA           | Cee'd SW            | 2012/09-2016/06 |         | ● | ● | 4   | 0         | 433Mhz | Continental | 529333N100                | S180052092Z | S180052092                               |
| A0755 | EU | Renault       | Fluence             | 2016/01-2016/12 |         | ○ | ● | 4   | A         | 433Mhz | Continental | 407004CB0A                | S180150006  | S180150006                               |
| A0757 | EU | Renault       | Latitude            | 2016/01-2016/12 |         | ○ | ● | 4   | A         | 433Mhz | Continental | 407004CB0A                | S180150006  | S180150006                               |
| A0758 | EU | Renault       | Scenic IV           | 2016/01-2016/12 |         | ○ | ● | 4   | A         | 433Mhz | Continental | 407004CB0A                | S180150006  | S180150006                               |
| B0273 | EU | JAC           | Refine S3           | 2015/01-2015/12 | 433MHz  | ○ | ● | 4   | S         | 433Mhz | Schrader    | TP3040001                 |             |                                          |
| B0852 | EU | Volvo         | S90                 | 2016/01-2016/12 |         | ○ | ● | 4   |           | 433Mhz | Schrader    | 31362304                  |             |                                          |
| B0853 | EU | Volvo         | V90                 | 2015/04-2016/12 |         | ○ | ● | 4   |           | 433Mhz | Schrader    | 31362304                  |             |                                          |
| B0854 | EU | Mercedes      | GLK Class           | 2015/10-2016/12 |         | ● | ● | 4   | A         | 433Mhz | Schrader    | A0009050030               |             |                                          |
| C0051 | EU | Chrysler      | 300                 | 2014/06-2016/06 |         | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029400AD                |             | 56029400AC/<br>56029400AD                |
| C0222 | EU | Opel/Vauxhall | Antara              | 2014/06-2015/12 |         | ○ | ● | 4   | Copy only | 433Mhz | Schrader    | 13581561                  |             | 13581561                                 |
| A0022 | EU | Hyundai       | H-1/i800/H300       | 2014/03-2015/12 |         | ● | ● | 4   | 0         | 433Mhz | Continental | 529334H100                |             | S180052072                               |
| C0321 | US | Cadillac      | ATS-V               | 2014/01-2015/12 | 315MHz  | ○ | ● | 4   | S         | 315Mhz | Schrader    | 20964159                  |             | 20964159                                 |
| C1020 | EU | Chrysler      | Grand Voyager       | 2016/01-2016/12 |         | ○ | ● | 4/5 | A         | 433Mhz | Continental | 68105280AF                |             |                                          |
| C1021 | EU | Chrysler      | Sebring Convertible | 2007/02-2016/12 |         | ○ | ● | 4/5 | A         | 433Mhz | Schrader    | 56029359AC                |             | 56029359AC/<br>56029359AB/<br>56029359AA |
| C1022 | EU | Jeep          | B-CUV               | 2014/10-2016/12 |         | ○ | ● | 4/5 | A         | 433Mhz | Continental | 68105280AF                |             |                                          |
| C1023 | EU | Jeep          | D-CUV               | 2013/05-2016/12 |         | ○ | ● | 4/5 | A         | 433Mhz | Continental | 68105280AF                |             |                                          |
| C0026 | EU | Cadillac      | SRX                 | 2005/01-2006/12 |         | ● | ● | 4   | S         | 433Mhz | Schrader    | 25774007                  | 90518110    | 25774007                                 |
| B0242 | EU | Citroen       | C4 Aircross         | 2014/04-2016/06 |         | ○ | ● | 4   | S         | 433Mhz | Continental | 4250C477/<br>1612477080   | S180052094Z | S180052094                               |
| B0277 | EU | Jaguar        | F-Type              | 2013/03-2016/06 |         | ○ | ● | 4   | A         | 433Mhz | Continental | C2D21599                  | S180052028C | S180052028                               |
| B0322 | EU | Land Rover    | FreeLander          | 2005/01-2015/12 |         | ● | ● | 4/5 | A         | 433Mhz | Continental | LR021935                  | S180084770Z | S180052022                               |
| B0331 | EU | Land Rover    | Range Rover         | 2015/06-2016/12 |         | ○ | ● | 4/5 | A         | 433Mhz | Continental | GX631A159AA               |             | S180052076A                              |
| C0240 | EU | Opel/Vauxhall | Insigna             | 2008/01-2014/04 |         | ● | ● | 4   | A/0       | 433Mhz | Schrader    | 13348393                  |             | 13313134/<br>13348393/<br>13327259       |
| B0518 | EU | Peugeot       | 4008                | 2014/06-2016/06 |         | ○ | ● | 4   | S         | 433Mhz | Continental | 4250C477/<br>1612477080   | S180052094Z | S180052094                               |
| B0849 | EU | Volvo         | XC90                | 2011/01-2016/06 |         | ● | ● | 4   | A         | 433Mhz | Schrader    | 31329981/<br>30748354     | 90518149    | 30748354                                 |
| B0848 | EU | Volvo         | XC90                | 2015/01-2016/06 |         | ● | ● | 4   | A         | 433Mhz | Schrader    | 31362304                  |             | 30748354                                 |
| B0850 | EU | Volvo         | XC90 (LCV)          | 2015/06-2016/06 |         | ● | ● | 4   | A         | 433Mhz | Schrader    | 31362304                  |             | 30748354                                 |
| B0851 | EU | Volvo         | XC90 (LCV)          | 2015/06-2016/06 |         | ● | ● | 4   | A         | 433Mhz | Schrader    | 31329981/<br>30748354     | 90518149    | 30748354                                 |
| C0359 | US | Cadillac      | Escalade            | 2007/01-2007/12 | Snap in | ● | ● | 4   | S         | 315Mhz | Schrader    | 25799331                  |             | 25799331                                 |
| C0716 | US | Ford          | Explorer            | 2013/01-2015/09 | 315MHz  | ● | ● | 4   | S         | 315Mhz | Schrader    | CM5T1A150AA               |             | CM5T-1A180-AA/<br>CM5T-1A150-AA          |
| C0715 | US | Ford          | Explorer            | 2015/10-2016/12 | 315MHz  | ○ | ● | 4   | S         | 315Mhz | Schrader    | F2GT1A180AB               |             | F2GT1A180AB                              |
| A0425 | US | KIA           | Sedona              | 2009/01-2014/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Lear        | 529332G200                |             | 52933-2G200                              |
| A0429 | US | KIA           | Sorento             | 2009/01-2010/12 | 315Mhz  | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333E000                |             |                                          |
| B0323 | US | Land Rover    | LR2                 | 2008/01-2013/12 | 315MHz  | ● | ● | 4/5 | A         | 315Mhz | Continental | LR021936/<br>LR018859     |             |                                          |
| A0032 | EU | Hyundai       | ix20                | 2008/01-2013/09 | JC      | ● | ● | 4   | 0         | 433Mhz | Continental | 529331J000                | S180084710Z | S180052012                               |
| A0034 | EU | Hyundai       | ix20                | 2013/10-2016/06 | IX5     | ● | ● | 4   | 0         | 433Mhz | Continental | 33N100/ 529332            | S180052092Z | S180052092                               |
| A0035 | EU | Hyundai       | ix35                | 2010/01-2013/08 |         | ● | ● | 4   | 0         | 433Mhz | TRW         | 529333M000                |             | 52933-3M000                              |
| A0039 | EU | Hyundai       | ix55                | 2009/01-2012/12 |         | ● | ● | 4   | 0         | 433Mhz | Lear        | 529333J000                | 701002      | 52933-3J000                              |
| A0042 | EU | Hyundai       | Santa Fe            | 2009/01-2012/05 |         | ● | ● | 4   | 0         | 433Mhz | Lear        | 529332B000                |             | 52933-2B000                              |
| A0069 | EU | KIA           | Pro Cee'd           | 2008/01-2012/08 |         | ● | ● | 4   | 0         | 433Mhz | Continental | 529332L600/<br>529332L000 | S180014820Z | S180030002                               |
| A0070 | EU | KIA           | Pro Cee'd           | 2012/09-2016/06 |         | ● | ● | 4   | 0         | 433Mhz | Continental | 529333N100                | S180052092Z | S180052092                               |

|       |    |               |                 |                 |         |   |   |   |       |        |             |                           |                       |                                    |
|-------|----|---------------|-----------------|-----------------|---------|---|---|---|-------|--------|-------------|---------------------------|-----------------------|------------------------------------|
| A0080 | EU | KIA           | Sorento         | 2012/07-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 529333N100/<br>529332M650 | S180052092Z           | S180052092                         |
| A0316 | US | Hyundai       | Azera           | 2012/01-2013/12 | 315MHz  | ● | ● | 4 | 0     | 315Mhz | TRW         | 529333V000                | 225816-104            | 225816-104                         |
| A0346 | US | Hyundai       | Sonata Hybrid   | 2015/01-2016/12 | 315MHz  | ● | ● | 4 | 0     | 315Mhz | Continental | 52933A5000                | S180052041F           | S180052041                         |
| A0028 | EU | Hyundai       | i30             | 2011/11-2016/06 | GD      | ● | ● | 4 | 0     | 433Mhz | Continental | 529333N100                | S180052092Z           | S180052092                         |
| B0780 | EU | Volvo         | V50             | 2012/01-2014/06 |         | ● | ○ | 4 | A     | 433Mhz | Continental | 31302096                  | S180052020            | S180052020                         |
| C0213 | EU | Opel/Vauxhall | Adam            | 2012/01-2014/07 |         | ● | ● | 4 | A/O   | 433Mhz | Schrader    | 13581562                  |                       | 13581562                           |
| C0218 | EU | Opel/Vauxhall | Ampera          | 2005/07-2016/06 |         | ● | ● | 4 | A/O   | 433Mhz | Schrader    | 13348393                  | 90518407              | 13348393                           |
| C0229 | EU | Opel/Vauxhall | Astra J         | 2009/10-2011/09 |         | ● | ● | 4 | 0     | 433Mhz | Schrader    | 13348393                  |                       | 13313134/<br>13327259/<br>13348393 |
| C0228 | EU | Opel/Vauxhall | Astra J         | 2011/10-2014/05 |         | ● | ● | 4 | A/O   | 433Mhz | Schrader    | 13348393                  |                       | 13313134/<br>13327259/<br>13348393 |
| C0233 | EU | Opel/Vauxhall | Cascada         | 2013/01-2014/05 |         | ● | ● | 4 | A/O   | 433Mhz | Schrader    | 13348393                  | 90518407              | 13348393                           |
| C0231 | EU | Opel/Vauxhall | Cascada         | 2014/06-2016/06 |         | ● | ● | 4 | A/O   | 433Mhz | Schrader    | 13581560                  |                       | 13581560                           |
| C0239 | EU | Opel/Vauxhall | Insigna         | 2014/05-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Schrader    | 13581560                  |                       | 13581560                           |
| C0250 | EU | Opel/Vauxhall | Movano B        | 2014/06-2016/12 |         | ● | ● | 4 | A     | 433Mhz | Schrader    | 407001628R                |                       | 407001628R-B                       |
| C0256 | EU | Opel/Vauxhall | Vivaro B        | 2014/03-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Schrader    | 407001628R                |                       | 407001628R-B                       |
| C0264 | EU | Opel/Vauxhall | Zafira Tourer C | 2009/01-2014/05 |         | ● | ● | 4 | A/O   | 433Mhz | Schrader    | 13348393                  |                       | 13313134/<br>13327259/<br>13348393 |
| C0262 | EU | Opel/Vauxhall | Zafira Tourer C | 2014/06-2016/06 |         | ● | ● | 4 | O/S   | 433Mhz | Schrader    | 13581560                  |                       | 13581560                           |
| B0288 | US | Jaguar        | XF              | 2010/01-2015/12 | 433MHz  | ● | ● | 4 | A     | 433Mhz | Continental | C2Z15016                  | S180084770Z           | S120123002H                        |
| B0289 | US | Jaguar        | XF              | 2010/01-2015/12 | 315MHz  | ● | ● | 4 | A     | 315Mhz | Continental | C2Z15017/<br>C2C41656     |                       |                                    |
| A0036 | EU | Hyundai       | ix35            | 2013/09-2015/12 | Lo Line | ● | ● | 4 | 0     | 433Mhz | TRW         | 529332S410/<br>529332S400 |                       | 52933-2S400                        |
| A0037 | EU | Hyundai       | ix35            | 2013/09-2015/12 | Hi Line | ● | ● | 4 | A/O   | 433Mhz | TRW         | 529332Y450                |                       | 52933-2Y450                        |
| A0043 | EU | Hyundai       | Santa Fe        | 2012/06-2013/03 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 52933A5100                | S180052040E           |                                    |
| A0045 | EU | Hyundai       | Solaris         | 2014/01-2015/12 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 529331J000                | S180084710Z           | S180052012                         |
| A0046 | EU | Hyundai       | Sonata          | 2013/06-2015/12 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 529331J000                | S180084710Z           | S180052012                         |
| A0049 | EU | Hyundai       | Veloster        | 2011/03-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Schrader    | 529332V100                | 90518481              | 52933-2V100                        |
| A0050 | EU | Infiniti      | EX              | 2008/01-2013/12 |         | ● | ● | 4 | 0     | 433Mhz | Schrader    | 40700JY00C/<br>407001AY0A | 90518394              | 40700-JY00C                        |
| A0051 | EU | Infiniti      | FX              | 2008/03-2013/12 |         | ● | ● | 4 | 0     | 433Mhz | Schrader    | 40700JY00C                | 90518295/<br>90518394 | 40700-JY00C                        |
| A0052 | EU | Infiniti      | G37 Coupe       | 2008/06-2013/06 |         | ● | ● | 4 | 0     | 433Mhz | Schrader    | 40700JY00C                | 90518295/<br>90518394 | 40700-JY00C                        |
| A0053 | EU | Infiniti      | G37 Sedan       | 2008/06-2013/03 |         | ● | ● | 4 | 0     | 433Mhz | Schrader    | 40700JY00C                | 90518295/<br>90518394 | 40700-JY00C                        |
| A0055 | EU | Infiniti      | M               | 2010/01-2013/12 |         | ● | ● | 4 | 0     | 433Mhz | Pacific     | 407001LL0C                | PMV-107U              | 40700-1LL0C                        |
| A0057 | EU | Infiniti      | Q50             | 2013/04-2016/06 |         | ● | ● | 4 | S     | 433Mhz | Continental | 407003JA0A                | S180052036Z           | S180052036                         |
| A0058 | EU | Infiniti      | Q60             | 2013/07-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Pacific     | 407006WY0B                |                       | PMV-CA14                           |
| A0059 | EU | Infiniti      | Q70             | 2014/01-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Pacific     | 407006WY0B                |                       | PMV-CA14                           |
| A0060 | EU | Infiniti      | QX50            | 2014/01-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Pacific     | 407006WY0B                |                       | PMV-CA14                           |
| A0063 | EU | Infiniti      | QX70            | 2014/01-2016/06 |         | ● | ● | 4 | S/O/A | 433Mhz | Pacific     | 407006WY0B                |                       | PMV-CA14                           |
| A0066 | EU | KIA           | Carens          | 2012/01-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 529333N100                | S180052092Z           | S180052092                         |
| A0067 | EU | KIA           | Cee'd           | 2006/01-2012/02 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 529332L600                | S180014820Z           | S180030002                         |
| A0068 | EU | KIA           | Cee'd           | 2012/03-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 529333N100                | S180052092Z           | S180052092                         |
| A0071 | EU | KIA           | Optima          | 2011/01-2013/07 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 529331J000                | S180084710Z           | S180052012                         |
| A0072 | EU | KIA           | Optima          | 2013/08-2015/09 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 529333N100                | S180052092Z           | S180052092                         |
| A0073 | EU | KIA           | Picanto         | 2014/04-2016/06 |         | ● | ● | 4 | 0     | 433Mhz | Continental | 529333N100                | S180052092Z           | S180052092                         |
| A0075 | EU | KIA           | Rio             | 2012/01-2014/06 |         | ● | ● | 4 | 0     | 433Mhz | TRW         | 529333X300                |                       | 52933-3X300                        |
| A0076 | EU | KIA           | Rio             | 2014/07-2016/06 | Hi line | ● | ● | 4 | 0     | 433Mhz | TRW         | 529333V600                |                       | 52933-3V600                        |
| A0077 | EU | KIA           | Rio             | 2014/07-2016/06 | Lo line | ● | ● | 4 | 0     | 433Mhz | TRW         | 529333X305                |                       | 52933-3X305                        |

|       |    |       |          |                 |  |   |   |     |   |        |             |                                          |             |             |
|-------|----|-------|----------|-----------------|--|---|---|-----|---|--------|-------------|------------------------------------------|-------------|-------------|
| A0078 | EU | KIA   | Sorento  | 2009/01-2012/06 |  | ● | ● | 4   | 0 | 433Mhz | Continental | 529331J000                               | S180084710Z | S180052012  |
| A0081 | EU | KIA   | Soul     | 2009/02-2013/10 |  | ● | ● | 4   | 0 | 433Mhz | Continental | 529331J000                               | S180084710Z | S180052012  |
| A0082 | EU | KIA   | Soul     | 2013/11-2016/06 |  | ● | ● | 4   | 0 | 433Mhz | Schrader    | 52933B2100                               |             | 52933-B2100 |
| A0083 | EU | KIA   | Sportage | 2010/01-2013/12 |  | ● | ● | 4   | 0 | 433Mhz | TRW         | 529333M000                               |             | 52933-3M000 |
| A0085 | EU | KIA   | Sportage | 2014/01-2015/12 |  | ● | ● | 4   | 0 | 433Mhz | TRW         | 529332S410                               |             | 52933-2S410 |
| A0086 | EU | KIA   | Venga    | 2010/06-2014/03 |  | ● | ● | 4   | 0 | 433Mhz | Continental | 529331J000                               | S180084710Z | S180052012  |
| A0087 | EU | KIA   | Venga    | 2014/04-2016/06 |  | ● | ● | 4   | A | 433Mhz | Continental | 529333N100/<br>529332M650                | S180052092Z | S180052092  |
| A0088 | EU | Lexus | C-CUV    | 2014/11-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0089 | EU | Lexus | CT       | 2014/06-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0090 | EU | Lexus | CT 200h  | 2014/05-2015/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0091 | EU | Lexus | ES 250   | 2013/06-2014/04 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260730070                               | PMV-107J    | 42607-30070 |
| A0092 | EU | Lexus | ES 250   | 2014/05-2016/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0093 | EU | Lexus | ES 300h  | 2013/06-2014/04 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260730070                               | PMV-107J    | 42607-30070 |
| A0094 | EU | Lexus | ES 300h  | 2014/05-2016/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0095 | EU | Lexus | ES 350   | 2008/10-2012/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260750011                               | PMV-107K    |             |
| A0096 | EU | Lexus | ES 350   | 2012/06-2014/04 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260730070                               | PMV-107J    | 42607-30070 |
| A0097 | EU | Lexus | ES 350   | 2014/05-2016/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0098 | EU | Lexus | GS 250   | 2012/01-2014/08 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260730070                               | PMV-107J    | 42607-30070 |
| A0099 | EU | Lexus | GS 250   | 2014/09-2015/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0100 | EU | Lexus | GS 300   | 2006/08-2011/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260750011                               | PMV-107K    |             |
| A0101 | EU | Lexus | GS 300h  | 2013/10-2014/08 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260750011                               | PMV-107K    |             |
| A0102 | EU | Lexus | GS 300h  | 2014/09-2015/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0104 | EU | Lexus | GS 350   | 2006/08-2014/08 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260750011                               | PMV-107K    |             |
| A0105 | EU | Lexus | GS 350   | 2014/09-2015/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0106 | EU | Lexus | GS 430   | 2006/08-2011/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260750011                               | PMV-107K    |             |
| A0107 | EU | Lexus | GS 450h  | 2006/02-2011/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260750011                               | PMV-107K    |             |
| A0108 | EU | Lexus | GS 450h  | 2012/01-2014/08 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260730070                               | PMV-107J    | 42607-30070 |
| A0109 | EU | Lexus | GS 450h  | 2014/09-2015/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0110 | EU | Lexus | GS 460   | 2006/08-2011/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260750011                               | PMV-107K    |             |
| A0111 | EU | Lexus | GX 400   | 2013/08-2014/04 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260730070                               | PMV-107J    | 42607-30070 |
| A0112 | EU | Lexus | GX 400   | 2014/05-2016/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |
| A0113 | EU | Lexus | GX 460   | 2013/08-2014/04 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260730070                               | PMV-107J    | 42607-30070 |
| A0114 | EU | Lexus | GX 460   | 2014/05-2016/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031 | PMV-C210    |             |

|       |    |       |                  |                 |  |   |   |     |   |        |         |                                                         |                       |                |
|-------|----|-------|------------------|-----------------|--|---|---|-----|---|--------|---------|---------------------------------------------------------|-----------------------|----------------|
| A0115 | EU | Lexus | GX 470           | 2004/01-2009/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0116 | EU | Lexus | IS 250/IS 250C   | 2006/08-2014/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0117 | EU | Lexus | IS 250/IS 250C   | 2014/06-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260742020/<br>4260702030/<br>4260702031/<br>4260730070 | PMV-C210/<br>PMV-107J |                |
| A0118 | EU | Lexus | IS 300C          | 2006/08-2014/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0119 | EU | Lexus | IS 300C          | 2014/06-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260742020/<br>4260702030/<br>4260702031/<br>4260730070 | PMV-C210/<br>PMV-107J |                |
| A0120 | EU | Lexus | IS 300h          | 2013/08-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260742020/<br>4260702030/<br>4260702031/<br>4260730070 | PMV-C210/<br>PMV-107J |                |
| A0121 | EU | Lexus | IS 350/IS 350C   | 2006/08-2014/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0122 | EU | Lexus | IS 350/IS 350C   | 2014/06-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260742020/<br>4260702030/<br>4260702031/<br>4260730070 | PMV-C210/<br>PMV-107J |                |
| A0123 | EU | Lexus | IS F             | 2010/08-2014/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0124 | EU | Lexus | IS F             | 2014/06-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260742020/<br>4260702030/<br>4260702031/<br>4260730070 | PMV-C210/<br>PMV-107J |                |
| A0125 | EU | Lexus | LFA              | 2010/01-2012/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0126 | EU | Lexus | LS 460/LS 460L   | 2006/08-2014/04 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0127 | EU | Lexus | LS 460/LS 460L   | 2014/05-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260742020/<br>4260702030/<br>4260702031                | PMV-C210              |                |
| A0128 | EU | Lexus | LS 600h/LS 600hL | 2006/08-2014/04 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0129 | EU | Lexus | LS 600h/LS 600hL | 2014/05-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260742020/<br>4260702030/<br>4260702031                | PMV-C210              |                |
| A0130 | EU | Lexus | LX 460           | 2008/01-2014/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0131 | EU | Lexus | LX 460           | 2014/06-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260742020/<br>4260702030/<br>4260702031                | PMV-C210              |                |
| A0132 | EU | Lexus | LX 470           | 2005/01-2007/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0133 | EU | Lexus | LX 570           | 2008/01-2014/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0134 | EU | Lexus | LX 570           | 2014/06-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260742020/<br>4260702030/<br>4260702031/<br>4260730070 | PMV-C210              |                |
| A0135 | EU | Lexus | NX300H           | 2014/03-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260730070                                              | PMV-107J              | 42607-30070    |
| A0136 | EU | Lexus | RX 270           | 2006/01-2014/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0137 | EU | Lexus | RX 270           | 2014/06-2015/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260702020/<br>4260702030/<br>4260702031                | PMV-C210              |                |
| A0138 | EU | Lexus | RX 350           | 2004/02-2008/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0139 | EU | Lexus | RX 350           | 2009/01-2014/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0140 | EU | Lexus | RX 350           | 2014/06-2016/06 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260748020                                              | PAXPMVC215            | 42607-48020-VK |
| A0141 | EU | Lexus | RX 400h          | 2004/02-2008/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0142 | EU | Lexus | RX 450h          | 2009/01-2014/05 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |
| A0143 | EU | Lexus | RX 450h          | 2014/06-2015/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260702020/<br>4260702030/<br>4260702031                | PMV-C210              |                |
| A0144 | EU | Lexus | SC 430           | 2001/10-2010/12 |  | ● | ● | 4/5 | 0 | 433Mhz | Pacific | 4260750011                                              | PMV-107K              |                |

|       |    |            |           |                 |         |   |   |   |           |        |             |                                                         |                             |                             |
|-------|----|------------|-----------|-----------------|---------|---|---|---|-----------|--------|-------------|---------------------------------------------------------|-----------------------------|-----------------------------|
| A0145 | EU | Mitsubishi | ASX       | 2014/08-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C477                                                | S180052094Z                 | S180052094                  |
| A0146 | EU | Mitsubishi | Attrage   | 2014/08-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C275                                                | S180052094Z                 | S180150004                  |
| A0147 | EU | Mitsubishi | i-Miev    | 2014/08-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C477                                                | S180052094Z                 | S180052094                  |
| A0148 | EU | Mitsubishi | L200      | 2014/08-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C477                                                | S180052094Z                 | S180052094                  |
| A0149 | EU | Mitsubishi | Lancer    | 2014/08-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C477                                                | S180052094Z                 | S180052094                  |
| A0150 | EU | Mitsubishi | Mirage    | 2014/08-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C275                                                | S180052094Z                 | S180150004                  |
| A0151 | EU | Mitsubishi | Montero   | 2014/10-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C275                                                | S180052094Z                 | S180150004                  |
| A0152 | EU | Mitsubishi | Outlander | 2014/08-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C477                                                | S180052094Z                 | S180052094                  |
| A0153 | EU | Mitsubishi | Pajero    | 2014/07-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C275                                                | S180052094Z                 | S180150004                  |
| A0154 | EU | Mitsubishi | Shogun    | 2014/08-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C275                                                | S180052094Z                 | S180150004                  |
| A0155 | EU | Mitsubishi | Spacestar | 2014/07-2016/06 |         | ● | ● | 4 | C         | 433Mhz | Continental | 4250C275                                                | S180052094Z                 | S180150004                  |
| A0156 | EU | Nissan     | 370Z      | 2008/01-2014/06 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 40700JY00C                                              | 90518295                    | 40700-JY00C                 |
| A0157 | EU | Nissan     | 370Z      | 2014/07-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Pacific     | 407006WY0A/<br>407003HNOB                               | PMV-CA14                    | 40700-6WY0A/<br>40700-3HNOB |
| A0158 | EU | Nissan     | Almera    | 2013/05-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Continental | 407003VU0A                                              | S180052048Z                 | S180052048                  |
| A0159 | EU | Nissan     | B-EV      | 2014/01-2014/12 |         | ● | ● | 4 | 0         | 433Mhz | Continental | 407003VU0A                                              | S180052048Z                 | S180052048                  |
| A0160 | EU | Nissan     | C-Hatch   | 2014/10-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Continental | 407003VU0A                                              | S180052048Z                 | S180052048                  |
| A0161 | EU | Nissan     | Cube      | 2008/01-2014/09 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 40700JY00B                                              | 90518295                    | 40700-JY00B                 |
| A0162 | EU | Nissan     | GT-R      | 2009/02-2013/12 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 40700JY00C                                              | 90518295                    | 40700-JY00C                 |
| A0164 | EU | Nissan     | GT-R      | 2014/01-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Pacific     | 4070062B0A                                              |                             |                             |
| A0165 | EU | Nissan     | Juke      | 2010/06-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Pacific     | 407006WY0B                                              | PMV-CA14                    | 40700-6WY0B                 |
| A0166 | EU | Nissan     | Leaf      | 2014/05-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Pacific     | 407006WY0B                                              | PMV-CA14                    | 40700-6WY0B                 |
| A0167 | EU | Nissan     | Micra     | 2013/01-2014/06 |         | ● | ● | 4 | 0         | 433Mhz | Pacific     | 407001LLOC                                              | PMV-107U                    | 40700-1LLOC                 |
| A0168 | EU | Nissan     | Micra     | 2014/07-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Pacific     | 407006WY0A/<br>407003HNOB                               | PMV-CA14                    | 40700-6WY0A/<br>40700-3HNOB |
| A0169 | EU | Nissan     | Murano    | 2007/10-2014/05 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 40700JY00B                                              | 90518295                    | 40700-JY00B                 |
| A0170 | EU | Nissan     | Murano    | 2014/06-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Pacific     | 407006WY0A                                              | PMV-CA14                    | 40700-6WY0A                 |
| A0171 | EU | Nissan     | Navara    | 2004/10-2014/08 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 40700JY00B                                              | 90518295                    | 40700-JY00B                 |
| A0173 | EU | Nissan     | Navara    | 2014/09-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 40700JY00B                                              | 90518295                    | 40700-JY00B                 |
| A0175 | EU | Nissan     | Note      | 2013/08-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Continental | 407003VU0A                                              | S180052048Z                 | S180052048                  |
| A0176 | EU | Nissan     | NV200     | 2014/04-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Continental | 407003VU0A                                              | S180052048Z                 | S180052048                  |
| A0178 | EU | Nissan     | Patrol    | 2010/01-2014/11 | Y61/Y62 | ● | ● | 4 | 0         | 433Mhz | Pacific     | 407001LLOC/<br>407001LLOD                               | PMV-107U                    | 40700-1LLOC                 |
| A0179 | EU | Nissan     | Pixo      | 2009/01-2014/12 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 40700JY00B                                              | 90518295                    | 40700-JY00B                 |
| A0180 | EU | Nissan     | Primera   | 2002/01-2007/05 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 40700AV600                                              |                             | 40700-AV600                 |
| A0181 | EU | Nissan     | Pulsar    | 2014/07-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Continental | 407003VU0A                                              | S180052048Z/<br>S180052048E | S180052048                  |
| A0182 | EU | Nissan     | Qashqai   | 2013/12-2016/06 |         | ● | ● | 4 | A/O/S     | 433Mhz | Continental | 407003VU0A                                              | S180052048Z                 | S180052048                  |
| A0183 | EU | Nissan     | Sentra    | 2014/08-2015/12 |         | ● | ● | 4 | 0         | 433Mhz | Continental | 407003VU0A                                              | S180052048Z                 | S180052048                  |
| A0184 | EU | Nissan     | Teana     | 2014/01-2015/12 |         | ● | ● | 4 | 0/S       | 433Mhz | Continental | 407003JA0A                                              | S180052036Z                 | S180052036                  |
| A0185 | EU | Nissan     | Tiida     | 2014/07-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Continental | 407003VU0A                                              | S180052048Z                 | S180052048                  |
| A0186 | EU | Nissan     | X-Trail   | 2013/11-2016/06 |         | ● | ● | 4 | A/O/S     | 433Mhz | Continental | 407003VU0A                                              | S180052048Z                 | S180052048                  |
| A0187 | EU | Renault    | Captur    | 2013/01-2015/12 |         | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R                |                             | 407001628R<br>RDE024/RDE026 |
| A0188 | EU | Renault    | Clio III  | 2005/05-2014/05 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 8200253215/<br>8200924614/<br>7701476638/<br>7701478868 | 8200253215                  |                             |
| A0189 | EU | Renault    | Clio IV   | 2014/06-2016/06 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R                |                             | 407001628R<br>RDE024/RDE026 |
| A0191 | EU | Renault    | Espace IV | 2002/07-2014/12 |         | ● | ● | 4 | 0         | 433Mhz | Schrader    | 8200023746/<br>400011621R/<br>407002138R                | 8200023746/<br>8200169160   | 400012631R                  |
| A0192 | EU | Renault    | Espace V  | 2015/01-2016/12 |         | ○ | ● | 4 | A         | 433Mhz | Continental | 407004CB0A                                              | S180150006                  | S180150006                  |

|       |    |           |                   |                 |  |   |   |   |           |        |             |                                          |                             |                               |
|-------|----|-----------|-------------------|-----------------|--|---|---|---|-----------|--------|-------------|------------------------------------------|-----------------------------|-------------------------------|
| A0193 | EU | Renault   | Fluence           | 2010/01-2015/12 |  | ○ | ● | 4 | Copy only | 433Mhz | Continental | 407000435R                               | S180084700Z                 | S180052004                    |
| A0194 | EU | Renault   | Kangoo            | 2014/06-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |                             | 407001628R<br>RDE024/RDE026   |
| A0195 | EU | Renault   | Koleos            | 2008/01-2013/12 |  | ● | ● | 4 | 0         | 433Mhz | Schrader    | 40700JY00C                               | 90518295                    | 40700-JY00C                   |
| A0196 | EU | Renault   | Koleos            | 2014/01-2016/06 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 407003VU0A                               | S180052048Z                 | S180052048                    |
| A0197 | EU | Renault   | Koleos (LCV)      | 2008/02-2015/12 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |                             |                               |
| A0199 | EU | Renault   | Laguna II         | 2000/12-2007/09 |  | ● | ● | 4 | 0         | 433Mhz | Schrader    | 8200023746                               | 8200023746/<br>8200169160   | 400012631R                    |
| A0200 | EU | Renault   | Laguna III        | 2007/10-2015/03 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 407003743R/<br>407000435R                | S180052064A/<br>S180084700Z | S180052064/<br>S180052004     |
| A0201 | EU | Renault   | Latitude          | 2010/09-2015/12 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 407003743R/<br>407000435R                | S180052064A/<br>S180084700Z | S180052064/<br>S180052004     |
| A0202 | EU | Renault   | Master            | 2009/11-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |                             | 407001628R-B<br>RDE024/RDE026 |
| A0203 | EU | Renault   | Megane I          | 2001/01-2002/08 |  | ● | ● | 4 | 0         | 433Mhz | Schrader    | 8200023746                               | 8200023746/<br>8200169160   | 400012631R                    |
| A0204 | EU | Renault   | Megane II         | 2002/09-2008/09 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 407005578R                               | S180014810Z                 | S120123006                    |
| A0205 | EU | Renault   | Megane III        | 2008/10-2015/12 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 407003743R/<br>407000435R                | S180052064A/<br>S180084700Z | S180052064/<br>S180052004     |
| A0206 | EU | Renault   | Modus             | 2004/04-2012/12 |  | ● | ● | 4 | 0         | 433Mhz | Schrader    | 7701478868/<br>8200924614                | 8200253215                  |                               |
| A0207 | EU | Renault   | Scenic I          | 2001/01-2003/04 |  | ● | ● | 4 | 0         | 433Mhz | Schrader    | 407002425R                               | 8200023746/<br>8200169160   | 400012631R                    |
| A0208 | EU | Renault   | Scenic II         | 2003/05-2008/12 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 407005578R                               | S180014810Z                 | S120123006                    |
| A0209 | EU | Renault   | Scenic II restyle | 2006/01-2008/12 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 407005578R                               | S180014810Z                 | S120123006                    |
| A0210 | EU | Renault   | Scenic III        | 2009/01-2015/12 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 407003743R/<br>407000435R                | S180052064A/<br>S180084700Z | S180052064/<br>S180052004     |
| A0211 | EU | Renault   | Scenic RX4        | 2001/01-2003/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 407002138R                               | 8200023746/<br>8200169160   | 400012631R                    |
| A0212 | EU | Renault   | Symbol/Thalia     | 2013/04-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |                             | 407001628R-B<br>RDE024/RDE026 |
| A0213 | EU | Renault   | Trafic            | 2014/01-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |                             | 407001628R-B<br>RDE024/RDE026 |
| A0214 | EU | Renault   | Twingo            | 2007/01-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |                             | 407001628R-B<br>RDE024/RDE026 |
| A0215 | EU | Renault   | Vel Satis         | 2001/09-2009/12 |  | ● | ● | 4 | 0         | 433Mhz | Schrader    | 8200023746                               | 8200023746/<br>8200169160   | 400012631R                    |
| A0216 | EU | Renault   | Wind              | 2010/06-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |                             | 407001628R-B<br>RDE024/RDE026 |
| A0217 | EU | Renault   | Zoe               | 2012/09-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Continental | 407003743R/<br>407000435R                | S180052064A/<br>S180084700Z | S180052064/<br>S180052004     |
| A0218 | EU | Ssangyong | Actyon            | 2014/03-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 4199034000                               |                             | 4199034000                    |
| A0219 | EU | Ssangyong | C-CUV             | 2015/05-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Huf/Beru    | 4199035000                               |                             | 4199035000                    |
| A0220 | EU | Ssangyong | Korando           | 2013/08-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 4199034000                               |                             | 4199034000                    |
| A0221 | EU | Ssangyong | Kyron             | 2014/06-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 4199034000                               |                             | 4199034000                    |
| A0222 | EU | Ssangyong | Nomad             | 2014/06-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 4199034000                               |                             | 4199034000                    |
| A0223 | EU | Ssangyong | Rexton            | 2014/05-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 4199034000                               |                             | 4199034000                    |
| A0224 | EU | Ssangyong | Rodius            | 2014/05-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 4199034000                               |                             | 4199034000                    |
| A0225 | EU | Ssangyong | Tivoli            | 2015/06-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Huf/Beru    | 4199035000                               |                             | 4199035000                    |
| A0226 | EU | Subaru    | BRZ               | 2014/01-2016/06 |  | ● | ● | 4 | 0         | 433Mhz | Pacific     | 28103CA101/<br>28103CA010                |                             |                               |

|       |    |        |              |                 |        |   |   |     |           |        |             |                                             |                                          |                                          |
|-------|----|--------|--------------|-----------------|--------|---|---|-----|-----------|--------|-------------|---------------------------------------------|------------------------------------------|------------------------------------------|
| A0237 | EU | Suzuki | Alto         | 2014/06-2016/06 |        | ○ | ● | 4   | Copy only | 433Mhz | Continental | 4313961M00/<br>4313061M00                   | S180052024Z                              | S180052024                               |
| A0239 | EU | Suzuki | Jimny        | 2014/06-2016/06 |        | ○ | ● | 4   | C         | 433Mhz | Continental | 4313961M00                                  | S180052024Z                              | S180052024                               |
| A0240 | EU | Suzuki | Swift        | 2013/08-2016/06 |        | ○ | ● | 4   | Copy only | 433Mhz | Continental | 4313961M00                                  | S180052024Z                              | S180052024                               |
| A0241 | EU | Suzuki | SX4          | 2014/08-2016/06 |        | ○ | ● | 4   | S         | 433Mhz | Continental | 4313961M00                                  | S180052024Z                              | S180052024                               |
| A0242 | EU | Suzuki | SX4 S-Cross  | 2013/08-2016/06 |        | ○ | ● | 4   | Copy only | 433Mhz | Continental | 4313961M00                                  | S180052024Z                              | S180052024                               |
| A0243 | EU | Toyota | Alphard      | 2014/10-2016/06 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260742020                                  | PMV-C210                                 | PMV-C210                                 |
| A0244 | EU | Toyota | Auris        | 2014/08-2016/06 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260702030/<br>4260702031                   | PMV-C210                                 | 42607-02030/<br>42607-02031              |
| A0245 | EU | Toyota | Avensis      | 2014/08-2016/06 |        | ● | ● | 4/5 | S         | 433Mhz | Pacific     | 4260702030/<br>4260702031                   | PMV-C210                                 | 42607-02030/<br>42607-02031              |
| A0246 | EU | Toyota | Aygo         | 2014/01-2015/12 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260702031                                  | PMV-C210                                 | PMV-C210                                 |
| A0247 | EU | Toyota | Camry        | 2014/06-2015/12 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260702031                                  | PMV-C210                                 | PMV-C210                                 |
| A0248 | EU | Toyota | Corolla      | 2013/01-2016/06 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260702030/<br>4260702031/<br>4260742020    | PMV-C210                                 | PMV-C210                                 |
| A0249 | EU | Toyota | Land Cruiser | 2005/01-2014/07 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260750011                                  | PMV-107K                                 |                                          |
| A0250 | EU | Toyota | Land Cruiser | 2014/08-2016/06 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260730070/<br>4260702031                   | PMV-107J/<br>PMV-C210                    | 42607-30070/<br>42607-02031              |
| A0251 | EU | Toyota | Prius        | 2014/05-2016/06 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260742020/<br>4260742021                   | PMV-C210                                 |                                          |
| A0252 | EU | Toyota | Proace       | 2013/01-2014/05 |        | ● | ● | 4/5 | 0         | 433Mhz | Schrader    | 9677130580                                  |                                          | 9677130580                               |
| A0254 | EU | Toyota | RAV4         | 2006/01-2012/11 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260750011                                  | PMV-107K                                 |                                          |
| A0255 | EU | Toyota | RAV4         | 2012/12-2016/06 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260742020/<br>4260742021                   | PMV-C210                                 | PMV-C210                                 |
| A0256 | EU | Toyota | Verso        | 2013/01-2014/07 |        | ● | ● | 4/5 | S         | 433Mhz | Pacific     | 4260702030                                  | PMV-C210                                 | 42607-02030                              |
| A0257 | EU | Toyota | Verso        | 2014/08-2016/06 |        | ● | ● | 4/5 | S         | 433Mhz | Pacific     | 4260702031                                  | PMV-C210                                 | 42607-02031                              |
| A0259 | EU | Toyota | Yaris        | 2014/05-2016/06 |        | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260742020/<br>4260702030/<br>4260702031    | PMV-C210                                 | PMV-C210                                 |
| A0260 | US | Acura  | CSX          | 2008/01-2011/12 | 315MHz | ● | ● | 4   | 0         | 315Mhz | TRW         | 42753SNAA83                                 | 217652-114                               | 217652-114                               |
| A0261 | US | Acura  | CSX          | 2012/01-2012/12 | 315MHz | ● | ● | 4   | 0         | 315Mhz | TRW         | 42753TROA81                                 | 217652-114                               | 217652-114                               |
| A0262 | US | Acura  | ILX          | 2013/01-2015/12 | 315MHz | ● | ● | 4   | S         | 315Mhz | Continental | 42753TX6A81                                 | S180052044G                              | S180052044                               |
| A0263 | US | Acura  | MDX          | 2004/01-2006/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | TRW         | 06421S3VA04                                 | 218898-101                               | 218898-101                               |
| A0264 | US | Acura  | MDX          | 2007/01-2013/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Pacific     | 42753STKA04                                 | PMV-107G                                 | 42753-STK-A04                            |
| A0265 | US | Acura  | MDX          | 2014/01-2015/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Continental | 42753TX4A51                                 | S180052042G                              | S180052042                               |
| A0266 | US | Acura  | RDX          | 2007/01-2012/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Pacific     | 42753STKA04                                 | PMV-107G                                 | 42753-STK-A04                            |
| A0267 | US | Acura  | RDX          | 2013/01-2015/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Continental | 42753TX4A51                                 | S180052042G                              | S180052042                               |
| A0268 | US | Acura  | RL           | 2005/01-2008/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | TRW         | 06421S3VA04                                 | 218898-101                               | 218898-101                               |
| A0269 | US | Acura  | RL           | 2009/01-2013/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | TRW         | 42753SHJA53                                 | 217652-116                               | 217652-116                               |
| A0270 | US | Acura  | RLX          | 2014/01-2015/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | TRW         | 42753TY2A51                                 |                                          |                                          |
| A0271 | US | Acura  | TL           | 2005/01-2008/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | TRW         | 06421S3VA04                                 | 218898-101                               | 218898-101                               |
| A0272 | US | Acura  | TL           | 2009/01-2013/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | TRW         | 42753TK4A01                                 | 217652-112                               | 217652-112                               |
| A0273 | US | Acura  | TL           | 2014/01-2014/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | TRW         | 42753TY2A51                                 |                                          |                                          |
| A0274 | US | Acura  | TLX          | 2014/11-2016/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Continental | 42753TZ3A51                                 | S180052060A                              | S180052060                               |
| A0275 | US | Acura  | TSX          | 2007/01-2008/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Pacific     | 42753STKA04                                 | PMV-107G                                 | 42753-STK-A04                            |
| A0276 | US | Acura  | TSX          | 2009/01-2014/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Pacific     | 42753TL2A52                                 | PMV-107G                                 | 42753-TL2-A52                            |
| A0277 | US | Acura  | ZDX          | 2010/01-2015/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | TRW         | 42753TK4A01                                 | 217652-112                               | 217652-112                               |
| A0278 | US | Honda  | Accord       | 2008/01-2012/12 | 315MHz | ● | ● | 4   | 0         | 315Mhz | Pacific     | 42753SWA316                                 | PMV-107M                                 | 42753-SWA-316                            |
| A0280 | US | Honda  | Civic        | 2008/01-2011/12 | 315MHz | ● | ● | 4   | 0         | 315Mhz | TRW         | 42753TR3A81/<br>42753TROA81/<br>42753SNAA83 | 225260-103/<br>217652-114/<br>217652-109 | 225260-103/<br>217652-114/<br>217652-109 |
| A0281 | US | Honda  | Civic        | 2012/01-2013/12 | 315MHz | ● | ● | 4   | 0         | 315Mhz | TRW         | 42753TR3A81/<br>42753TROA81/<br>42753SNAA83 | 225260-103/<br>217652-114/<br>217652-109 | 225260-103/<br>217652-114/<br>217652-109 |

|       |    |         |                 |                 |         |   |   |   |   |        |             |                                             |                           |                                                   |
|-------|----|---------|-----------------|-----------------|---------|---|---|---|---|--------|-------------|---------------------------------------------|---------------------------|---------------------------------------------------|
| A0282 | US | Honda   | Civic           | 2014/01-2015/12 | 315MHz  | ● | ● | 4 | S | 315Mhz | TRW         | 42753TR3A81/<br>42753SNAA83                 | 225260-103/<br>217652-109 | 225260-103/<br>217652-109                         |
| A0283 | US | Honda   | Crosstour       | 2010/01-2015/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Continental | 42753TP6A82                                 | S180052025E               | S180052025                                        |
| A0284 | US | Honda   | CR-V            | 2007/01-2011/12 | Alloy   | ● | ● | 4 | 0 | 315Mhz | Pacific     | 42753SWA316                                 | PMV-107M                  | 42753-SWA-316                                     |
| A0285 | US | Honda   | CR-V            | 2007/01-2011/12 | Steel   | ● | ● | 4 | 0 | 315Mhz | Pacific     | 42753SWA315                                 | PMV-107M                  | 42753-SWA-315                                     |
| A0286 | US | Honda   | CR-V            | 2012/01-2014/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Continental | 42753TP6A82                                 | S180052025E               | S180052025                                        |
| A0287 | US | Honda   | CR-Z            | 2011/01-2014/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 42753SNAA83                                 | 217652-114                | 217652-114                                        |
| A0288 | US | Honda   | Element         | 2006/01-2007/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 06421SCVA00                                 |                           |                                                   |
| A0289 | US | Honda   | Element         | 2008/01-2008/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 42753SHJA82                                 | 217652-115                | 217652-115                                        |
| A0290 | US | Honda   | Element         | 2009/01-2011/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 42753SNAA83                                 | 217652-114                | 217652-114                                        |
| A0291 | US | Honda   | Fit             | 2008/01-2008/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Pacific     | 42753SWA316                                 | PMV-107M                  | 42753-SWA-316                                     |
| A0292 | US | Honda   | Fit             | 2009/01-2014/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 42753SNAA83                                 | 217652-114                | 217652-114                                        |
| A0294 | US | Honda   | Insight         | 2010/01-2014/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 42753SNAA83                                 | 217652-114                | 217652-114                                        |
| A0295 | US | Honda   | Odyssey         | 2006/01-2007/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 06421SCVA00                                 |                           |                                                   |
| A0296 | US | Honda   | Odyssey         | 2008/01-2010/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 42753SHJA82                                 | 217652-115                | 217652-115                                        |
| A0297 | US | Honda   | Odyssey         | 2011/01-2016/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 42753SNAA83                                 | 217652-114                | 217652-114                                        |
| A0298 | US | Honda   | Odyssey Touring | 2005/01-2007/12 | 315MHz  | ● | ● | 4 | A | 315Mhz | TRW         | 06421S3VA04                                 | 218898-101                | 218898-101                                        |
| A0299 | US | Honda   | Odyssey Touring | 2008/01-2010/12 | 315MHz  | ● | ● | 4 | A | 315Mhz | TRW         | 42753SHJA53                                 | 217652-116                | 217652-116                                        |
| A0300 | US | Honda   | Odyssey Touring | 2011/01-2016/12 | 315MHz  | ● | ● | 4 | A | 315Mhz | TRW         | 42753SNAA83                                 | 217652-114                | 217652-114                                        |
| A0301 | US | Honda   | Pilot           | 2005/01-2005/12 | Alloy   | ● | ● | 4 | A | 315Mhz | TRW         | 06421S3VA04                                 | 218898-101                | 218898-101                                        |
| A0302 | US | Honda   | Pilot           | 2005/01-2008/12 | Steel   | ● | ● | 4 | A | 315Mhz | TRW         | 06421S9VA03/<br>06421S3VA04                 | 218898-103/<br>218898-101 | 218898-103/<br>218898-101                         |
| A0303 | US | Honda   | Pilot           | 2006/01-2008/12 | Alloy   | ● | ● | 4 | A | 315Mhz | TRW         | 06421S3VA04                                 | 218898-101                | 218898-101                                        |
| A0305 | US | Honda   | Pilot           | 2009/01-2015/12 | 315Mhz  | ● | ● | 4 | A | 315Mhz | Pacific     | 42753STKA04                                 | PMV-107G                  | 42753-STK-A04                                     |
| A0306 | US | Honda   | Pilot Touring   | 2009/01-2015/12 | 315MHz  | ● | ● | 4 | A | 315Mhz | Pacific     | 42753STKA04                                 | PMV-107G                  | 42753-STK-A04                                     |
| A0307 | US | Honda   | Ridgeline       | 2006/01-2008/12 | Alloy   | ● | ● | 4 | A | 315Mhz | TRW         | 06421S3VA04                                 | 218898-101                | 218898-101                                        |
| A0308 | US | Honda   | Ridgeline       | 2006/01-2008/12 | Steel   | ● | ● | 4 | A | 315Mhz | TRW         | 06421S9VA03/<br>06421S3VA04                 | 218898-103/<br>218898-101 | 218898-103/<br>218898-101                         |
| A0309 | US | Honda   | Ridgeline       | 2009/01-2014/12 | Alloy   | ● | ● | 4 | A | 315Mhz | TRW         | 42753SHJA53                                 | 217652-116                | 217652-116                                        |
| A0310 | US | Honda   | Ridgeline       | 2009/01-2014/12 | Steel   | ● | ● | 4 | A | 315Mhz | TRW         | 06421S3VA04                                 | 218898-101                | 218898-101                                        |
| A0311 | US | Honda   | Ridgeline RTL   | 2009/01-2013/12 | 315MHz  | ● | ● | 4 | A | 315Mhz | TRW         | 42753SHJA53                                 | 217652-116                | 217652-116                                        |
| A0312 | US | Honda   | S2000           | 2008/01-2009/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Pacific     | 42753S2A325/<br>42753S2A315/<br>42753S2A305 | PMV-107M                  | 42753-S2A-325/<br>42753-S2A-315/<br>42753-S2A-305 |
| A0313 | US | Hyundai | Accent          | 2008/01-2011/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 529332F000                                  | 216707-101                | 216707-101                                        |
| A0314 | US | Hyundai | Accent          | 2012/01-2014/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Continental | 529332M000                                  | S180052017G               | S180052017                                        |
| A0315 | US | Hyundai | Azera           | 2007/01-2011/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Lear        | 529332G200                                  |                           | 52933-2G200                                       |
| A0317 | US | Hyundai | Azera           | 2014/01-2016/12 | 433MHz  | ● | ● | 4 | 0 | 433Mhz | TRW         | 529333V600                                  | 225816-104                | 225816-104                                        |
| A0318 | US | Hyundai | Elantra         | 2007/01-2010/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Lear        | 529332G200                                  |                           | 52933-2G200                                       |
| A0319 | US | Hyundai | Elantra         | 2011/01-2014/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 529333X200                                  | 225816-101                | 225816-101                                        |
| A0321 | US | Hyundai | Elantra GT      | 2013/01-2015/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Continental | 52933A5000                                  | S180052041F               | S180052041                                        |
| A0322 | US | Hyundai | Elantra Touring | 2009/01-2012/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Continental | 529332M000                                  | S180052017G               | S180052017                                        |
| A0324 | US | Hyundai | Entourage       | 2007/01-2010/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Lear        | 529334D200                                  |                           | 52933-4D200                                       |
| A0325 | US | Hyundai | Equus           | 2011/01-2014/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 529332F000                                  | 216707-101                | 216707-101                                        |
| A0326 | US | Hyundai | Equus           | 2015/01-2016/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Continental | 529333N000                                  |                           | 529333N000                                        |
| A0327 | US | Hyundai | Genesis Coupe   | 2010/01-2012/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Continental | 529332M000                                  | S180052017G               | S180052017                                        |
| A0328 | US | Hyundai | Genesis Coupe   | 2013/01-2015/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Continental | 52933A5000                                  | S180052041F               | S180052041                                        |
| A0329 | US | Hyundai | Genesis Sedan   | 2009/01-2014/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | TRW         | 529332F000                                  | 216707-101                | 216707-101                                        |
| A0330 | US | Hyundai | Genesis Sedan   | 2015/01-2016/12 | 433MHz  | ● | ● | 4 | 0 | 433Mhz | Continental | 529333N100                                  | S180052092Z               | S180052092                                        |
| A0331 | US | Hyundai | Santa Fe        | 2007/01-2007/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Lear        | 529334D200                                  |                           | 52933-4D200                                       |
| A0332 | US | Hyundai | Santa Fe        | 2008/01-2008/12 | Hi line | ● | ● | 4 | 0 | 315Mhz | Lear        | 529334D200                                  |                           | 52933-4D200                                       |
| A0333 | US | Hyundai | Santa Fe        | 2008/01-2008/12 | Lo Line | ● | ● | 4 | 0 | 315Mhz | Lear        | 529332G200                                  |                           | 52933-2G200                                       |
| A0334 | US | Hyundai | Santa Fe        | 2009/01-2009/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Lear        | 529332G200                                  |                           | 52933-2G200                                       |
| A0335 | US | Hyundai | Santa Fe        | 2010/01-2012/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Lear        | 529330W100                                  |                           | 52933-0W100                                       |
| A0336 | US | Hyundai | Santa Fe        | 2013/01-2014/12 | 315MHz  | ● | ● | 4 | 0 | 315Mhz | Continental | 52933A5000                                  | S180052041F               | S180052041                                        |

|       |    |          |                     |                 |            |   |   |   |     |        |             |                                          |                                    |                                             |
|-------|----|----------|---------------------|-----------------|------------|---|---|---|-----|--------|-------------|------------------------------------------|------------------------------------|---------------------------------------------|
| A0337 | US | Hyundai  | Santa Fe            | 2015/01-2016/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Continental | 529333N000/<br>529332M550                | S180052091C                        | S180052091                                  |
| A0338 | US | Hyundai  | Santa Fe Sport      | 2015/01-2016/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Continental | 529333N000/<br>529332M550                | S180052091C                        | S180052091                                  |
| A0339 | US | Hyundai  | Sonata              | 2006/01-2007/12 | Lo Line    | ● | ● | 4 | 0   | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0340 | US | Hyundai  | Sonata              | 2008/01-2008/12 | AM Lo Line | ● | ● | 4 | 0   | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0341 | US | Hyundai  | Sonata              | 2008/01-2008/12 | FM Lo Line | ● | ● | 4 | 0   | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0342 | US | Hyundai  | Sonata              | 2009/01-2009/12 | Lo Line    | ● | ● | 4 | 0   | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0343 | US | Hyundai  | Sonata              | 2010/01-2013/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Continental | 529332M000                               | S180052017G                        | S180052017                                  |
| A0344 | US | Hyundai  | Sonata              | 2014/01-2014/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Continental | 529333N000/<br>529332M550                | S180052091C                        | S180052091                                  |
| A0345 | US | Hyundai  | Sonata (Exc:Hybrid) | 2015/01-2016/12 | 433MHz     | ● | ● | 4 | 0   | 433Mhz | Schrader    | 52933C1100/<br>52933C8000                |                                    | 52933-C1100                                 |
| A0347 | US | Hyundai  | Tiburon             | 2007/01-2007/12 | Lo Line    | ● | ● | 4 | 0   | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0348 | US | Hyundai  | Tiburon             | 2008/01-2008/12 | Lo Line    | ● | ● | 4 | 0   | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0349 | US | Hyundai  | Tucson              | 2006/01-2007/12 | 315Mhz     | ● | ● | 4 | 0   | 315Mhz | TRW         | 529333E000/<br>529331F000                |                                    |                                             |
| A0350 | US | Hyundai  | Tucson              | 2008/01-2009/12 | 315Mhz     | ● | ● | 4 | 0   | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0351 | US | Hyundai  | Tucson              | 2010/01-2014/03 | 315Mhz     | ● | ● | 4 | 0   | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0352 | US | Hyundai  | Veloster            | 2012/01-2016/12 | 315MHz     | ● | ● | 4 | A/0 | 315Mhz | Schrader    | 529332V000                               |                                    | 52933-2V000                                 |
| A0354 | US | Hyundai  | Veracruz            | 2006/01-2007/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Lear        | 529334D200                               |                                    | 52933-4D200                                 |
| A0355 | US | Hyundai  | Veracruz            | 2008/01-2008/12 | Hi line    | ● | ● | 4 | 0   | 315Mhz | Lear        | 529334D200                               |                                    | 52933-4D200                                 |
| A0356 | US | Hyundai  | Veracruz            | 2008/01-2008/12 | Lo Line    | ● | ● | 4 | 0   | 315Mhz | Lear        | 529332G200                               |                                    | 52933-2G200                                 |
| A0357 | US | Hyundai  | Veracruz            | 2009/01-2012/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Lear        | 529332G200                               |                                    | 52933-2G200                                 |
| A0358 | US | Hyundai  | Veracruz            | 2013/01-2013/12 | Lo Line    | ● | ● | 4 | 0   | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0359 | US | Infiniti | EX Series           | 2008/01-2008/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CD001                               |                                    | 40700-CD001                                 |
| A0360 | US | Infiniti | EX Series           | 2009/01-2010/04 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Pacific     | 40700JK00C                               | PMV-107L                           | 40700-JK00C                                 |
| A0361 | US | Infiniti | EX Series           | 2010/05-2013/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0C                | PMV-C811/<br>PMV-107S              | 40700-1LA0E/<br>40700-1LA0C                 |
| A0363 | US | Infiniti | FX Series           | 2003/01-2008/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CD001                               |                                    | 40700-CD001                                 |
| A0364 | US | Infiniti | FX Series           | 2009/01-2010/04 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Pacific     | 40700JK00B/<br>40700JK00C                | PMV-107L/<br>PMV-107L              | 40700-JK00B/<br>40700-JK00C                 |
| A0365 | US | Infiniti | FX Series           | 2010/05-2013/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0C                | PMV-C811/<br>PMV-107S              | 40700-1LA0E/<br>40700-1LA0C                 |
| A0371 | US | Infiniti | G Series            | 2003/01-2006/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CD001                               |                                    | 40700-CD001                                 |
| A0372 | US | Infiniti | G Series            | 2007/01-2007/12 | Coupe      | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700JA01B/<br>40700JA02B                |                                    | 40700-JA01B                                 |
| A0373 | US | Infiniti | G Series            | 2007/01-2007/12 | Sedan      | ● | ● | 4 | 0   | 315Mhz | Pacific     | 40700JK00C                               | PMV-107L                           | 40700-JK00C                                 |
| A0374 | US | Infiniti | G Series            | 2008/01-2010/04 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Pacific     | 40700JK00B/<br>40700JK00C                | PMV-107L/<br>PMV-107L              | 40700-JK00B/<br>40700-JK00C                 |
| A0375 | US | Infiniti | G Series            | 2010/05-2013/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0C                | PMV-C811/<br>PMV-107S              | 40700-1LA0E/<br>40700-1LA0C                 |
| A0376 | US | Infiniti | JX35                | 2013/01-2013/12 | 433MHz     | ● | ● | 4 | 0   | 433Mhz | Continental | 407003JA0A                               | S180052036Z                        | S180052036                                  |
| A0381 | US | Infiniti | M Series            | 2003/01-2007/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CD001                               |                                    | 40700-CD001                                 |
| A0382 | US | Infiniti | M Series            | 2008/01-2010/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 407001AA0C                               |                                    | 40700-1AA0C                                 |
| A0383 | US | Infiniti | M Series            | 2011/01-2013/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0C                | PMV-C811/<br>PMV-107S              | 40700-1LA0E/<br>40700-1LA0C                 |
| A0385 | US | Infiniti | Q40                 | 2015/01-2015/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0A/<br>407001LA0C | PMV-C811/<br>PMV-107S/<br>PMV-107S | 40700-1LA0E/<br>40700-1LA0A/<br>40700-1LA0C |
| A0386 | US | Infiniti | Q45                 | 2003/01-2006/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CD001                               |                                    | 40700-CD001                                 |
| A0388 | US | Infiniti | Q50                 | 2013/07-2015/12 | 315MHz     | ● | ● | 4 | 0   | 315Mhz | Continental | 407004GA0A                               | S180052037C                        | S180052037                                  |
| A0389 | US | Infiniti | Q60                 | 2014/01-2015/12 | 315MHz     | ● | ● | 4 | S   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0C                | PMV-C811/<br>PMV-107S              | 40700-1LA0E/<br>40700-1LA0C                 |
| A0390 | US | Infiniti | Q70                 | 2014/01-2015/12 | 315MHz     | ● | ● | 4 | S   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0C                | PMV-C811/<br>PMV-107S              | 40700-1LA0E/<br>40700-1LA0C                 |
| A0391 | US | Infiniti | QX4                 | 2003/01-2003/12 | 315MHz     | ● | ● | 4 | S   | 315Mhz | Schrader    | 40700CD001                               |                                    | 40700-CD001                                 |

|       |    |          |           |                 |         |   |   |     |           |        |             |                                          |                                    |                                             |
|-------|----|----------|-----------|-----------------|---------|---|---|-----|-----------|--------|-------------|------------------------------------------|------------------------------------|---------------------------------------------|
| A0392 | US | Infiniti | QX50      | 2014/01-2015/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0C                | PMV-C811/<br>PMV-107S              | 40700-1LA0E/<br>40700-1LA0C                 |
| A0393 | US | Infiniti | QX56      | 2004/01-2007/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Schrader    | 40700CK002/<br>40700CK001                |                                    | 40700-CK002/<br>40700-CK001                 |
| A0397 | US | Infiniti | QX56      | 2008/01-2010/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Schrader    | 40700JA01B                               |                                    | 40700-JA01B                                 |
| A0398 | US | Infiniti | QX56      | 2011/01-2013/12 | 315MHz  | ● | ● | 4   | S         | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0A/<br>407001LA0C | PMV-C811/<br>PMV-107S/<br>PMV-107S | 40700-1LA0E/<br>40700-1LA0A/<br>40700-1LA0C |
| A0399 | US | Infiniti | QX60      | 2014/01-2015/12 | 433MHz  | ● | ● | 4   | 0         | 433Mhz | Continental | 407003JA0A                               | S180052036Z                        | S180052036                                  |
| A0400 | US | Infiniti | QX70      | 2014/01-2015/12 | 315MHz  | ● | ● | 4   | S         | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0C                | PMV-C811/<br>PMV-107S              | 40700-1LA0E/<br>40700-1LA0C                 |
| A0401 | US | Infiniti | QX80      | 2014/01-2015/12 | 315MHz  | ● | ● | 4   | S         | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0C                | PMV-C811/<br>PMV-107S              | 40700-1LA0E/<br>40700-1LA0C                 |
| A0402 | US | Isuzu    | Ascender  | 2006/01-2011/12 | 315MHz  | ○ | ● | 4   | S         | 315Mhz | Schrader    | 25774006                                 |                                    | 25774006                                    |
| A0403 | US | Isuzu    | i-290     | 2007/01-2011/12 | 315MHz  | ○ | ● | 4   | S         | 315Mhz | Schrader    | 15122618                                 |                                    | 15122618                                    |
| A0404 | US | Isuzu    | i-370     | 2007/01-2011/12 | 315MHz  | ○ | ● | 4   | S         | 315Mhz | Schrader    | 15122618                                 |                                    | 15122618                                    |
| A0405 | US | Isuzu    | Rodeo     | 2004/01-2004/12 | 433MHz  | ○ | ● | 4   | S         | 433Mhz | Schrader    | 52088990AC/<br>52088990AD                |                                    | 52088990AC/<br>52088990AD                   |
| A0406 | US | KIA      | Amanti    | 2007/01-2007/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0407 | US | KIA      | Amanti    | 2008/01-2008/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0408 | US | KIA      | Amanti    | 2009/01-2009/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0409 | US | KIA      | Amanti    | 2010/01-2011/12 | 315MHz  | ○ | ● | 4   | Copy only | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0410 | US | KIA      | Borrego   | 2009/01-2011/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0411 | US | KIA      | Cadenza   | 2014/01-2016/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Continental | 52933A5000                               | S180052041F                        | S180052041                                  |
| A0412 | US | KIA      | Forte     | 2010/01-2013/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Continental | 529332M000                               | S180052017G                        | S180052017                                  |
| A0414 | US | KIA      | Magentis  | 2008/01-2010/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Lear        | 529332G200                               |                                    | 52933-2G200                                 |
| A0416 | US | KIA      | Optima    | 2006/01-2010/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Lear        | 529332G200                               |                                    | 52933-2G200                                 |
| A0417 | US | KIA      | Optima    | 2011/01-2014/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Continental | 529332M000                               | S180052017G                        | S180052017                                  |
| A0418 | US | KIA      | Rio       | 2007/01-2011/12 | Lo Line | ● | ● | 4   | 0         | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0419 | US | KIA      | Rio       | 2012/01-2016/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333X200                               | 225816-101                         | 225816-101                                  |
| A0421 | US | KIA      | Rondo     | 2006/01-2011/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Lear        | 529332G200                               |                                    | 52933-2G200                                 |
| A0423 | US | KIA      | Sedona    | 2006/01-2008/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Lear        | 529334D800/<br>529334D200/<br>529334D000 |                                    | 52933-4D800/<br>52933-4D200/<br>52933-4D000 |
| A0427 | US | KIA      | Sorento   | 2005/01-2007/12 | 315Mhz  | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0428 | US | KIA      | Sorento   | 2008/01-2008/12 | 315Mhz  | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0431 | US | KIA      | Sorento   | 2011/01-2015/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Continental | 529332M000                               | S180052017G                        | S180052017                                  |
| A0432 | US | KIA      | Soul      | 2010/01-2013/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | Continental | 529332M000                               | S180052017G                        | S180052017                                  |
| A0433 | US | KIA      | Soul      | 2014/01-2016/12 | 433MHz  | ● | ● | 4   | 0         | 433Mhz | Schrader    | 52933B2100                               |                                    | 52933-B2100                                 |
| A0434 | US | KIA      | Spectra   | 2007/01-2009/12 | Lo Line | ● | ● | 4   | 0         | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0435 | US | KIA      | Spectra   | 2010/01-2011/12 | Lo Line | ○ | ● | 4   | Copy only | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0436 | US | KIA      | Sportage  | 2005/01-2007/12 | Lo Line | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0437 | US | KIA      | Sportage  | 2008/01-2008/12 | Lo Line | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0438 | US | KIA      | Sportage  | 2009/01-2013/12 | Lo Line | ● | ● | 4   | 0         | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0439 | US | KIA      | Sportage  | 2011/01-2013/12 | Lo Line | ● | ● | 4   | 0         | 315Mhz | TRW         | 529332F000                               | 216707-101                         | 216707-101                                  |
| A0440 | US | KIA      | Sportage  | 2014/01-2016/12 | 315MHz  | ● | ● | 4   | 0         | 315Mhz | TRW         | 529332S500                               | 225816-127                         | 225816-127                                  |
| A0441 | US | KIA      | Tuscany   | 2007/01-2008/12 | 315Mhz  | ○ | ● | 4   | Copy only | 315Mhz | TRW         | 529333E000                               |                                    |                                             |
| A0442 | US | Lexus    | CT 200H   | 2011/01-2016/12 | 315MHz  | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260733021                               | PMV-107J                           | 42607-33021                                 |
| A0446 | US | Lexus    | ES Series | 2007/01-2012/12 | 315MHz  | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260733021                               | PMV-107J                           | 42607-33021                                 |
| A0447 | US | Lexus    | ES Series | 2013/01-2016/12 | 315MHz  | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260730060                               | 3729A-PMVC010                      | 42607-30060                                 |
| A0448 | US | Lexus    | GS 300    | 2005/01-2012/12 | 315MHz  | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260733021                               | PMV-107J                           | 42607-33021                                 |
| A0449 | US | Lexus    | GS 350    | 2007/01-2012/12 | 315MHz  | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260733021                               | PMV-107J                           | 42607-33021                                 |
| A0450 | US | Lexus    | GS 350    | 2013/01-2016/12 | 315MHz  | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260730060                               | 3729A-PMVC010                      | 42607-30060                                 |
| A0451 | US | Lexus    | GS 350    | 2013/01-2015/12 | 433MHz  | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260730070                               | PMV-107J                           | 42607-30070                                 |
| A0452 | US | Lexus    | GS 430    | 2005/01-2006/06 | 315MHz  | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260730030                               | PMV-1017                           | 42607-30030                                 |

|       |    |            |           |                 |        |   |   |     |   |        |          |                                          |               |                         |
|-------|----|------------|-----------|-----------------|--------|---|---|-----|---|--------|----------|------------------------------------------|---------------|-------------------------|
| A0453 | US | Lexus      | GS 430    | 2006/07-2007/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0454 | US | Lexus      | GS 450h   | 2007/01-2012/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0455 | US | Lexus      | GS 450h   | 2013/01-2016/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260730060                               | 3729A-PMVC010 | 42607-30060             |
| A0456 | US | Lexus      | GS 460    | 2008/01-2012/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0457 | US | Lexus      | GS 460    | 2013/01-2016/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260730060                               | 3729A-PMVC010 | 42607-30060             |
| A0458 | US | Lexus      | GX 460    | 2010/01-2016/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0459 | US | Lexus      | GX 470    | 2004/01-2005/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021/<br>4260733011/<br>4260735010 | PMV-107J      | 42607-33021             |
| A0460 | US | Lexus      | GX 470    | 2006/01-2006/06 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260730030                               | PMV-1017      | 42607-30030             |
| A0461 | US | Lexus      | GX 470    | 2006/07-2014/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0462 | US | Lexus      | HS 250h   | 2010/01-2012/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260775010/<br>4260733021                | PMV-107J      | 42607-75010             |
| A0463 | US | Lexus      | IS 250    | 2006/01-2013/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0464 | US | Lexus      | IS 300h   | 2006/01-2013/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0465 | US | Lexus      | IS 350    | 2006/01-2013/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0466 | US | Lexus      | IS C      | 2006/01-2012/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0467 | US | Lexus      | IS F      | 2006/01-2013/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0468 | US | Lexus      | IS F      | 2014/01-2015/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260730060                               | 3729A-PMVC010 | 42607-30060             |
| A0469 | US | Lexus      | IS Series | 2006/01-2013/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0470 | US | Lexus      | IS Series | 2014/01-2016/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260730060                               | 3729A-PMVC010 | 42607-30060             |
| A0471 | US | Lexus      | LFA       | 2012/01-2013/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0473 | US | Lexus      | LS 460    | 2007/01-2013/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0475 | US | Lexus      | LS 600h   | 2013/01-2013/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0476 | US | Lexus      | LS Serial | 2014/01-2016/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260730060                               | 3729A-PMVC010 | 42607-30060             |
| A0477 | US | Lexus      | LX 470    | 2005/01-2007/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0479 | US | Lexus      | LX 570    | 2008/01-2016/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0480 | US | Lexus      | NX        | 2014/01-2016/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260730060                               | 3729A-PMVC010 | 42607-30060             |
| A0481 | US | Lexus      | RC        | 2015/01-2016/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260730060                               | 3729A-PMVC010 | 42607-30060             |
| A0482 | US | Lexus      | RC F      | 2015/01-2016/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260730060                               | 3729A-PMVC010 | 42607-30060             |
| A0483 | US | Lexus      | RX 330    | 2006/01-2006/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0484 | US | Lexus      | RX 350    | 2007/01-2012/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0485 | US | Lexus      | RX 350    | 2013/01-2015/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 426070E011/<br>4260733021                | PMV107J       | 42607-0E011             |
| A0486 | US | Lexus      | RX 400h   | 2007/01-2012/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0487 | US | Lexus      | RX 450h   | 2007/01-2013/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0489 | US | Lexus      | SC 430    | 2007/01-2011/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Pacific  | 4260733021                               | PMV-107J      | 42607-33021             |
| A0490 | US | Mitsubishi | Eclipse   | 2006/01-2007/12 | Alloy  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | MN103081                                 |               | MN103081                |
| A0491 | US | Mitsubishi | Eclipse   | 2006/01-2007/12 | Steel  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | MN103081                                 |               | MN103081                |
| A0492 | US | Mitsubishi | Eclipse   | 2008/01-2010/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Schrader | MN103081                                 |               | MN103081                |
| A0493 | US | Mitsubishi | Eclipse   | 2011/01-2012/12 | Alloy  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | 4250B877                                 |               | 4250B877                |
| A0494 | US | Mitsubishi | Eclipse   | 2011/01-2012/12 | Steel  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | 4250B875                                 |               | 4250B875                |
| A0496 | US | Mitsubishi | Endeavor  | 2003/01-2006/12 | 433MHz | ● | ● | 4/5 | 0 | 433Mhz | Schrader | MN103033/<br>52088990AC                  |               | MN103033/<br>52088990AC |
| A0497 | US | Mitsubishi | Endeavor  | 2007/01-2007/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Schrader | MN103081                                 |               | MN103081                |
| A0498 | US | Mitsubishi | Endeavor  | 2007/01-2007/12 | 433MHz | ● | ● | 4/5 | 0 | 433Mhz | Schrader | MN103033                                 |               | MN103033                |
| A0499 | US | Mitsubishi | Endeavor  | 2008/01-2010/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Schrader | MN103081                                 |               | MN103081                |
| A0500 | US | Mitsubishi | Endeavor  | 2011/01-2012/12 | Alloy  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | 4250B877                                 |               | 4250B877                |
| A0501 | US | Mitsubishi | Endeavor  | 2011/01-2012/12 | Steel  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | 4250B875                                 |               | 4250B875                |
| A0502 | US | Mitsubishi | Galant    | 2004/01-2006/12 | 433MHz | ● | ● | 4/5 | 0 | 433Mhz | Schrader | MN103033                                 |               | MN103033                |
| A0503 | US | Mitsubishi | Galant    | 2007/01-2009/12 | Alloy  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | MN103081                                 |               | MN103081                |
| A0504 | US | Mitsubishi | Galant    | 2007/01-2009/12 | Steel  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | MN103081                                 |               | MN103081                |
| A0505 | US | Mitsubishi | Galant    | 2010/01-2010/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Schrader | MN103081                                 |               | MN103081                |
| A0506 | US | Mitsubishi | Galant    | 2011/01-2013/12 | Alloy  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | 4250B877                                 |               | 4250B877                |
| A0507 | US | Mitsubishi | Galant    | 2011/01-2013/12 | Steel  | ● | ● | 4/5 | 0 | 315Mhz | Schrader | 4250B875                                 |               | 4250B875                |

|       |    |            |              |                 |           |   |   |     |     |        |             |                                                                        |                             |                                                                             |
|-------|----|------------|--------------|-----------------|-----------|---|---|-----|-----|--------|-------------|------------------------------------------------------------------------|-----------------------------|-----------------------------------------------------------------------------|
| A0508 | US | Mitsubishi | i-MiEV       | 2010/01-2016/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Continental | 4250B975                                                               | S180052027C                 | S180052027                                                                  |
| A0509 | US | Mitsubishi | Lancer       | 2008/01-2010/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Continental | 4250A225/<br>4250B975                                                  |                             |                                                                             |
| A0510 | US | Mitsubishi | Lancer       | 2011/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Continental | 4250B668/<br>4250B975                                                  | S180052027B/<br>S180052027C | S180052027                                                                  |
| A0511 | US | Mitsubishi | Mirage       | 2014/01-2015/12 | 315MHz    | ● | ● | 4/5 | A   | 315Mhz | Continental | 4250B668                                                               | S180052027B                 | S180052027                                                                  |
| A0512 | US | Mitsubishi | Montero      | 2003/01-2006/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Schrader    | MN103081                                                               |                             | MN103081                                                                    |
| A0513 | US | Mitsubishi | Outlander    | 2007/01-2010/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Continental | 4250A225                                                               |                             |                                                                             |
| A0514 | US | Mitsubishi | Outlander    | 2011/01-2014/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Continental | 4250B668                                                               | S180052027B                 | S180052027                                                                  |
| A0515 | US | Mitsubishi | Raider       | 2008/01-2010/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Schrader    | 56029319AC/<br>56029319AB/<br>56029319AA                               |                             | 56029319AC/<br>56029319AB/<br>56029319AA                                    |
| A0516 | US | Mitsubishi | RVR          | 2010/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Continental | 4250B668/<br>4250B975                                                  | S180052027B                 | S180052027                                                                  |
| A0517 | US | Nissan     | 350Z         | 2003/01-2006/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CD001                                                             |                             | 40700-CD001                                                                 |
| A0518 | US | Nissan     | 350Z         | 2007/01-2009/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0B/<br>407001AA0C/<br>40700JA01C                               |                             | 40700-1AA0B/<br>40700-1AA0C/<br>40700-JA01C                                 |
| A0519 | US | Nissan     | 370Z         | 2009/01-2010/04 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Pacific     | 40700JK00C                                                             | PMV-107L                    | 40700-JK00C                                                                 |
| A0520 | US | Nissan     | 370Z         | 2010/05-2016/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0D/<br>407001LA0C/<br>407001LA0B/<br>407001LA0A | PMV-C811/<br>PMV-107S       | 40700-1LA0E/<br>40700-1LA0D/<br>40700-1LA0C/<br>40700-1LA0B/<br>40700-1LA0A |
| A0521 | US | Nissan     | Altima       | 2006/01-2011/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0B/<br>40700JA01B/<br>40700JA02B                               |                             | 40700-1AA0B/<br>40700-JA01B/<br>40700-JA02B                                 |
| A0522 | US | Nissan     | Altima Coupe | 2012/01-2014/12 | 315MHz    | ● | ● | 4   | 0/S | 315Mhz | Continental | 407003AN0A                                                             | S180052033G                 | S180052033                                                                  |
| A0523 | US | Nissan     | Altima Sedan | 2013/01-2015/12 | 433MHz    | ● | ● | 4   | 0/S | 433Mhz | Continental | 407003JA0B/<br>407003JA0A                                              | S180052036G/<br>S180052036Z | S180052036                                                                  |
| A0524 | US | Nissan     | Armada       | 2005/01-2006/12 | Alloy     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                             | 40700-CK001                                                                 |
| A0525 | US | Nissan     | Armada       | 2005/01-2006/12 | Steel     | ● | ○ | 4   | 0   | 315Mhz | Schrader    | 40700CK002                                                             |                             | 40700-CK002                                                                 |
| A0526 | US | Nissan     | Armada       | 2007/01-2008/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                             | 40700-CK001                                                                 |
| A0527 | US | Nissan     | Armada       | 2009/01-2015/12 | 315MHz    | ● | ● | 4   | 0/S | 315Mhz | Schrader    | 407001AA0B/<br>40700JA02B                                              |                             | 40700-1AA0B/<br>40700-JA02B                                                 |
| A0528 | US | Nissan     | Cube         | 2011/01-2015/12 | with iKey | ● | ● | 4   | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0D/<br>407001LA0C/<br>407001LA0B/<br>407001LA0A | PMV-C811/<br>PMV-107S       | 40700-1LA0E/<br>40700-1LA0D/<br>40700-1LA0C/<br>40700-1LA0B/<br>40700-1LA0A |
| A0529 | US | Nissan     | Cube         | 2009/01-2015/12 | no iKey   | ● | ○ | 4   | 0   | 315Mhz | Schrader    | 407001AA0C                                                             |                             | 40700-1AA0B/<br>40700-1AA0C/<br>40700-JA01C                                 |
| A0530 | US | Nissan     | Frontier     | 2003/01-2004/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CD001                                                             |                             | 40700-CD001                                                                 |
| A0531 | US | Nissan     | Frontier     | 2005/01-2007/12 | Alloy     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                             | 40700-CK001                                                                 |
| A0532 | US | Nissan     | Frontier     | 2005/01-2007/12 | Steel     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK002/<br>40700CK001                                              |                             | 40700-CK002                                                                 |
| A0533 | US | Nissan     | Frontier     | 2008/01-2008/12 | Alloy     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                             | 40700-CK001                                                                 |
| A0534 | US | Nissan     | Frontier     | 2008/01-2008/12 | Steel     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700JA01B                                                             |                             | 40700-JA01B                                                                 |
| A0535 | US | Nissan     | Frontier     | 2009/01-2013/04 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0D/<br>407001AA0B/<br>40700JA02B/<br>40700CK001                |                             | 407001AA0D/<br>407001AA0B/<br>40700JA02B/<br>40700CK001                     |
| A0536 | US | Nissan     | GT-R         | 2009/01-2016/12 | 315MHz    | ● | ● | 4   | 0/S | 315Mhz | Schrader    | 407001AA0B/<br>40700JA00C/<br>40700JA01B                               |                             | 40700-1AA0B/<br>40700-JA00C/<br>40700-JA01B                                 |
| A0537 | US | Nissan     | Juke         | 2011/01-2015/12 | no iKey   | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0B/<br>407001AA0C/<br>40700JA01B                               |                             | 40700-1AA0B/<br>40700-1AA0C/<br>40700-JA01B                                 |

|       |    |        |              |                 |           |   |   |   |     |        |             |                                                                        |                             |                                                                             |
|-------|----|--------|--------------|-----------------|-----------|---|---|---|-----|--------|-------------|------------------------------------------------------------------------|-----------------------------|-----------------------------------------------------------------------------|
| A0538 | US | Nissan | Juke         | 2011/01-2015/12 | with iKey | ● | ● | 4 | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0D/<br>407001LA0C/<br>407001LA0B/<br>407001LA0A | PMV-C811/<br>PMV-107S       | 40700-1LA0E/<br>40700-1LA0D/<br>40700-1LA0C/<br>40700-1LA0B/<br>40700-1LA0A |
| A0539 | US | Nissan | Leaf         | 2011/01-2012/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0D/<br>407001LA0C/<br>407001LA0B/<br>407001LA0A | PMV-C811/<br>PMV-107S       | 40700-1LA0E/<br>40700-1LA0D/<br>40700-1LA0C/<br>40700-1LA0B/<br>40700-1LA0A |
| A0540 | US | Nissan | Leaf         | 2013/01-2013/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0D/<br>407001LA0C/<br>407001LA0B/<br>407001LA0A | PMV-C811/<br>PMV-107S       | 40700-1LA0E/<br>40700-1LA0D/<br>40700-1LA0C/<br>40700-1LA0B/<br>40700-1LA0A |
| A0542 | US | Nissan | Maxima       | 2006/01-2006/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                             | 40700-CK001                                                                 |
| A0543 | US | Nissan | Maxima       | 2007/01-2007/12 | Alloy     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                             | 40700-CK001                                                                 |
| A0544 | US | Nissan | Maxima       | 2007/01-2007/12 | Steel     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 407001AA0B/<br>40700JA01B/<br>40700JA02B                               |                             | 40700-1AA0B/<br>40700-JA01B/<br>40700-JA02B                                 |
| A0545 | US | Nissan | Maxima       | 2008/01-2011/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 407001AA0D/<br>407001AA0B/<br>40700JA01B/<br>40700JA02B                |                             | 40700-1AA0D/<br>40700-1AA0B/<br>40700-JA01B/<br>40700-JA02B                 |
| A0546 | US | Nissan | Maxima (SCH) | 2012/01-2015/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 407001AA0D                                                             |                             | 407001AA0D                                                                  |
| A0547 | US | Nissan | Maxima GCC   | 2013/01-2013/12 | 433MHz    | ● | ● | 4 | S   | 433Mhz | Schrader    | 40700JY00B                                                             | 90518295                    | 40700-JY00B                                                                 |
| A0548 | US | Nissan | Murano       | 2003/01-2006/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CD001                                                             |                             | 40700-CD001                                                                 |
| A0549 | US | Nissan | Murano       | 2007/01-2009/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 407001AA0B/<br>40700JA01B/<br>40700JA02B                               |                             | 40700-1AA0B/<br>40700-JA01B/<br>40700-JA02B                                 |
| A0550 | US | Nissan | Murano       | 2010/01-2014/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 407001AA0B/<br>407001AA0C/<br>40700JA01B                               |                             | 40700-1AA0B/<br>40700-1AA0C/<br>40700-JA01B                                 |
| A0551 | US | Nissan | Murano       | 2015/01-2016/12 | 433MHz    | ● | ● | 4 | 0   | 433Mhz | Continental | 407003JA0B/<br>407003JA0A                                              |                             |                                                                             |
| A0552 | US | Nissan | NV 200       | 2013/01-2015/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 407001AA0D                                                             |                             | 40700-1AA0D                                                                 |
| A0553 | US | Nissan | NV1500       | 2012/01-2015/12 | 315MHz    | ● | ● | 4 | S   | 315Mhz | Schrader    | 407001PA0A                                                             |                             | 40700-1PA0A                                                                 |
| A0554 | US | Nissan | NV2500HD     | 2012/01-2015/12 | 315MHz    | ● | ● | 4 | S   | 315Mhz | Schrader    | 407001PA0A                                                             |                             | 40700-1PA0A                                                                 |
| A0555 | US | Nissan | NV3500HD     | 2012/01-2015/12 | 315MHz    | ● | ● | 4 | S   | 315Mhz | Schrader    | 407001PA0A                                                             |                             | 40700-1PA0A                                                                 |
| A0556 | US | Nissan | Pathfinder   | 2003/01-2003/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CD001                                                             |                             | 40700-CD001                                                                 |
| A0557 | US | Nissan | Pathfinder   | 2004/01-2004/12 | Alloy     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                             | 40700-CK001                                                                 |
| A0558 | US | Nissan | Pathfinder   | 2004/01-2004/12 | Steel     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CK002                                                             |                             | 40700-CK002                                                                 |
| A0559 | US | Nissan | Pathfinder   | 2005/01-2006/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                             | 40700-CK001                                                                 |
| A0560 | US | Nissan | Pathfinder   | 2007/01-2012/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 407001AA0B/<br>40700JA02B                                              |                             | 40700-1AA0B/<br>40700-JA02B                                                 |
| A0561 | US | Nissan | Pathfinder   | 2013/01-2015/12 | 433MHz    | ● | ● | 4 | 0/S | 433Mhz | Continental | 407003JA0B/<br>407003JA0A                                              | S180052036G/<br>S180052036Z | S180052036                                                                  |
| A0562 | US | Nissan | Patrol       | 2008/01-2010/12 | 433MHz    | ● | ● | 4 | 0   | 433Mhz | Pacific     | 407001LL0C                                                             | PMV-107U                    | 40700-1LL0C                                                                 |
| A0563 | US | Nissan | Quest        | 2004/01-2004/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CK002                                                             |                             | 40700-CK002                                                                 |
| A0564 | US | Nissan | Quest        | 2005/01-2007/12 | Alloy     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                             | 40700-CK001                                                                 |
| A0565 | US | Nissan | Quest        | 2005/01-2007/12 | Steel     | ● | ● | 4 | 0   | 315Mhz | Schrader    | 40700CK002                                                             |                             | 40700-CK002                                                                 |
| A0566 | US | Nissan | Quest        | 2008/01-2010/12 | 315MHz    | ● | ● | 4 | 0   | 315Mhz | Schrader    | 407001AA0B/<br>40700JA01B/<br>40700JA02B                               |                             | 40700-1AA0B/<br>40700-JA01B/<br>40700-JA02B                                 |

|       |    |        |                 |                 |           |   |   |     |     |        |             |                                                                        |                       |                                                                             |
|-------|----|--------|-----------------|-----------------|-----------|---|---|-----|-----|--------|-------------|------------------------------------------------------------------------|-----------------------|-----------------------------------------------------------------------------|
| A0567 | US | Nissan | Quest           | 2011/01-2015/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Pacific     | 407001LA0E/<br>407001LA0D/<br>407001LA0C/<br>407001LA0B/<br>407001LA0A | PMV-C811/<br>PMV-107S | 40700-1LA0E/<br>40700-1LA0D/<br>40700-1LA0C/<br>40700-1LA0B/<br>40700-1LA0A |
| A0568 | US | Nissan | Rogue           | 2008/01-2013/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0B/<br>40700JA01C                                              |                       | 40700-1AA0B/<br>40700-JA01C                                                 |
| A0569 | US | Nissan | Rogue           | 2014/01-2015/12 | 433MHz    | ● | ● | 4   | S   | 433Mhz | Continental | 407003VU0A                                                             | S180052048Z           | S180052048                                                                  |
| A0570 | US | Nissan | Rogue Select    | 2014/01-2015/12 | Japan     | ● | ● | 4   | S   | 315Mhz | Pacific     | 40700JK01A/<br>40700JK01B                                              | PMV-C813              | 40700-JK01A/<br>40700-JK01B                                                 |
| A0571 | US | Nissan | Rogue Select    | 2014/01-2015/12 | USA       | ● | ● | 4   | S   | 433Mhz | Continental | 407003VU0A                                                             | S180052048Z           | S180052048                                                                  |
| A0572 | US | Nissan | Sentra          | 2007/01-2012/12 | 315MHz    | ● | ● | 4   | 0/S | 315Mhz | Schrader    | 40700CK001/<br>40700JA01B/<br>407001AA0B/<br>40700JA02B                |                       | 40700-CK001                                                                 |
| A0573 | US | Nissan | Sentra          | 2013/01-2015/12 | with iKey | ● | ● | 4   | S   | 315Mhz | Continental | 407003AN1B/<br>407003AN1A                                              | S180052035D           | S180052035                                                                  |
| A0574 | US | Nissan | Sentra          | 2013/01-2015/12 | no iKey   | ● | ● | 4   | S   | 315Mhz | Continental | 407003AN0B/<br>407003AN0A                                              | S180052033G           | S180052033                                                                  |
| A0575 | US | Nissan | Titan           | 2004/01-2004/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK002                                                             |                       | 40700-CK002                                                                 |
| A0576 | US | Nissan | Titan           | 2005/01-2007/12 | Alloy     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                       | 40700-CK001                                                                 |
| A0577 | US | Nissan | Titan           | 2005/01-2007/12 | Steel     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK002                                                             |                       | 40700-CK002                                                                 |
| A0578 | US | Nissan | Titan           | 2008/01-2008/12 | Alloy     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CD001                                                             |                       | 40700-CD001                                                                 |
| A0579 | US | Nissan | Titan           | 2008/01-2008/12 | Steel     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0D/<br>40700JA02B                                              |                       | 40700-1AA0D/<br>40700-JA02B                                                 |
| A0580 | US | Nissan | Titan           | 2009/01-2015/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0D/<br>40700JA02B                                              |                       | 40700-1AA0D/<br>40700-JA02B                                                 |
| A0581 | US | Nissan | Versa Sedan     | 2007/01-2008/12 | Alloy     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK001/<br>407001AA0B                                              |                       | 40700-CK001                                                                 |
| A0582 | US | Nissan | Versa Sedan     | 2007/01-2008/12 | Steel     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0D/<br>407001AA0B/<br>40700JA02B                               |                       | 40700-1AA0D/<br>40700-1AA0B/<br>40700-JA02B                                 |
| A0583 | US | Nissan | Versa Sedan     | 2009/01-2011/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0D/<br>407001AA0B/<br>40700JA02B                               |                       | 40700-1AA0D/<br>40700-1AA0B/<br>40700-JA02B                                 |
| A0584 | US | Nissan | Versa Sedan     | 2012/01-2012/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0C/<br>407001AA0B                                              |                       | 407001AA0C/<br>407001AA0B                                                   |
| A0585 | US | Nissan | Versa Sedan     | 2013/01-2016/12 | with iKey | ● | ● | 4   | S   | 315Mhz | Continental | 407003AN1B/<br>407003AN1A                                              | S180052035D           | S180052035                                                                  |
| A0586 | US | Nissan | Versa Sedan     | 2013/01-2016/12 | no iKey   | ● | ● | 4   | S   | 315Mhz | Continental | 407003AN0B/<br>407003AN0A                                              | S180052033G           | S180052033                                                                  |
| A0587 | US | Nissan | Versa Hatchback | 2007/01-2013/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 407001AA0D                                                             | 407001AA0D            | 407001AA0D                                                                  |
| A0588 | US | Nissan | Xterra          | 2003/01-2004/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CD001                                                             |                       | 40700-CD001                                                                 |
| A0589 | US | Nissan | Xterra          | 2005/01-2005/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                       | 40700-CK001                                                                 |
| A0590 | US | Nissan | Xterra          | 2006/01-2011/12 | Alloy     | ● | ● | 4   | 0   | 315Mhz | Schrader    | 40700CK001                                                             |                       | 40700-CK001                                                                 |
| A0591 | US | Nissan | Xterra          | 2006/01-2011/12 | Steel     | ● | ○ | 4   | 0   | 315Mhz | Schrader    | 40700CK002                                                             |                       | 40700-CK002                                                                 |
| A0592 | US | Nissan | Xterra          | 2012/01-2015/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Continental | 407003AN0B/<br>407003AN0A                                              | S180052033G           | S180052033                                                                  |
| A0593 | US | Scion  | FR-S            | 2013/01-2016/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Pacific     | SU00300754                                                             | 3729A-PMVC010         |                                                                             |
| A0594 | US | Scion  | IQ              | 2012/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Pacific     | 4260733011                                                             | PMV-107J              | 42607-33011                                                                 |
| A0595 | US | Scion  | TC              | 2006/01-2016/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Pacific     | 4260733011                                                             | PMV-107J              | 42607-33011                                                                 |
| A0596 | US | Scion  | XB              | 2007/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Pacific     | 4260733011                                                             | PMV-107J              | 42607-33011                                                                 |
| A0597 | US | Scion  | XD              | 2008/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0   | 315Mhz | Pacific     | 4260733011                                                             | PMV-107J              | 42607-33011                                                                 |
| A0598 | US | Subaru | B9 Tribeca      | 2006/01-2014/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 28103AG00B/<br>28103AG00A                                              |                       | 28103AG00B/<br>28103AG00A                                                   |
| A0599 | US | Subaru | BRZ             | 2013/01-2016/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Pacific     | 28103CA000                                                             | PMV-C010              | 28103CA000                                                                  |
| A0600 | US | Subaru | Forester        | 2008/01-2015/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 28103AG01C                                                             |                       | 28103AG01C                                                                  |
| A0601 | US | Subaru | Impreza         | 2008/01-2015/12 | 315MHz    | ● | ● | 4   | 0   | 315Mhz | Schrader    | 28103AG01C                                                             |                       | 28103AG01C                                                                  |

|       |    |        |                   |                 |           |   |   |     |   |        |             |                                                         |               |                                                             |
|-------|----|--------|-------------------|-----------------|-----------|---|---|-----|---|--------|-------------|---------------------------------------------------------|---------------|-------------------------------------------------------------|
| A0602 | US | Subaru | Legacy            | 2004/01-2007/12 | 315MHz    | ● | ● | 4   | 0 | 315Mhz | Schrader    | 28103AG00B/<br>28103AG00A                               |               | 28103AG00B/<br>28103AG00A                                   |
| A0603 | US | Subaru | Legacy            | 2008/01-2015/12 | 315MHz    | ● | ● | 4   | 0 | 315Mhz | Schrader    | 28103AG01C                                              |               | 28103AG01C                                                  |
| A0604 | US | Subaru | Outback           | 2004/01-2007/12 | 315MHz    | ● | ● | 4   | 0 | 315Mhz | Schrader    | 28103AG00B/<br>28103AG00A                               |               | 28103AG00B/<br>28103AG00A                                   |
| A0605 | US | Subaru | Outback           | 2008/01-2015/12 | 315MHz    | ● | ● | 4   | 0 | 315Mhz | Schrader    | 28103AG01C                                              |               | 28103AG01C                                                  |
| A0606 | US | Subaru | Tribeca           | 2008/01-2015/12 | 315MHz    | ● | ● | 4   | 0 | 315Mhz | Schrader    | 28103AG01C                                              |               | 28103AG01C                                                  |
| A0607 | US | Subaru | XV Crosstrek      | 2013/01-2015/12 | 315MHz    | ● | ● | 4   | 0 | 315Mhz | Schrader    | 28103AG01C                                              |               | 28103AG01C                                                  |
| A0608 | US | Suzuki | Equator           | 2009/01-2013/12 | 315MHz    | ○ | ● | 4   | S | 315Mhz | Schrader    | 4321182Z00                                              |               | 43211-82Z00                                                 |
| A0609 | US | Suzuki | Forenza           | 2007/01-2008/12 | 315MHz    | ○ | ● | 4   | S | 315Mhz | Schrader    | 4313085Z03                                              |               | 43130-85Z03                                                 |
| A0610 | US | Suzuki | Grand Vitara      | 2007/01-2013/12 | 315MHz    | ○ | ● | 4   | S | 315Mhz | Schrader    | 4313054J21                                              |               | 43130-54J21                                                 |
| A0611 | US | Suzuki | Kizashi           | 2010/01-2013/12 | 315MHz    | ○ | ● | 4   | S | 315Mhz | Continental | 4313057L00                                              | S180052015E   | S180052015                                                  |
| A0612 | US | Suzuki | Reno              | 2007/01-2008/12 | 315MHz    | ○ | ● | 4   | S | 315Mhz | Schrader    | 4313085Z00                                              |               |                                                             |
| A0613 | US | Suzuki | SX4               | 2007/01-2013/12 | 315MHz    | ○ | ● | 4   | S | 315Mhz | Schrader    | 4313054J21                                              |               | 43130-54J21                                                 |
| A0614 | US | Suzuki | Verona            | 2005/01-2006/12 | 315MHz    | ○ | ● | 4   | S | 315Mhz | Schrader    | 4313086Z20                                              |               | 43130-86Z20                                                 |
| A0615 | US | Suzuki | XL-7              | 2005/01-2006/12 | 315MHz    | ○ | ● | 4   | S | 315Mhz | Schrader    | 4313054J21                                              |               | 43130-54J21                                                 |
| A0616 | US | Suzuki | XL-7              | 2007/01-2011/12 | 315MHz    | ○ | ● | 4   | S | 315Mhz | Continental | 4313078J10                                              |               |                                                             |
| A0617 | US | Toyota | 4 Runner          | 2003/01-2006/08 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260735010                                              | PMV-1017      | 42607-35010                                                 |
| A0619 | US | Toyota | 4 Runner          | 2006/09-2016/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J      | 42607-33011/<br>42607-06011/<br>42607-33021                 |
| A0621 | US | Toyota | Avalon            | 2007/01-2012/12 | 315Mhz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J      | 42607-33011/<br>42607-06011/<br>42607-33021                 |
| A0622 | US | Toyota | Avalon            | 2013/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260706020                                              | 3729A-PMVC010 | 42607-06020                                                 |
| A0623 | US | Toyota | Camry             | 2007/01-2011/12 | 315Mhz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011/<br>4260706011/<br>4260733021/<br>4260734020 | PMV-107J      | 42607-33011/<br>42607-06011/<br>42607-33021/<br>42607-34020 |
| A0625 | US | Toyota | Camry             | 2012/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260706020                                              | 3729A-PMVC010 | 42607-06020                                                 |
| A0626 | US | Toyota | Camry Hybrid      | 2008/01-2011/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011/<br>4260706011/<br>4260733021/<br>4260734020 | PMV-107J      | 42607-33011/<br>42607-06011/<br>42607-33021/<br>42607-34020 |
| A0627 | US | Toyota | Camry Hybrid      | 2014/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260706020                                              | 3729A-PMVC010 | 42607-06020                                                 |
| A0628 | US | Toyota | Corolla           | 2006/01-2013/12 | 315Mhz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011/<br>4260706011/<br>4260733021/<br>4260734020 | PMV-107J      | 42607-33011/<br>42607-06011/<br>42607-33021/<br>42607-34020 |
| A0630 | US | Toyota | Corolla           | 2014/01-2016/12 | 315MHz    | ● | ● | 4/5 | S | 315Mhz | Pacific     | 4260706020                                              | 3729A-PMVC010 | 42607-06020                                                 |
| A0632 | US | Toyota | FJ Cruiser        | 2008/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J      | 42607-33011/<br>42607-06011/<br>42607-33021                 |
| A0634 | US | Toyota | Highlander        | 2007/01-2013/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J      | 42607-33011/<br>42607-06011/<br>42607-33021                 |
| A0635 | US | Toyota | Highlander        | 2014/01-2016/12 | Smart Key | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260706020                                              | 3729A-PMVC010 | 42607-06020                                                 |
| A0636 | US | Toyota | Highlander Hybrid | 2008/01-2012/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011                                              | PMV-107J      | 42607-33011                                                 |
| A0637 | US | Toyota | Highlander Hybrid | 2013/01-2014/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260706020                                              |               | 42607-06020                                                 |
| A0638 | US | Toyota | Highlander RKE    | 2014/01-2016/12 | Canada    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 426070R010                                              | 228408-101    | 228408-101                                                  |
| A0639 | US | Toyota | Land Cruiser      | 2005/01-2005/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J      | 42607-33011/<br>42607-06011/<br>42607-33021                 |
| A0642 | US | Toyota | Land Cruiser      | 2006/01-2014/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J      | 42607-33011/<br>42607-06011/<br>42607-33021                 |
| A0643 | US | Toyota | Land Cruiser      | 2015/01-2015/12 | 315MHz    | ● | ● | 4/5 | 0 | 315Mhz | Pacific     | 4260730060                                              | 3729A-PMVC010 | 42607-30060                                                 |

|       |    |        |                    |                 |              |   |   |     |   |        |         |                                                         |                                          |                                             |
|-------|----|--------|--------------------|-----------------|--------------|---|---|-----|---|--------|---------|---------------------------------------------------------|------------------------------------------|---------------------------------------------|
| A0644 | US | Toyota | Matrix             | 2007/01-2014/12 | Japan made   | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0645 | US | Toyota | Matrix             | 2007/01-2014/12 | USA made     | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0646 | US | Toyota | Prius              | 2006/01-2012/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0647 | US | Toyota | Prius              | 2013/01-2015/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0648 | US | Toyota | Prius C            | 2012/01-2015/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260706020                                              | 3729A-PMVC010                            | 42607-06020                                 |
| A0649 | US | Toyota | Prius V            | 2012/01-2016/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0650 | US | Toyota | RAV4               | 2006/01-2006/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0651 | US | Toyota | RAV4               | 2007/01-2013/06 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0652 | US | Toyota | RAV4(Smart key)    | 2013/07-2016/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260752020/<br>4260706020                               | 3729A-PMVC010                            | 42607-52020/<br>42607-06020                 |
| A0653 | US | Toyota | RAV4(Standard key) | 2013/07-2016/12 | 315Mhz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 426070R010                                              | 228408-101                               | 228408-101                                  |
| A0654 | US | Toyota | RAV4 EV            | 2012/01-2012/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0655 | US | Toyota | Sequoia            | 2004/01-2007/12 | 315Mhz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260733021/<br>4260706011/<br>426070C020 | PMV-107J                                 | 42607-0C020                                 |
| A0657 | US | Toyota | Sequoia            | 2008/01-2008/12 | 315Mhz       | ● | ● | 4/5 | 0 | 315Mhz | TRW     | 426070C070/<br>4260708010/<br>426070C030                | 226196-101/<br>216709-106/<br>216709-101 | 226196-101/<br>216709-106/<br>216709-101    |
| A0659 | US | Toyota | Sequoia            | 2009/01-2016/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | TRW     | 426070C070/<br>4260708010                               | 226196-101/<br>216709-106                | 226196-101/<br>216709-106                   |
| A0660 | US | Toyota | Sienna             | 2006/01-2015/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | TRW     | 426070C070/<br>4260708010                               | 226196-101/<br>216709-106                | 226196-101/<br>216709-106                   |
| A0661 | US | Toyota | Solara             | 2006/01-2011/12 | 315MHz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0662 | US | Toyota | Tacoma             | 2005/01-2006/06 | Alloy        | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 42607AD020                                              | PMV-1017                                 | 42607-AD020                                 |
| A0663 | US | Toyota | Tacoma             | 2005/01-2006/06 | Steel        | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260704010                                              | PMV-108J                                 |                                             |
| A0664 | US | Toyota | Tacoma             | 2006/07-2015/12 | Alloy        | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260706011/<br>4260733021                | PMV-107J                                 | 42607-33011/<br>42607-06011/<br>42607-33021 |
| A0665 | US | Toyota | Tacoma             | 2006/07-2015/12 | Steel        | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260704010                                              | PMV-108J                                 |                                             |
| A0667 | US | Toyota | Tundra             | 2005/01-2005/12 | 315Mhz       | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260733021/<br>4260706011                | PMV-107J                                 | 42607-33011/<br>42607-33021/<br>42607-06011 |
| A0668 | US | Toyota | Tundra             | 2006/01-2006/12 | lloy Pacific | ● | ● | 4/5 | 0 | 315Mhz | Pacific | 4260733011/<br>4260733021/<br>4260706011/<br>426070C020 | PMV-107J                                 | 42607-0C020                                 |
| A0669 | US | Toyota | Tundra             | 2006/01-2006/12 | Alloy TRW    | ● | ● | 4/5 | 0 | 315Mhz | TRW     | 426070C070/<br>4260708010/<br>426070C050                | 226196-101/<br>216709-106/<br>216709-105 | 226196-101/<br>216709-106/<br>216709-105    |

|       |    |         |                |                 |               |   |   |     |           |        |             |                                          |                                          |                                             |
|-------|----|---------|----------------|-----------------|---------------|---|---|-----|-----------|--------|-------------|------------------------------------------|------------------------------------------|---------------------------------------------|
| A0670 | US | Toyota  | Tundra         | 2006/01-2006/12 | Steel Pacific | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260733011/<br>4260733021/<br>4260706011 | PMV-107J                                 | 42607-33011/<br>42607-33021/<br>42607-06011 |
| A0671 | US | Toyota  | Tundra         | 2006/01-2006/12 | Steel TRW     | ● | ● | 4/5 | 0         | 315Mhz | TRW         | 426070C060                               | 216710-105                               | 216710-106                                  |
| A0672 | US | Toyota  | Tundra         | 2007/01-2016/12 | Alloy         | ● | ● | 4/5 | 0         | 315Mhz | TRW         | 426070C070/<br>4260708010/<br>426070C050 | 226196-101/<br>216709-106/<br>216709-105 | 226196-101/<br>216709-106/<br>216709-105    |
| A0673 | US | Toyota  | Tundra         | 2007/01-2015/12 | Steel         | ● | ● | 4/5 | 0         | 315Mhz | TRW         | 426070C060                               | 216710-105                               | 216710-106                                  |
| A0674 | US | Toyota  | Venza          | 2009/01-2015/12 | 315MHz        | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260733011/<br>4260733021/<br>4260706011 | PMV-107J                                 | 42607-33011/<br>42607-33021/<br>42607-06011 |
| A0675 | US | Toyota  | Yaris          | 2007/01-2011/12 | 315MHz        | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260733011/<br>4260733021/<br>4260706011 | PMV-107J                                 | 42607-33011/<br>42607-33021/<br>42607-06011 |
| A0676 | US | Toyota  | Yaris          | 2012/01-2015/12 | 315MHz        | ● | ● | 4/5 | 0         | 315Mhz | Pacific     | 4260706020                               | 3729A-PMVC010                            | 42607-06020                                 |
| A0678 | US | KIA     | Optima         | 2015/01-2015/12 | 315MHz        | ● | ● | 4   | 0         | 315Mhz | Continental | 52933A5000                               | S180052041F                              | S180052041                                  |
| A0680 | EU | Hyundai | Centennial     | 2013/07-2015/12 |               | ● | ● | 4   | 0         | 433Mhz | TRW         | 529333M000                               | 220916-101                               | 220916-101                                  |
| A0681 | EU | Hyundai | Elantra        | 2008/01-2012/12 |               | ● | ● | 4   | 0         | 433Mhz | Continental | 529332L600/<br>529332L000                | S180014820Z                              | S180030002                                  |
| A0684 | EU | Hyundai | Tucson         | 2015/07-2016/06 |               | ● | ● | 4   | 0         | 433Mhz | Schrader    | 52933C1100/<br>52933C8000                |                                          |                                             |
| A0696 | EU | Hyundai | ix35           | 2015/10-2016/12 | TL            | ○ | ● | 4   | Copy only | 433Mhz | Schrader    | 52933C1100/<br>52933C8000                |                                          |                                             |
| A0698 | EU | Suzuki  | Grand Vitara   | 2014/06-2016/06 |               | ○ | ● | 4   | A         | 433Mhz | Continental | 4313961M00/<br>4313061M00                | S180052024Z                              | S180052024                                  |
| A0699 | EU | Suzuki  | Vitara         | 2015/01-2016/06 |               | ○ | ● | 4   | A         | 433Mhz | Continental | 4313961M00/<br>4313061M00                | S180052024Z                              | S180052024                                  |
| A0700 | EU | Lexus   | NX200          | 2014/07-2016/06 |               | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260730070                               | PMV-107J                                 | 42607-30070                                 |
| A0701 | EU | Renault | Kadjar         | 2015/04-2016/06 |               | ○ | ● | 4   | A         | 433Mhz | Continental | 407004CB0A                               | S180150006                               | S180150006D                                 |
| A0702 | US | Acura   | ILX            | 2016/01-2016/12 | 315MHz        | ● | ● | 4   | A         | 315Mhz | Continental | 42753TZ3A51                              | S180052060A                              | S180052060                                  |
| A0703 | US | Acura   | MDX            | 2016/01-2016/12 | 315MHz        | ● | ● | 4   | A         | 315Mhz | Continental | 42753TZ3A51                              | S180052060A                              | S180052060                                  |
| A0704 | US | Acura   | RDX            | 2016/01-2016/12 | 315MHz        | ● | ● | 4   | A         | 315Mhz | Continental | 42753TZ3A51                              | S180052060A                              | S180052060                                  |
| A0706 | EU | Nissan  | NV400          | 2014/06-2016/06 |               | ● | ● | 4   | 0         | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |                                          | 407001628R-B                                |
| A0707 | US | Nissan  | FUGA           | 2003/01-2005/12 | 315MHz        | ● | ● | 4   | 0/S       | 315Mhz | Schrader    | 40700CD001                               |                                          | 40700-CD001                                 |
| A0708 | US | Hyundai | Tucson         | 2014/04-2015/12 | 315MHz        | ○ | ● | 4   | Copy only | 315Mhz | TRW         | 529332S500                               | 225816-127                               | 225816-127                                  |
| A0709 | US | Hyundai | Elantra GT     | 2016/01-2016/12 | 315MHz        | ○ | ● | 4   | Copy only | 315Mhz | Continental | 529333N000/<br>529332M550                | S180052091C                              | S180052091                                  |
| A0710 | EU | Hyundai | Santa Fe       | 2013/04-2016/06 |               | ● | ● | 4   | 0         | 433Mhz | Continental | 529333N100                               | S180052092Z                              | S180052092                                  |
| A0713 | US | Hyundai | Accent         | 2015/01-2016/12 | 433MHz        | ● | ● | 4   | 0         | 433Mhz | Continental | 529333N100                               | S180052092Z                              | S180052092                                  |
| A0714 | US | Hyundai | Elantra        | 2015/01-2016/12 | 315MHz        | ● | ● | 4   | 0         | 315Mhz | TRW         | 529333X205                               |                                          | 52933-3X205                                 |
| A0715 | US | Hyundai | Tucson         | 2016/01-2016/12 | 433MHz        | ○ | ● | 4   | Copy only | 433Mhz | Schrader    | 52933C1100                               |                                          |                                             |
| A0716 | US | Nissan  | Frontier (SCH) | 2013/05-2015/12 | 315MHz        | ● | ● | 4   | 0         | 315Mhz | Schrader    | 407001AA0D                               |                                          | 407001AA0D                                  |
| A0717 | US | Nissan  | Frontier (VDO) | 2013/05-2015/12 | 315MHz        | ● | ● | 4   | 0         | 315Mhz | Continental | 407003AN0A                               |                                          | 40700-3AN0A                                 |
| A0718 | US | Nissan  | Maxima (VDO)   | 2012/01-2015/12 | 315MHz        | ● | ● | 4   | 0         | 315Mhz | Continental | 407003AN0A                               |                                          | 40700-3AN0A                                 |
| A0719 | US | KIA     | Sorento        | 2016/01-2016/12 | 433MHz        | ○ | ● | 4   |           | 433Mhz | Continental | 529333N100                               | S180052092Z                              | S180052092                                  |
| A0720 | US | Nissan  | Maxima (VDO)   | 2016/01-2016/12 | 433Mhz        | ● | ● | 4   |           | 433Mhz | Continental | 407003JA0B                               |                                          |                                             |
| A0721 | US | Subaru  | WRX            | 2015/01-2016/12 | 315Mhz        | ● | ● | 4   |           | 315Mhz | Schrader    | 28103AJ00A                               |                                          |                                             |
| A0722 | US | Acura   | RLX            | 2016/01-2016/12 | 315Mhz        | ● | ● | 4   |           | 315Mhz | Continental | 42753TZ3A51                              | S180052060A                              | S180052060                                  |
| A0723 | EU | KIA     | Optima         | 2015/10-2016/12 | JF            | ○ | ● | 4   | A         | 433Mhz | Continental | 52933D4100                               |                                          |                                             |
| A0724 | EU | Lexus   | RX AL20        | 2016/01-2016/12 |               | ● | ● | 4/5 | 0         | 433Mhz | Pacific     | 4260702020/<br>4260702030/<br>4260702031 | PMV-C210                                 |                                             |
| A0727 | US | KIA     | Forte          | 2016/01-2016/12 | 315MHz        | ○ | ● | 4   | Copy only | 315Mhz | TRW         | 529333X205                               |                                          | 52933-3X205                                 |
| A0728 | US | KIA     | Sedona         | 2015/01-2016/12 | 433MHz        | ○ | ● | 4   |           | 433Mhz | Schrader    | 52933B2100                               |                                          | 52933-B2100                                 |
| A0729 | US | Scion   | IM             | 2016/01-2016/12 | 315Mhz        | ○ | ● | 4/5 | Copy only | 315Mhz | Pacific     | 4260752020                               | 3729A-PMVC010                            | 42607-52020                                 |

|       |    |              |              |                 |        |   |   |   |   |        |             |                                              |             |                                    |
|-------|----|--------------|--------------|-----------------|--------|---|---|---|---|--------|-------------|----------------------------------------------|-------------|------------------------------------|
| A0730 | US | Subaru       | Forester     | 2016/01-2016/12 | 315Mhz | ● | ● | 4 |   | 315Mhz | Schrader    | 28103AJ00A                                   |             |                                    |
| A0731 | US | Subaru       | Impreza      | 2016/01-2016/12 | 315Mhz | ● | ● | 4 |   | 315Mhz | Schrader    | 28103AJ00A                                   |             |                                    |
| A0732 | US | Subaru       | Legacy       | 2016/01-2016/12 | 315Mhz | ● | ● | 4 |   | 315Mhz | Schrader    | 28103AJ00A                                   |             |                                    |
| A0733 | US | Subaru       | Outback      | 2016/01-2016/12 | 315Mhz | ● | ● | 4 |   | 315Mhz | Schrader    | 28103AJ00A                                   |             |                                    |
| A0734 | US | Subaru       | XV Crosstrek | 2016/01-2016/12 | 315Mhz | ● | ● | 4 |   | 315Mhz | Schrader    | 28103AJ00A                                   |             |                                    |
| A0742 | EU | Daewoo       | Gentra       | 2013/08-2016/06 |        | ○ | ● | 4 |   | 433Mhz | Schrader    | 25789964                                     | 90518185    | 25789964/<br>22853740/<br>13581561 |
| A0743 | EU | Daewoo       | Nexia        | 2014/06-2016/06 |        | ○ | ● | 4 |   | 433Mhz | Schrader    | 25789964                                     | 90518185    | 25789964/<br>22853740/<br>13581561 |
| A0756 | EU | Renault      | Laguna IV    | 2015/04-2016/12 |        | ○ | ● | 4 | A | 433Mhz | Continental | 407004CB0A                                   | S180150006  | S180150006                         |
| B0001 | EU | Alpina       | Alpina 3     | 2013/01-2016/06 |        | ○ | ● | 4 | A | 433Mhz | Continental | 36106856209                                  | S180052056F | S180052056                         |
| B0002 | EU | Alpina       | Alpina 3     | 2009/10-2012/12 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                                  | 532207012   | RDE012                             |
| B0003 | EU | Alpina       | Alpina 3     | 2007/03-2009/09 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                                  | 532207008   | RDE008                             |
| B0004 | EU | Alpina       | Alpina 5     | 2010/01-2016/12 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                                  | 532207012   | RDE012                             |
| B0005 | EU | Alpina       | Alpina 6     | 2010/12-2016/06 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                                  | 532207012   | RDE012                             |
| B0006 | EU | Alpina       | Alpina 6     | 2006/03-2010/11 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                                  | 532207008   | RDE008                             |
| B0007 | EU | Alpina       | Alpina 7     | 2010/09-2015/12 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                                  | 532207012   | RDE012                             |
| B0008 | EU | Alpina       | XD3          | 2010/09-2015/12 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                                  | 532207012   | RDE012                             |
| B0009 | EU | Aston Martin | DB9          | 2010/05-2015/12 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA                                 | 532207011   | RDE011                             |
| B0010 | US | Aston Martin | DB9          | 2010/05-2015/12 | 433Mhz | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA/<br>CD23360671AA/<br>7PP907275F | 532207011   | RDE011                             |
| B0011 | EU | Aston Martin | DBS          | 2012/09-2014/12 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | 224549                                       | 532207001   | RDE001                             |
| B0012 | EU | Aston Martin | DBS          | 2007/09-2012/08 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA                                 | 532207011   | RDE011                             |
| B0013 | EU | Aston Martin | Rapide       | 2010/03-2015/12 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA                                 | 532207011   | RDE011                             |
| B0014 | US | Aston Martin | Rapide       | 2010/03-2015/12 | 433Mhz | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA/<br>CD23360671AA/<br>7PP907275F | 532207011   | RDE011                             |
| B0015 | EU | Aston Martin | V12 Vantage  | 2012/01-2013/12 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | CD23360671AA                                 | 532207011   | RDE011                             |
| B0016 | EU | Aston Martin | V12 Zagato   | 2012/09-2015/12 |        | ○ | ● | 4 |   | 433Mhz | Huf/Beru    | 7PP907275F                                   | 532207011   | RDE011                             |
| B0017 | EU | Aston Martin | V8 Vantage   | 2010/05-2015/06 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA                                 | 532207011   | RDE011                             |
| B0018 | EU | Aston Martin | V8 Vantage S | 2013/01-2015/06 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA                                 | 532207011   | RDE011                             |
| B0019 | EU | Aston Martin | Vanquish     | 2012/10-2015/12 |        | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | CD23360671AA                                 | 532207011   | RDE011                             |
| B0020 | US | Aston Martin | Vanquish     | 2010/01-2015/12 | 433Mhz | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA/<br>CD23360671AA/<br>7PP907275F | 532207011   | RDE011                             |
| B0021 | US | Aston Martin | Vantage      | 2010/01-2015/12 | 433Mhz | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA/<br>CD23360671AA/<br>7PP907275F | 532207011   | RDE011                             |
| B0022 | US | Aston Martin | Virage       | 2012/01-2012/12 | 433Mhz | ○ | ● | 4 | A | 433Mhz | Huf/Beru    | AD43360671AA/<br>CD23360671AA/<br>7PP907275F | 532207011   | RDE011                             |
| B0023 | US | Audi         | A3           | 2012/10-2014/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Continental | 1K0907253D                                   | S122215001C |                                    |
| B0024 | EU | Audi         | A3           | 2012/06-2015/12 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 5Q0907275                                    | 532207018   | RDE018                             |
| B0025 | US | Audi         | A3           | 2006/01-2012/10 | 315MHz | ● | ● | 4 | S | 315Mhz | Continental | 1K0907253D                                   | S122215001C |                                    |
| B0026 | US | Audi         | A4           | 2009/01-2012/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Continental | 1K0907253D                                   | S122215001C |                                    |
| B0027 | EU | Audi         | A4           | 2004/11-2008/07 |        | ● | ● | 4 | S | 433Mhz | Huf/Beru    | 4F0907275D                                   | 532207011   | RDE011                             |
| B0028 | US | Audi         | A4           | 2002/01-2008/12 | 433MHz | ● | ● | 4 | S | 433Mhz | Huf/Beru    | 4F0907275B                                   | 532207011   | RDE011                             |
| B0029 | US | Audi         | A4 Cabriolet | 2003/01-2012/12 | 433MHz | ● | ● | 4 | S | 433Mhz | Huf/Beru    | 4F0907275D                                   | 532207011   | RDE011                             |
| B0030 | US | Audi         | A5           | 2008/01-2012/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | 1K0907253D                                   | S122215001C |                                    |
| B0031 | EU | Audi         | A5           | 2006/12-2015/12 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 5Q0907275                                    | 532207018   | RDE018                             |
| B0032 | EU | Audi         | A6           | 2011/01-2015/12 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 5Q0907275                                    | 532207018   | RDE018                             |
| B0033 | US | Audi         | A6           | 2010/01-2015/12 | 433MHz | ● | ● | 4 | S | 433Mhz | Huf/Beru    | 4F0907275D                                   | 532207011   | RDE011                             |
| B0034 | EU | Audi         | A6           | 2009/06-2010/12 |        | ● | ● | 4 | S | 433Mhz | Huf/Beru    | 4F0907275E                                   | 532207011   | RDE011                             |

|       |    |      |               |                 |        |   |   |     |   |        |             |                           |             |        |
|-------|----|------|---------------|-----------------|--------|---|---|-----|---|--------|-------------|---------------------------|-------------|--------|
| B0035 | US | Audi | A6            | 2005/01-2009/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0036 | EU | Audi | A6            | 2004/05-2009/05 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0037 | US | Audi | A6            | 2002/01-2004/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Huf/Beru    | 4D0907275A                | 532107001   | RDE004 |
| B0038 | US | Audi | A6 Allroad    | 2010/01-2011/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0039 | EU | Audi | A6 Allroad    | 2009/11-2016/06 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 7PP907275F                | 532207011   | RDE011 |
| B0040 | US | Audi | A6 Allroad    | 2007/01-2009/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0041 | EU | Audi | A6 Allroad    | 2006/01-2009/10 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0042 | US | Audi | A6 Allroad    | 2001/01-2005/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Huf/Beru    | 4D0907275A                | 532107001   | RDE004 |
| B0043 | EU | Audi | A6 Allroad    | 2000/04-2005/12 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C                | 532207001   | RDE001 |
| B0044 | EU | Audi | A6 Quattro    | 2011/01-2015/12 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 5Q0907275                 | 532207018   | RDE018 |
| B0045 | EU | Audi | A6 Quattro    | 2009/06-2010/12 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275E                | 532207011   | RDE011 |
| B0046 | EU | Audi | A6 Quattro    | 2004/01-2009/05 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 7PP907275F                | 532207011   | RDE011 |
| B0047 | EU | Audi | A7            | 2010/09-2016/06 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 5Q0907275                 | 532207018   | RDE018 |
| B0049 | EU | Audi | A8            | 2009/11-2016/06 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 7PP907275F                | 532207011   | RDE011 |
| B0050 | US | Audi | A8            | 2004/01-2015/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C                | 532107001   | RDE001 |
| B0051 | US | Audi | A8            | 2003/01-2012/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Huf/Beru    | 4D0907275A                | 532107001   | RDE004 |
| B0052 | US | Audi | A8            | 2003/01-2003/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C                | 532107001   | RDE001 |
| B0053 | EU | Audi | A8            | 2002/10-2010/07 |        | ● | ● | 4/5 | S | 433Mhz | Huf/Beru    | 4D0907275C                | 532207001   | RDE001 |
| B0054 | US | Audi | A8            | 2000/01-2002/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Huf/Beru    | 4D0907275A                | 532107001   | RDE004 |
| B0055 | EU | Audi | A8            | 1999/01-2001/11 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C                | 532207001   | RDE001 |
| B0056 | EU | Audi | Q3 (8U)       | 2011/07-2016/06 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 5Q0907275                 | 532207018   | RDE018 |
| B0057 | US | Audi | Q5            | 2009/01-2015/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Continental | 1K0907253D                | S122215001C |        |
| B0058 | EU | Audi | Q5            | 2008/09-2016/06 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 5Q0907275                 | 532207018   | RDE018 |
| B0059 | EU | Audi | Q7            | 2015/01-2016/06 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 5Q0907275                 | 532207018   | RDE018 |
| B0060 | US | Audi | Q7            | 2010/01-2015/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0061 | EU | Audi | Q7            | 2009/06-2014/12 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 7PP907275F                | 532207011   | RDE011 |
| B0062 | EU | Audi | Q7            | 2005/11-2009/05 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 7PP907275F                | 532207011   | RDE011 |
| B0063 | US | Audi | Q7            | 2005/01-2009/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0064 | US | Audi | Q7            | 2005/01-2009/12 | 315MHz | ○ | ● | 4   |   | 315Mhz | Huf/Beru    | 4F0907275H/<br>7PP907275G |             |        |
| B0065 | US | Audi | R8            | 2010/01-2015/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0066 | EU | Audi | R8            | 2009/06-2015/03 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275E                | 532207011   | RDE011 |
| B0067 | US | Audi | R8            | 2008/01-2009/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0068 | EU | Audi | R8            | 2006/01-2009/05 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0069 | US | Audi | RS4           | 2007/01-2008/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0070 | EU | Audi | RS4           | 2006/04-2008/12 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0071 | US | Audi | RS4 Cabriolet | 2008/01-2009/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0072 | US | Audi | RS6           | 2000/01-2005/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Huf/Beru    | 4D0907275A                | 532107001   | RDE004 |
| B0073 | US | Audi | RS6           | 2000/01-2005/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C                | 532207001   | RDE001 |
| B0074 | EU | Audi | RS6/RS6 Plus  | 2013/01-2016/06 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 7PP907275F                | 532207011   | RDE011 |
| B0075 | EU | Audi | RS6/RS6 Plus  | 2008/01-2010/12 |        | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0076 | EU | Audi | RS6/RS6 Plus  | 2000/04-2005/09 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C                | 532207001   | RDE001 |
| B0077 | US | Audi | RS7           | 2014/01-2015/12 | 433Mhz | ● | ● | 4   |   | 433Mhz | Huf/Beru    | 7PP907275F                | 532207011   | RDE011 |
| B0078 | EU | Audi | RS7           | 2013/01-2015/12 |        | ● | ● | 4   |   | 433Mhz | Huf/Beru    | 7PP907275F                | 532207011   | RDE011 |
| B0079 | US | Audi | S4            | 2010/01-2014/12 | 315MHz | ● | ● | 4   | A | 315Mhz | Continental | 1K0907253D                | S122215001C |        |
| B0080 | EU | Audi | S4            | 2004/01-2007/12 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0081 | US | Audi | S4            | 2002/01-2008/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0082 | US | Audi | S5            | 2008/01-2014/12 | 315MHz | ● | ● | 4   | A | 315Mhz | Continental | 1K0907253D                | S122215001C |        |
| B0083 | US | Audi | S6            | 2010/01-2011/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0084 | EU | Audi | S6            | 2009/07-2011/12 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0085 | US | Audi | S6            | 2004/01-2009/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0086 | EU | Audi | S6            | 2004/01-2009/06 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275B                | 532207011   | RDE011 |
| B0087 | EU | Audi | S8            | 2009/11-2016/06 |        | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4F0907275D                | 532207011   | RDE011 |
| B0088 | US | Audi | S8            | 2008/01-2009/12 | 433MHz | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C                | 532207001   | RDE001 |

|       |    |         |                         |                 |         |   |   |     |   |        |             |             |             |            |
|-------|----|---------|-------------------------|-----------------|---------|---|---|-----|---|--------|-------------|-------------|-------------|------------|
| B0089 | US | Audi    | S8                      | 2004/01-2007/12 | 433MHz  | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C  | 532207001   | RDE001     |
| B0090 | US | Audi    | S8                      | 2003/01-2003/12 | 315MHz  | ● | ● | 4   | S | 315Mhz | Huf/Beru    | 4D0907275A  | 532107001   | RDE004     |
| B0091 | US | Audi    | S8                      | 2003/01-2003/12 | 433MHz  | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C  | 532207001   | RDE001     |
| B0092 | EU | Audi    | S8                      | 2002/10-2009/10 |         | ● | ● | 4/5 | S | 433Mhz | Huf/Beru    | 4D0907275C  | 532207001   | RDE001     |
| B0093 | US | Audi    | S8                      | 2000/01-2002/12 | 315MHz  | ● | ● | 4   | S | 315Mhz | Huf/Beru    | 4D0907275A  | 532107001   | RDE004     |
| B0094 | EU | Audi    | S8                      | 1999/09-2002/09 |         | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C  | 532207001   | RDE001     |
| B0095 | US | Audi    | SQ5                     | 2014/01-2015/12 | 433Mhz  | ● | ● | 4   |   | 433Mhz | Huf/Beru    | 4F0907275D  | 532207011   | RDE011     |
| B0096 | EU | Audi    | TT                      | 2014/02-2016/06 |         | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 5Q0907275   | 532207018   | RDE018     |
| B0097 | US | Audi    | TT                      | 2007/01-2014/12 | 315MHz  | ● | ● | 4   | S | 315Mhz | Continental | 1K0907253D  | S122215001C |            |
| B0100 | US | Bentley | Arnage                  | 2008/01-2008/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275B  | 532207011   | RDE011     |
| B0101 | US | Bentley | Azure                   | 2010/01-2015/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275B  | 532207011   | RDE011     |
| B0102 | EU | Bentley | Azure                   | 2007/01-2016/06 |         | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 7PP907275F  | 532207011   | RDE011     |
| B0103 | US | Bentley | Azure                   | 2007/01-2009/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275B  | 532207011   | RDE011     |
| B0105 | US | Bentley | Continental             | 2012/01-2015/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275D  | 532207011   | RDE011     |
| B0106 | US | Bentley | Continental             | 2006/01-2011/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275B  | 532207011   | RDE011     |
| B0107 | US | Bentley | Continental             | 2005/06-2005/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275B  | 532207011   | RDE011     |
| B0108 | US | Bentley | Continental             | 2005/01-2005/05 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4D0907275C  | 532207001   | RDE001     |
| B0109 | US | Bentley | Continental             | 2003/01-2004/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4D0907275C  | 532207001   | RDE001     |
| B0110 | EU | Bentley | Continental Flying Spur | 2005/03-2016/06 |         | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 7PP907275F  | 532207011   | RDE011     |
| B0111 | EU | Bentley | Continental GT          | 2005/06-2016/06 |         | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 7PP907275F  | 532207011   | RDE011     |
| B0112 | EU | Bentley | Continental GT          | 2003/09-2005/05 |         | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 4D0907275C  | 532207001   | RDE001     |
| B0113 | US | Bentley | Flying Spur             | 2011/01-2015/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275B  | 532207011   | RDE011     |
| B0114 | US | Bentley | Flying Spur             | 2005/01-2010/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275B  | 532207011   | RDE011     |
| B0115 | US | Bentley | Flying Spur             | 2005/01-2010/12 | 315MHz  | ○ | ● | 4   | A | 315Mhz | Huf/Beru    | 4F0907275C  |             |            |
| B0116 | US | Bentley | Mulsanne                | 2013/01-2015/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275D  | 532207011   | RDE011     |
| B0117 | US | Bentley | Mulsanne                | 2011/01-2012/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275B  | 532207011   | RDE011     |
| B0118 | EU | Bentley | Mulsanne                | 2010/01-2016/06 |         | ● | ● | 4   | S | 433Mhz | Huf/Beru    | 7PP907275F  | 532207011   | RDE011     |
| B0119 | EU | BMW     | 1 Series                | 2014/03-2016/06 |         | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0120 | US | BMW     | 1 Series                | 2010/10-2015/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0121 | EU | BMW     | 1 Series                | 2010/09-2014/02 |         | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0122 | US | BMW     | 1 Series                | 2007/01-2010/09 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0123 | EU | BMW     | 1 Series                | 2006/12-2010/08 |         | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0124 | EU | BMW     | 2 Series                | 2014/07-2016/06 | F45/F46 | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0125 | US | BMW     | 2 SERIES                | 2014/03-2016/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0126 | EU | BMW     | 2 Series                | 2014/03-2016/06 | F22/F23 | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0127 | US | BMW     | 2 SERIES                | 2014/01-2014/12 | 433MHz  | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0128 | EU | BMW     | 3 Series                | 2014/03-2016/06 |         | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0129 | US | BMW     | 3 Series                | 2010/01-2013/06 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0130 | EU | BMW     | 3 Series                | 2009/09-2011/09 |         | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0131 | US | BMW     | 3 Series                | 2007/01-2009/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0132 | EU | BMW     | 3 Series                | 2006/01-2009/08 |         | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0133 | US | BMW     | 3 Series                | 2000/01-2006/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36118378682 | 532207002   | RDE002     |
| B0134 | US | BMW     | 3 Series                | 2000/01-2002/12 | 315MHz  | ● | ● | 4   | A | 315Mhz | Huf/Beru    | 36118378681 | 532107001   | RDE004     |
| B0135 | EU | BMW     | 3 Series                | 1999/03-2005/12 |         | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36118378682 | 532207002   | RDE002     |
| B0136 | US | BMW     | 3 Series                | 1999/01-1999/12 | 315MHz  | ● | ● | 4   | A | 315Mhz | Huf/Beru    | 36118378681 | 532107001   | RDE004     |
| B0137 | US | BMW     | 3 Series GT             | 2014/03-2016/12 | 433MHz  | ○ | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0138 | US | BMW     | 3 Series GT             | 2013/01-2014/02 | 433MHz  | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0139 | US | BMW     | 3 Series Sedan          | 2014/03-2015/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0140 | US | BMW     | 3 Series Sedan          | 2013/01-2014/02 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0141 | US | BMW     | 3 Series Wagon          | 2014/03-2016/12 | 433MHz  | ○ | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0142 | US | BMW     | 3 Series Wagon          | 2013/01-2014/02 | 433MHz  | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0143 | US | BMW     | 4 Series                | 2005/01-2013/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0144 | EU | BMW     | 4 Series F32/F33/F36    | 2014/03-2016/06 |         | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0145 | US | BMW     | 4 Series (Huf)          | 2014/01-2014/12 | 433MHz  | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |

|       |    |     |                |                 |        |   |   |     |   |        |             |             |             |            |
|-------|----|-----|----------------|-----------------|--------|---|---|-----|---|--------|-------------|-------------|-------------|------------|
| B0146 | US | BMW | 4 Series (VD0) | 2014/03-2016/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0147 | EU | BMW | 5 Series       | 2014/03-2016/06 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0148 | US | BMW | 5 Series       | 2010/10-2016/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0149 | EU | BMW | 5 Series       | 2010/09-2014/02 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0150 | EU | BMW | 5 Series       | 2006/03-2010/08 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0151 | US | BMW | 5 Series       | 2006/01-2010/09 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0152 | US | BMW | 5 Series       | 2003/01-2005/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36118378682 | 532207002   | RDE002     |
| B0153 | US | BMW | 5 Series       | 2002/01-2002/12 | 315MHz | ● | ● | 4   | A | 315Mhz | Huf/Beru    | 36118378681 | 532107001   | RDE004     |
| B0154 | US | BMW | 5 Series       | 2002/01-2002/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36118378682 | 532207002   | RDE002     |
| B0155 | EU | BMW | 5 Series       | 2001/01-2006/12 |        | ○ | ● | 4   | S | 433Mhz | Huf/Beru    | 36112360420 | 532207002   | RDE002     |
| B0156 | US | BMW | 5 Series       | 2000/01-2001/12 | 315MHz | ● | ● | 4   | A | 315Mhz | Huf/Beru    | 36118378681 | 532107001   | RDE004     |
| B0157 | EU | BMW | 5 Series       | 1998/09-2003/07 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36118378682 | 532207002   | RDE002     |
| B0158 | US | BMW | 5 Series GT    | 2011/01-2016/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0159 | US | BMW | 6 Series       | 2015/01-2016/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0160 | EU | BMW | 6 Series       | 2014/03-2016/06 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0161 | US | BMW | 6 Series       | 2011/01-2014/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0162 | EU | BMW | 6 Series       | 2010/01-2014/02 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0163 | EU | BMW | 6 Series       | 2006/03-2009/12 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236798726 | 532207008   | RDE008     |
| B0164 | US | BMW | 6 Series       | 2006/01-2010/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0165 | US | BMW | 7 Series       | 2015/01-2015/12 | 433Mhz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0166 | EU | BMW | 7 Series       | 2014/03-2015/05 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0167 | US | BMW | 7 Series       | 2010/10-2014/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0168 | EU | BMW | 7 Series       | 2010/09-2014/02 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0169 | US | BMW | 7 Series       | 2006/01-2010/09 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0170 | EU | BMW | 7 Series       | 2006/01-2010/08 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0171 | US | BMW | 7 Series       | 2002/01-2005/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Huf/Beru    | 36118378682 | 532207002   | RDE002     |
| B0172 | US | BMW | 7 Series       | 2000/01-2001/12 | 315MHz | ● | ● | 4   | A | 315Mhz | Huf/Beru    | 36118378681 | 532107001   | RDE004     |
| B0173 | US | BMW | 7 Series       | 2000/01-2001/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36118378682 | 532207002   | RDE002     |
| B0174 | EU | BMW | 7 Series       | 1998/09-2005/12 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36118378682 | 532207002   | RDE002     |
| B0175 | US | BMW | I3             | 2015/01-2016/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0176 | EU | BMW | i3             | 2013/08-2016/06 |        | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0177 | US | BMW | I8             | 2015/01-2016/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0178 | EU | BMW | i8             | 2014/03-2016/06 |        | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0179 | US | BMW | M1             | 2011/01-2012/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0180 | US | BMW | M3             | 2015/01-2015/12 | 433Mhz | ○ | ● | 4   | A | 433Mhz | Continental | 36106856209 |             |            |
| B0181 | EU | BMW | M3             | 2014/04-2016/06 |        | ○ | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0182 | US | BMW | M3             | 2010/01-2013/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106856227 | 532207012   | RDE012     |
| B0183 | US | BMW | M3             | 2008/01-2009/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0184 | US | BMW | M4             | 2015/01-2015/12 | 433Mhz | ○ | ● | 4   | A | 433Mhz | Continental | 36106856209 |             |            |
| B0185 | EU | BMW | M4             | 2014/04-2016/06 |        | ○ | ● | 4   | A | 433Mhz | Continental | 36106856209 | S180052056Z | S180052056 |
| B0186 | EU | BMW | M5             | 2014/03-2016/06 |        | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0187 | US | BMW | M5             | 2011/06-2015/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106856227 | 532207012   | RDE012     |
| B0188 | US | BMW | M5             | 2006/01-2011/05 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0189 | EU | BMW | M6             | 2014/03-2016/06 |        | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0190 | US | BMW | M6             | 2011/06-2015/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106856227 | 532207012   | RDE012     |
| B0191 | US | BMW | M6             | 2006/01-2011/05 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36236781847 | 532207008   | RDE008     |
| B0192 | EU | BMW | M7             | 2014/03-2016/06 |        | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0193 | EU | BMW | X1             | 2015/08-2016/12 |        | ● | ● | 4   | A | 433Mhz | Continental | 36106856209 |             | S180052056 |
| B0194 | US | BMW | X1             | 2015/01-2016/12 | 433Mhz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0195 | EU | BMW | X1             | 2014/03-2015/07 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0196 | US | BMW | X1             | 2012/01-2014/12 | 433MHz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0197 | EU | BMW | X1             | 2009/10-2014/02 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106790054 | 532207012   | RDE012     |
| B0198 | US | BMW | X3             | 2015/01-2016/12 | 433Mhz | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |
| B0199 | EU | BMW | X3             | 2014/03-2016/06 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 36106798872 | 532207017   | RDE017     |

|       |    |         |                |                 |        |   |   |   |   |        |             |                             |             |                           |
|-------|----|---------|----------------|-----------------|--------|---|---|---|---|--------|-------------|-----------------------------|-------------|---------------------------|
| B0200 | US | BMW     | X3             | 2011/05-2014/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                 | 532207012   | RDE012                    |
| B0201 | EU | BMW     | X3             | 2010/11-2014/02 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                 | 532207012   | RDE012                    |
| B0202 | US | BMW     | X3             | 2006/01-2011/04 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847/<br>36236779490 | 532207008   | RDE008                    |
| B0203 | EU | BMW     | X3             | 2003/03-2010/08 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                 | 532207008   | RDE008                    |
| B0204 | US | BMW     | X4             | 2015/01-2016/12 | 433Mhz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106798872                 | 532207017   | RDE017                    |
| B0205 | EU | BMW     | X4             | 2013/07-2015/12 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106798872                 | 532207017   | RDE017                    |
| B0206 | US | BMW     | X5             | 2014/01-2016/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Continental | 36106856209                 | S180052056Z | S180052056                |
| B0207 | EU | BMW     | X5             | 2013/05-2016/06 |        | ● | ● | 4 | A | 433Mhz | Continental | 36106856209                 | S180052056Z | S180052056                |
| B0208 | US | BMW     | X5             | 2011/05-2013/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                 | 532207012   | RDE012                    |
| B0209 | EU | BMW     | X5             | 2011/01-2013/04 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106856227                 | 532207012   | RDE012                    |
| B0210 | EU | BMW     | X5             | 2006/11-2010/12 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                 | 532207008   | RDE008                    |
| B0211 | US | BMW     | X5             | 2006/01-2011/04 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                 | 532207008   | RDE008                    |
| B0212 | US | BMW     | X5             | 2000/01-2005/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36146752128                 | 532207003   | RDE003                    |
| B0213 | EU | BMW     | X5             | 1999/10-2006/10 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36146752128                 | 532207003   | RDE003                    |
| B0214 | US | BMW     | X6             | 2015/01-2016/12 | 433MHz | ○ | ● | 4 | A | 433Mhz | Continental | 36106856209                 | S180052056Z | S180052056                |
| B0215 | EU | BMW     | X6             | 2014/08-2016/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 36106856209                 | S180052056Z | S180052056                |
| B0216 | EU | BMW     | X6             | 2011/12-2014/07 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                 | 532207012   | RDE012                    |
| B0217 | US | BMW     | X6             | 2011/05-2014/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                 | 532207012   | RDE012                    |
| B0218 | US | BMW     | X6             | 2008/01-2011/04 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                 | 532207008   | RDE008                    |
| B0219 | EU | BMW     | X6             | 2007/12-2011/10 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                 | 532207008   | RDE008                    |
| B0220 | US | BMW     | X6 HYBRID      | 2009/01-2011/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                 | 532207008   | RDE008                    |
| B0221 | US | BMW     | Z Series       | 2015/01-2016/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106798872                 | 532207017   | RDE017                    |
| B0222 | US | BMW     | Z Series       | 2011/05-2014/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                 | 532207012   | RDE012                    |
| B0223 | US | BMW     | Z Series       | 2006/01-2011/04 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                 | 532207008   | RDE008                    |
| B0224 | EU | BMW     | Z4             | 2014/03-2016/09 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106798872                 | 532207017   | RDE017                    |
| B0225 | EU | BMW     | Z4             | 2010/09-2014/02 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054                 | 532207012   | RDE012                    |
| B0226 | EU | BMW     | Z4             | 2006/03-2010/08 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847                 | 532207008   | RDE008                    |
| B0227 | EU | BYD     | G5             | 2014/01-2015/12 | 433Mhz | ○ | ● | 4 | S | 433Mhz | BYD         | 6B3609200                   |             |                           |
| B0228 | EU | BYD     | G6             | 2013/01-2015/12 | 433Mhz | ○ | ● | 4 | S | 433Mhz | BYD         | 6B3609200                   |             |                           |
| B0229 | EU | BYD     | S7             | 2015/01-2015/12 | 433Mhz | ○ | ● | 4 | S | 433Mhz | BYD         | 6B3609200                   |             |                           |
| B0230 | EU | BYD     | Sirui          | 2015/01-2015/12 | 433Mhz | ○ | ● | 4 | S | 433Mhz | BYD         | 6B3609200                   |             |                           |
| B0231 | EU | BYD     | Song           | 2016/1-2016/12  | 433Mhz | ○ | ● | 4 | S | 433Mhz | BYD         | 6B3609200                   |             |                           |
| B0232 | EU | BYD     | Surui          | 2015/01-2015/12 | 433Mhz | ○ | ● | 4 | S | 433Mhz | BYD         | 6B3609200                   |             |                           |
| B0233 | EU | BYD     | Tang           | 2015/01-2015/12 | 433Mhz | ○ | ● | 4 | S | 433Mhz | BYD         | 6B3609200                   |             |                           |
| B0234 | EU | Citroen | Berlingo       | 2013/10-2016/12 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 9802003680/<br>9811536380   |             | 9802003680                |
| B0235 | EU | Citroen | Berlingo       | 2008/05-2013/09 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 5430W0                      |             | 9683420380                |
| B0236 | EU | Citroen | Berlingo (LCV) | 2008/05-2013/09 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 9673860880                  |             |                           |
| B0237 | EU | Citroen | C3             | 2014/01-2015/12 |        | ○ | ● | 4 | S | 433Mhz | Schrader    | 9802003680                  |             | 9802003680                |
| B0238 | EU | Citroen | C3             | 2013/01-2013/12 |        | ○ | ● | 4 | A | 433Mhz | Schrader    | 9802003680                  |             | 9802003680                |
| B0239 | EU | Citroen | C4             | 2013/10-2016/06 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 9802003680                  |             | 9802003680                |
| B0240 | EU | Citroen | C4             | 2008/08-2013/09 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 9683420380                  |             |                           |
| B0241 | EU | Citroen | C4             | 2004/11-2008/07 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 5430T4                      | S180014805Z | S120120001                |
| B0243 | EU | Citroen | C4 Picasso     | 2006/05-2013/12 |        | ● | ● | 4 |   | 433Mhz | Schrader    | 5430W0                      | 90818333    | 9673860880                |
| B0244 | EU | Citroen | C5             | 2013/09-2016/06 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 9802003680                  |             | 9802003680                |
| B0245 | EU | Citroen | C5             | 2004/08-2013/08 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 5430T4/<br>543093           | S180014805Z | S120120001                |
| B0246 | EU | Citroen | C5             | 2001/03-2004/07 |        | ● | ● | 4 | S | 433Mhz | Schrader    | 9634866180                  |             |                           |
| B0247 | EU | Citroen | C5 (LCV)       | 2007/10-2015/12 |        | ● | ● | 4 |   | 433Mhz | Schrader    | 9802003680                  |             | 9802003680                |
| B0248 | EU | Citroen | C6             | 2005/09-2013/05 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 5430T4/<br>543093           | S180014805Z | S120120001                |
| B0249 | EU | Citroen | C8             | 2014/07-2015/06 |        | ○ | ● | 4 |   | 433Mhz | Schrader    | 9802003680/<br>9811536380   |             | 9802003680/<br>9811536380 |
| B0250 | EU | Citroen | C8             | 2005/10-2014/06 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 5430T4                      | S180014805Z | S120120001                |

|       |    |         |                |                 |        |   |   |   |           |        |             |                                    |             |             |
|-------|----|---------|----------------|-----------------|--------|---|---|---|-----------|--------|-------------|------------------------------------|-------------|-------------|
| B0251 | EU | Citroen | C8             | 2002/06-2005/09 |        | ● | ● | 4 | S         | 433Mhz | Schrader    | 9634866180                         |             |             |
| B0252 | EU | Citroen | C-Cactus       | 2014/07-2016/06 |        | ○ | ● | 4 | S         | 433Mhz | Schrader    | 9802003680                         |             | 9802003680  |
| B0253 | EU | Citroen | C-Elysee       | 2012/09-2016/06 |        | ○ | ● | 4 | S         | 433Mhz | Schrader    | 9802003680                         |             | 9802003680  |
| B0254 | EU | Citroen | DS3            | 2015/01-2015/12 |        | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 9802003680                         |             | 9802003680  |
| B0255 | EU | Citroen | DS3            | 2009/12-2014/12 |        | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 9802003680                         |             | 9802003680  |
| B0256 | EU | Citroen | DS4            | 2014/02-2016/06 |        | ● | ● | 4 | 0         | 433Mhz | Schrader    | 9802003680                         |             | 9802003680  |
| B0257 | EU | Citroen | DS4            | 2010/12-2014/01 |        | ● | ● | 4 | 0         | 433Mhz | Schrader    | 9683420380                         |             |             |
| B0258 | EU | Citroen | DS4 (LCV)      | 2010/12-2014/01 |        | ● | ● | 4 |           | 433Mhz | Schrader    | 9802003680                         |             | 9802003680  |
| B0259 | EU | Citroen | DS5            | 2014/02-2016/06 |        | ● | ● | 4 | 0         | 433Mhz | Schrader    | 9802003680                         |             | 9802003680  |
| B0260 | EU | Citroen | DS5            | 2011/01-2014/01 |        | ● | ● | 4 | 0         | 433Mhz | Schrader    | 9683420380                         |             |             |
| B0261 | EU | Citroen | DS5 (LCV)      | 2011/06-2015/12 |        | ● | ● | 4 |           | 433Mhz | Schrader    | 9802003680                         |             | 9802003680  |
| B0262 | EU | Citroen | Jumper/Relay   | 2014/06-2016/06 | VAN    | ● | ● | 4 | A         | 433Mhz | Schrader    | 05154876AA/<br>A0009050030         |             | 670002790   |
| B0263 | EU | Citroen | Jumper/Relay   | 2014/06-2016/06 | BUS    | ● | ● | 4 | 0         | 433Mhz | Schrader    | 9802003680/<br>9811536380          |             | 9802003680  |
| B0264 | EU | Citroen | Jumpy/Dispatch | 2014/10-2016/06 |        | ● | ● | 4 | 0         | 433Mhz | Schrader    | 9811764480                         |             | 9811764480  |
| B0265 | EU | Citroen | Jumpy/Dispatch | 2011/01-2014/09 |        | ● | ● | 4 | 0         | 433Mhz | Schrader    | 9677130580                         |             | 9677130580  |
| B0266 | EU | Citroen | Nemo           | 2014/10-2015/12 |        | ○ | ● | 4 | S         | 433Mhz | Schrader    | 53104671                           |             | 53104671    |
| B0267 | EU | Citroen | Nemo           | 2007/10-2013/12 |        | ○ | ● | 4 | A         | 433Mhz | Schrader    | 53104671                           |             | 53104671    |
| B0268 | EU | DFPV    | AX7            | 2015/01-2015/12 | 433MHz | ○ | ● | 4 | Copy only | 433Mhz | Baolong     | FS43X0L4                           |             |             |
| B0269 | EU | Foton   | Tunland        | 2011/01-2015/12 | 433Mhz | ○ | ● | 4 |           | 433Mhz | TTE         | P1311220001A0                      |             |             |
| B0271 | EU | Haval   | H5             | 2010/01-2015/12 | 433Mhz | ○ | ● | 4 | S         | 433Mhz | SAT         | 3641110AK80XA                      |             |             |
| B0272 | EU | Haval   | H6             | 2011/01-2015/12 | 433Mhz | ○ | ● | 4 | S         | 433Mhz | SAT         | 3641100XKZ16A                      |             |             |
| B0274 | US | Jaguar  | F-Pace         | 2016/01-2016/12 | 433Mhz | ○ | ● | 4 |           | 433Mhz | Continental | C2D43636                           |             |             |
| B0275 | EU | Jaguar  | F-Pace         | 2015/12-2016/12 |        | ○ | ● | 4 | A         | 433Mhz | Continental | GX631A159AA                        |             | S180052076A |
| B0276 | US | Jaguar  | F-Type         | 2014/01-2016/12 | 433MHz | ○ | ● | 4 | A         | 433Mhz | Continental | C2D43636                           |             |             |
| B0278 | US | Jaguar  | S Type         | 2008/01-2010/12 | 315MHz | ○ | ● | 4 | A         | 315Mhz | Continental | XR855950                           |             |             |
| B0279 | US | Jaguar  | S Type         | 2005/01-2007/12 | 315MHz | ○ | ● | 4 | A         | 315Mhz | Continental | C2Z15017                           |             |             |
| B0280 | US | Jaguar  | S Type         | 2005/01-2007/12 | 433MHz | ○ | ● | 4 | A         | 433Mhz | Continental | C2Z15016                           | S180084770Z | S180052022  |
| B0281 | US | Jaguar  | X Type         | 2007/01-2011/12 | 315MHz | ○ | ● | 4 | A         | 315Mhz | Continental | XR855950                           |             |             |
| B0282 | US | Jaguar  | XE             | 2016/01-2016/12 | 433Mhz | ○ | ● | 4 |           | 433Mhz | Continental | C2D43636                           |             |             |
| B0283 | EU | Jaguar  | XE             | 2015/12-2016/12 |        | ○ | ● | 4 | A         | 433Mhz | Continental | GX631A159AA                        |             | S180052076A |
| B0284 | EU | Jaguar  | XE             | 2015/02-2015/11 |        | ○ | ● | 4 | Copy only | 433Mhz | Continental | C2D43636                           | S180052028C | S180052028  |
| B0285 | US | Jaguar  | XF             | 2016/01-2016/12 | 433Mhz | ○ | ● | 4 |           | 433Mhz | Continental | C2D43636                           |             |             |
| B0286 | EU | Jaguar  | XF             | 2015/06-2016/12 |        | ○ | ● | 4 | A         | 433Mhz | Continental | GX631A159AA                        |             | S180052076A |
| B0287 | EU | Jaguar  | XF             | 2014/07-2015/05 |        | ○ | ● | 4 | Copy only | 433Mhz | Continental | LR058023                           |             |             |
| B0290 | US | Jaguar  | XF             | 2009/01-2009/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Continental | C2Z15017/<br>C2C41656              |             |             |
| B0291 | US | Jaguar  | XF             | 2009/01-2009/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Continental | C2Z15016                           | S180084770Z | S120123002H |
| B0292 | EU | Jaguar  | XF             | 2007/01-2015/12 |        | ○ | ● | 4 | A         | 433Mhz | Continental | C2Z15016                           | S180084770Z | S120123002H |
| B0293 | US | Jaguar  | XJ             | 2012/01-2016/12 | 433MHz | ○ | ● | 4 | A         | 433Mhz | Continental | C2D43636                           |             |             |
| B0294 | EU | Jaguar  | XJ             | 2010/01-2015/12 |        | ○ | ● | 4 | A         | 433Mhz | Continental | C2Z15016                           | S180084770Z | S180052022  |
| B0295 | EU | Jaguar  | XJ             | 2005/01-2009/12 |        | ○ | ● | 4 | A         | 433Mhz | Continental | C2Z15016                           | S180084770Z | S180052022  |
| B0296 | US | Jaguar  | XJ             | 2004/01-2011/12 | 315MHz | ○ | ● | 4 | A         | 315Mhz | Continental | C2Z15017/<br>XR855950              |             |             |
| B0297 | US | Jaguar  | XJ             | 2004/01-2011/12 | 433MHz | ○ | ● | 4 | A         | 433Mhz | Continental | C2Z15016/<br>XR855949              | S180084770Z | S180052022  |
| B0298 | US | Jaguar  | XJR            | 2006/01-2015/12 | 315MHz | ○ | ● | 4 | A         | 315Mhz | Continental | XR855950                           |             |             |
| B0299 | US | Jaguar  | XK             | 2010/01-2015/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Continental | XR855950/<br>C2Z15017/<br>C2C41656 |             |             |
| B0300 | US | Jaguar  | XK             | 2010/01-2015/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Continental | XR855949                           |             |             |
| B0301 | EU | Jaguar  | XK             | 2006/01-2015/12 |        | ○ | ● | 4 | A         | 433Mhz | Continental | C2Z15016                           | S180084770Z | S180052022  |

|       |    |             |                    |                 |        |   |   |     |           |        |             |                                    |             |             |
|-------|----|-------------|--------------------|-----------------|--------|---|---|-----|-----------|--------|-------------|------------------------------------|-------------|-------------|
| B0302 | US | Jaguar      | XK                 | 2006/01-2009/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Continental | XR855950/<br>C2Z15017/<br>C2C41656 |             |             |
| B0303 | US | Jaguar      | XK                 | 2006/01-2009/12 | 433MHz | ● | ● | 4   | A         | 433Mhz | Continental | XR855949                           |             |             |
| B0304 | US | Jaguar      | XKR                | 2010/01-2015/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Continental | XR855950/<br>C2Z15017/<br>C2C41656 |             |             |
| B0305 | US | Jaguar      | XKR                | 2007/01-2009/12 | 315MHz | ● | ● | 4   | A         | 315Mhz | Continental | XR855950                           |             |             |
| B0306 | EU | Jaguar      | X-Type             | 2007/01-2015/12 |        | ○ | ● | 4   | A         | 433Mhz | Continental | C2Z15016                           | S180084770Z | S180052022  |
| B0307 | US | Lamborghini | Aventador          | 2012/01-2016/12 | 433Mhz | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 7PP907275F                         | 532207011   | RDE011      |
| B0308 | EU | Lamborghini | Aventador          | 2011/05-2016/06 |        | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 7PP907275F                         | 532207011   | RDE011      |
| B0309 | US | Lamborghini | Gallardo           | 2008/01-2013/12 | 433MHz | ○ | ● | 4   |           | 433Mhz | Huf/Beru    | 4F0907275B                         | 532207011   | RDE011      |
| B0310 | EU | Lamborghini | Gallardo           | 2007/01-2015/12 |        | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 7PP907275F                         | 532207011   | RDE011      |
| B0311 | US | Lamborghini | Gallardo LP560-4   | 2009/01-2009/12 | 433MHz | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 4F0907275B                         | 532207011   | RDE011      |
| B0312 | US | Lamborghini | Huracan            | 2015/01-2015/12 | 433Mhz | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 7PP907275F                         |             |             |
| B0313 | US | Lamborghini | Murcielago         | 2008/01-2010/12 | 433MHz | ○ | ● | 4   |           | 433Mhz | Huf/Beru    | 4F0907275B                         | 532207011   | RDE011      |
| B0314 | EU | Lamborghini | Murcielago         | 2007/01-2013/12 |        | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 7PP907275F                         | 532207011   | RDE011      |
| B0315 | US | Lamborghini | Murcielago LP640   | 2007/01-2011/12 | 433MHz | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 4F0907275B                         | 532207011   | RDE011      |
| B0316 | US | Lamborghini | Reventon           | 2008/01-2008/12 | 433MHz | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 4F0907275B                         | 532207011   | RDE011      |
| B0317 | EU | Land Rover  | Discovery 3        | 2005/01-2009/12 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR031712                           | A2C59511308 | T120123002  |
| B0318 | EU | Land Rover  | Discovery 4        | 2015/01-2016/06 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR066378                           | S180052028C | S180052028  |
| B0319 | EU | Land Rover  | Discovery 4        | 2010/01-2014/12 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR031712                           | A2C59511308 | T120123002  |
| B0320 | EU | Land Rover  | Discovery Sport    | 2015/09-2016/12 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | GX631A159AA                        |             | S180052076A |
| B0321 | EU | Land Rover  | Discovery Sport    | 2015/03-2015/08 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR066378                           | S180052028C | S180052028  |
| B0325 | US | Land Rover  | LR2                | 2008/01-2009/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Continental | LR018861                           | T120123002H | T120123002  |
| B0326 | US | Land Rover  | LR3                | 2006/01-2009/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | LR018860                           |             |             |
| B0327 | US | Land Rover  | LR3                | 2006/01-2009/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Continental | LR018861                           | T120123002H | T120123002  |
| B0328 | US | Land Rover  | LR3                | 2002/01-2005/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Huf/Beru    | YDB000060                          | 532207003   | RDE003      |
| B0329 | US | Land Rover  | LR4                | 2010/01-2015/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | LR021936/<br>LR018859              |             |             |
| B0330 | US | Land Rover  | LR4                | 2010/01-2015/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Continental | LR018861                           | T120123002H | T120123002  |
| B0332 | US | Land Rover  | Range Rover        | 2014/01-2016/12 | 433MHz | ● | ● | 4/5 |           | 433Mhz | Continental | LR066378                           |             |             |
| B0333 | EU | Land Rover  | Range Rover        | 2013/01-2015/05 |        | ○ | ● | 4/5 | Copy only | 433Mhz | Continental | LR058023                           | S180052028Z | S180052028  |
| B0334 | US | Land Rover  | Range Rover        | 2010/01-2013/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | LR021936                           |             |             |
| B0335 | EU | Land Rover  | Range Rover        | 2010/01-2012/12 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR021935                           | S180084770Z | S180052022  |
| B0336 | US | Land Rover  | Range Rover        | 2007/01-2009/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | LR018860                           |             |             |
| B0337 | US | Land Rover  | Range Rover        | 2007/01-2009/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Continental | LR018861                           | T120123002H | T120123002  |
| B0338 | US | Land Rover  | Range Rover        | 2006/01-2006/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | LR018860                           |             |             |
| B0339 | US | Land Rover  | Range Rover        | 2006/01-2006/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Continental | LR018861                           | T120123002H | T120123002  |
| B0340 | EU | Land Rover  | Range Rover        | 2005/01-2009/12 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR021935                           | S180084770Z | S180052022  |
| B0341 | EU | Land Rover  | Range Rover        | 2002/03-2003/02 |        | ● | ● | 4/5 | A         | 433Mhz | Huf/Beru    | YDB000061                          | 532207003   | RDE003      |
| B0342 | EU | Land Rover  | Range Rover Evoque | 2015/10-2016/12 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | GX631A159AA                        |             | S180052076A |
| B0343 | EU | Land Rover  | Range Rover Evoque | 2015/01-2015/09 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR066378                           | S180052028C | S180052028  |
| B0344 | US | Land Rover  | Range Rover Evoque | 2014/01-2016/12 | 433MHz | ● | ● | 4/5 |           | 433Mhz | Continental | LR066378                           |             |             |
| B0345 | US | Land Rover  | Range Rover Evoque | 2012/01-2013/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | LR010533                           |             |             |
| B0346 | EU | Land Rover  | Range Rover Evoque | 2011/07-2014/12 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR031712                           | A2C59511308 | T120123002  |
| B0347 | EU | Land Rover  | Range Rover Sport  | 2015/06-2016/12 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | GX631A159AA                        |             | S180052076A |
| B0348 | EU | Land Rover  | Range Rover Sport  | 2015/01-2015/05 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR066378                           | S180052028C | S180052028  |
| B0349 | EU | Land Rover  | Range Rover Sport  | 2014/06-2014/12 |        | ● | ● | 4/5 | A         | 433Mhz | Continental | LR031712                           | A2C59511308 | T120123002  |
| B0350 | US | Land Rover  | Range Rover Sport  | 2014/01-2016/12 | 433MHz | ● | ● | 4/5 |           | 433Mhz | Continental | LR066378                           |             |             |
| B0351 | US | Land Rover  | Range Rover Sport  | 2010/01-2013/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | LR010533                           |             |             |
| B0352 | US | Land Rover  | Range Rover Sport  | 2010/01-2011/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Continental | LR018861                           | T120123002H | T120123002  |
| B0353 | US | Land Rover  | Range Rover Sport  | 2006/01-2009/12 | 315MHz | ● | ● | 4/5 | A/O       | 315Mhz | Continental | LR018860                           |             |             |
| B0354 | US | Land Rover  | Range Rover Sport  | 2006/01-2009/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Continental | LR018861                           | T120123002H | T120123002  |

|       |    |            |                   |                 |        |   |   |     |     |        |             |                                             |             |                                             |
|-------|----|------------|-------------------|-----------------|--------|---|---|-----|-----|--------|-------------|---------------------------------------------|-------------|---------------------------------------------|
| B0355 | EU | Land Rover | Range Rover Vogue | 2015/01-2015/12 |        | ○ | ● | 4/5 | A   | 433Mhz | Continental | LR066378                                    | S180052028C | S180052028                                  |
| B0356 | EU | Land Rover | Range Rover Vogue | 2005/01-2013/12 |        | ● | ● | 4/5 | A   | 433Mhz | Continental | LR021935                                    | S180084770Z | S180052022                                  |
| B0357 | US | Maybach    | Landulet          | 2009/01-2012/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Huf/Beru    | A0055422418                                 | 532107001   | RDE004                                      |
| B0358 | EU | Maybach    | Landulet          | 2008/10-2014/12 |        | ● | ● | 4   | S   | 433Mhz | Huf/Beru    | A0055422318                                 | 532207001   | RDE001                                      |
| B0359 | US | Maybach    | Maybach 57        | 2003/01-2011/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Huf/Beru    | A0055422418                                 | 532107001   | RDE004                                      |
| B0360 | EU | Maybach    | Maybach 57        | 2002/02-2012/12 |        | ● | ● | 4   | S   | 433Mhz | Huf/Beru    | A0055422318                                 | 532207001   | RDE001                                      |
| B0361 | US | Maybach    | Maybach 57 S      | 2006/01-2012/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Huf/Beru    | A0055422418                                 | 532107001   | RDE004                                      |
| B0362 | US | Maybach    | Maybach 62        | 2003/01-2011/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Huf/Beru    | A0055422418                                 | 532107001   | RDE004                                      |
| B0363 | EU | Maybach    | Maybach 62        | 2002/02-2012/12 |        | ● | ● | 4   | S   | 433Mhz | Huf/Beru    | A0055422318                                 | 532207001   | RDE001                                      |
| B0364 | US | Maybach    | Maybach 62 S      | 2003/01-2012/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Huf/Beru    | A0055422418                                 | 532107001   | RDE004                                      |
| B0368 | EU | Mercedes   | A Class           | 2014/04-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100/<br>A0009050030                 |             | A0009054100/<br>A0009050030                 |
| B0369 | EU | Mercedes   | A Class           | 2012/12-2014/03 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009057200                                 |             | A 000 905 7200 Q01                          |
| B0370 | US | Mercedes   | B Class           | 2014/01-2015/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Schrader    | A0045400217/<br>A0009057200                 |             | A000 905 72 00                              |
| B0371 | EU | Mercedes   | B Class           | 2012/12-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100/<br>A0009050030                 |             | A0009054100/<br>A0009050030                 |
| B0372 | EU | Mercedes   | C Class           | 2014/03-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100/<br>A0009050030                 |             | A0009054100/<br>A0009050030                 |
| B0373 | EU | Mercedes   | C Class           | 2008/01-2014/02 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100/<br>A0009050030                 |             | A0009054100/<br>A0009050030                 |
| B0374 | US | Mercedes   | C Class           | 2007/01-2016/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Schrader    | A0045400217/<br>A0035400217                 |             | A 003 540 02 17                             |
| B0375 | EU | Mercedes   | Citan             | 2012/09-2016/06 |        | ● | ● | 4   | A/O | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R    |             | 407001628R-B                                |
| B0376 | US | Mercedes   | CL Class          | 2010/01-2015/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Schrader    | A0045400217/<br>A0035400217                 |             | A 003 540 02 17                             |
| B0377 | EU | Mercedes   | CL Class          | 2009/06-2016/12 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |             | A0009054100Q01                              |
| B0378 | US | Mercedes   | CL Class          | 2007/01-2009/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Continental | A0025407917                                 |             |                                             |
| B0379 | US | Mercedes   | CL Class          | 2007/01-2009/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017/<br>A0045429818                 | S180014730Z | S122228002                                  |
| B0380 | US | Mercedes   | CL Class          | 2000/01-2006/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Huf/Beru    | A0008223406                                 | 532107001   | A0008223406/<br>A0055422418                 |
| B0381 | US | Mercedes   | CL Class          | 2000/01-2006/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | A0008223306                                 | 532207001   | A0008223306/<br>A0055422318                 |
| B0382 | EU | Mercedes   | CL Class          | 1998/01-2006/02 |        | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | A0055422318                                 | 532207001   | RDE001                                      |
| B0383 | EU | Mercedes   | CLA Class         | 2014/06-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009050030                                 |             | A0009050030Q03                              |
| B0384 | US | Mercedes   | CLA Class         | 2014/01-2015/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Schrader    | A0045400217/<br>A0035400217                 |             | A0035400217                                 |
| B0385 | EU | Mercedes   | CLA Class         | 2012/12-2014/05 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009057200                                 |             | A0009057200Q01                              |
| B0386 | EU | Mercedes   | CLC Class         | 2008/06-2011/12 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |             |                                             |
| B0387 | US | Mercedes   | CLK Class         | 2008/01-2009/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Schrader    | A0045400217/<br>A0035400217                 |             | A 003 540 02 17                             |
| B0388 | EU | Mercedes   | CLK Class         | 2007/04-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009050030/<br>A0009054100/<br>A0009057200 |             | A0009050030/<br>A0009054100/<br>A0009057200 |
| B0389 | US | Mercedes   | CLK Class         | 2006/01-2007/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Huf/Beru    | A0008223406/<br>A0055422418                 | 532107001   | RDE004                                      |
| B0390 | US | Mercedes   | CLS Class         | 2012/01-2015/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Schrader    | A0035400217                                 |             | A 003 540 02 17                             |
| B0391 | EU | Mercedes   | CLS Class         | 2009/07-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |             |                                             |
| B0392 | US | Mercedes   | CLS Class         | 2006/01-2011/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Continental | A0025407917                                 |             |                                             |
| B0393 | US | Mercedes   | CLS Class         | 2006/01-2011/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017                                 | S180014730Z | S122228002                                  |
| B0394 | EU | Mercedes   | CLS Class (HUF)   | 2004/10-2005/06 |        | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | A0055422318                                 | 532207001   | RDE001                                      |
| B0395 | EU | Mercedes   | CLS Class (VDO)   | 2005/01-2009/06 |        | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017/<br>A0045429818                 | S180014730Z | S122228002                                  |
| B0396 | EU | Mercedes   | E Class           | 2014/06-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |             | A0009054100                                 |

|       |    |          |           |                 |        |   |   |   |   |        |             |                                             |             |                                 |
|-------|----|----------|-----------|-----------------|--------|---|---|---|---|--------|-------------|---------------------------------------------|-------------|---------------------------------|
| B0397 | US | Mercedes | E Class   | 2010/06-2016/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Schrader    | A0035400217                                 |             | A 003 540 02 17                 |
| B0398 | EU | Mercedes | E Class   | 2009/07-2014/05 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009054100                                 |             | A0009054100                     |
| B0399 | US | Mercedes | E Class   | 2006/01-2010/05 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | A0025407917                                 |             |                                 |
| B0400 | US | Mercedes | E Class   | 2006/01-2010/05 | 433MHz | ● | ● | 4 | A | 433Mhz | Continental | A0025408017/<br>A0045429818                 | S180014730Z | S122228002                      |
| B0401 | EU | Mercedes | E Class   | 2005/06-2009/06 |        | ● | ● | 4 | A | 433Mhz | Continental | A0025408017                                 | S180014730Z | S122228002                      |
| B0402 | EU | Mercedes | E Class   | 2002/03-2005/05 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | A0055422318                                 | 532207001   | RDE001                          |
| B0403 | US | Mercedes | E Class   | 2000/01-2005/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Huf/Beru    | A0008223406                                 | 532107001   | RDE004                          |
| B0404 | US | Mercedes | E Class   | 2000/01-2005/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | A0008223306                                 | 532207001   | RDE001                          |
| B0406 | EU | Mercedes | G Class   | 2007/04-2016/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009054100                                 |             | A0009054100                     |
| B0407 | US | Mercedes | G Class   | 2007/01-2016/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Schrader    | A0035400217                                 |             | A 003 540 02 17                 |
| B0408 | EU | Mercedes | GL Class  | 2013/01-2016/06 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009050030/<br>A0009054100/<br>A0009057200 |             | A 000 905 00 30<br>002          |
| B0409 | US | Mercedes | GL Class  | 2010/01-2015/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Schrader    | A0045400217/<br>A0035400217                 |             | 004 540 02 17/<br>003 540 02 17 |
| B0410 | EU | Mercedes | GL Class  | 2009/06-2012/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009054100                                 |             |                                 |
| B0411 | US | Mercedes | GL Class  | 2007/01-2009/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | A0025407917                                 |             |                                 |
| B0412 | US | Mercedes | GL Class  | 2007/01-2009/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Continental | A0025408017/<br>A0045429818                 | S180014730Z | S122228002                      |
| B0413 | EU | Mercedes | GL Class  | 2006/10-2009/05 |        | ● | ● | 4 | A | 433Mhz | Continental | A0025408017                                 | S180014730Z | S122228002                      |
| B0414 | EU | Mercedes | GLA Class | 2014/06-2016/06 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009050030                                 |             |                                 |
| B0415 | US | Mercedes | GLA Class | 2014/01-2015/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Schrader    | A0045400217                                 |             |                                 |
| B0416 | US | Mercedes | GLC Class | 2016/01-2016/12 | 433Mhz | ● | ● | 4 |   | 433Mhz | Schrader    | A0009050030/<br>A0045400217                 |             |                                 |
| B0417 | EU | Mercedes | GLC Class | 2015/01-2016/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009050030                                 |             |                                 |
| B0418 | US | Mercedes | GLE Class | 2016/01-2016/12 | 433Mhz | ● | ● | 4 | A | 433Mhz | Schrader    | A0009050030/<br>A0045400217                 |             | A 000 905 00 30                 |
| B0419 | EU | Mercedes | GLE Class | 2015/09-2016/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009050030/<br>A0009054100/<br>A0009057200 |             | A 000 905 00 30                 |
| B0420 | US | Mercedes | GLK Class | 2010/01-2015/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Schrader    | A0045400217/<br>A0035400217                 |             | 004 540 02 17/<br>003 540 02 17 |
| B0421 | EU | Mercedes | GLK Class | 2008/01-2015/09 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009054100                                 |             |                                 |
| B0422 | US | Mercedes | GLS Class | 2016/01-2016/12 | 433Mhz | ● | ● | 4 |   | 433Mhz | Schrader    | A0009050030/<br>A0045400217                 |             |                                 |
| B0423 | US | Mercedes | GT-S      | 2016/01-2016/12 | 433Mhz | ● | ● | 4 | A | 433Mhz | Schrader    | A0009050030/<br>A0045400217                 |             | A 000 905 00 30                 |
| B0424 | EU | Mercedes | GT-S AMG  | 2015/03-2016/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009054100/<br>A0009050030                 |             | A0009054100/<br>A0009050030     |
| B0425 | EU | Mercedes | M Class   | 2011/06-2014/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009054100                                 |             |                                 |
| B0426 | EU | Mercedes | M Class   | 2005/01-2011/05 |        | ● | ● | 4 | A | 433Mhz | Continental | A0025408017                                 | S180014730Z | S122228002                      |
| B0427 | EU | Mercedes | ML Class  | 2011/06-2016/06 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009054100                                 |             |                                 |
| B0428 | US | Mercedes | ML Class  | 2010/06-2015/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Schrader    | A0045400217/<br>A0035400217                 |             | A 003 540 02 17                 |
| B0429 | EU | Mercedes | ML Class  | 2009/08-2011/05 |        | ● | ● | 4 | S | 433Mhz | Schrader    | A0009054100/<br>A0009057200/<br>A0009050030 |             | A 000 905 41 00                 |
| B0430 | US | Mercedes | ML Class  | 2006/01-2010/05 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | A0025407917                                 |             |                                 |
| B0431 | US | Mercedes | ML Class  | 2006/01-2010/05 | 433MHz | ● | ● | 4 | A | 433Mhz | Continental | A0025408017/<br>A0045429818                 | S180014730Z | S122228002                      |
| B0432 | EU | Mercedes | ML Class  | 2005/07-2009/06 |        | ● | ● | 4 | A | 433Mhz | Continental | A0025408017                                 | S180014730Z | S122228002                      |
| B0433 | US | Mercedes | R Class   | 2010/01-2015/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Schrader    | A0035400217                                 |             | A 003 540 02 17                 |
| B0434 | EU | Mercedes | R Class   | 2009/08-2016/06 |        | ● | ● | 4 | A | 433Mhz | Schrader    | A0009054100                                 |             |                                 |
| B0435 | US | Mercedes | R Class   | 2006/01-2009/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | A0025407917                                 |             |                                 |
| B0436 | US | Mercedes | R Class   | 2006/01-2009/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Continental | A0025408017/<br>A0045429818                 | S180014730Z | S122228002                      |

|       |    |          |                |                 |        |   |   |     |     |        |             |                                             |                       |                                             |
|-------|----|----------|----------------|-----------------|--------|---|---|-----|-----|--------|-------------|---------------------------------------------|-----------------------|---------------------------------------------|
| B0437 | EU | Mercedes | R Class        | 2006/01-2009/07 |        | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017                                 | S180014730Z           | S122228002                                  |
| B0438 | EU | Mercedes | S Class        | 2013/07-2016/06 |        | ● | ● | 4   | S   | 433Mhz | Schrader    | A0009054100/<br>A0009057200/<br>A0009050030 | 90518279/<br>90518384 | A0025409017/<br>A0035400217/<br>A0009054100 |
| B0439 | US | Mercedes | S Class        | 2010/01-2015/12 | 433MHz | ● | ● | 4   | A/O | 433Mhz | Schrader    | A0035400217/<br>A0009057200/<br>A0045400217 |                       | A 003 540 02 17                             |
| B0440 | EU | Mercedes | S Class        | 2009/06-2013/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |                       |                                             |
| B0441 | US | Mercedes | S Class        | 2007/01-2009/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Continental | A0025407917                                 |                       |                                             |
| B0442 | US | Mercedes | S Class        | 2007/01-2009/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017/<br>A0045429818                 | S180014730Z           | S122228002                                  |
| B0443 | EU | Mercedes | S Class        | 2005/10-2009/05 |        | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017                                 | S180014730Z           | S122228002                                  |
| B0444 | US | Mercedes | S Class        | 2000/01-2006/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Huf/Beru    | A0008223406/<br>A0055422418                 | 532107001             | RDE004                                      |
| B0445 | US | Mercedes | S Class        | 2000/01-2006/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Huf/Beru    | A0008223306/<br>A0055422318                 | 532207001             | RDE001                                      |
| B0446 | EU | Mercedes | S Class        | 1999/07-2005/09 |        | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | A0055422318                                 | 532207001             | RDE001                                      |
| B0449 | US | Mercedes | SL Class       | 2012/07-2016/12 | 433MHz | ● | ● | 4   | A/O | 433Mhz | Schrader    | A0035400217                                 |                       | A 003 540 02 17                             |
| B0450 | EU | Mercedes | SL Class       | 2012/01-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |                       |                                             |
| B0451 | US | Mercedes | SL Class       | 2006/01-2012/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Continental | A0025407917                                 |                       |                                             |
| B0452 | US | Mercedes | SL Class       | 2006/01-2012/06 | 433MHz | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017/<br>A0045429818                 | S180014730Z           | S122228002                                  |
| B0453 | EU | Mercedes | SL Class       | 2005/06-2011/12 |        | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017                                 | S180014730Z           | S122228002                                  |
| B0454 | US | Mercedes | SL Class       | 2000/01-2005/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Huf/Beru    | A0008223406/<br>A0055422418                 | 532107001             | RDE004                                      |
| B0455 | US | Mercedes | SL Class       | 2000/01-2005/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | A0008223306/<br>A0055422318                 | 532207001             | RDE001                                      |
| B0456 | EU | Mercedes | SL Roadster    | 2001/08-2005/06 |        | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | A0055422318                                 | 532207001             | RDE001                                      |
| B0457 | US | Mercedes | SLK Class      | 2008/01-2015/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Schrader    | A0045400217/<br>A0035400217                 |                       | A 003 540 02 17                             |
| B0458 | EU | Mercedes | SLK Class      | 2007/04-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |                       |                                             |
| B0459 | US | Mercedes | SLR Class      | 2008/01-2009/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Continental | A0025407917                                 |                       |                                             |
| B0460 | US | Mercedes | SLR Class      | 2008/01-2009/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017                                 | S180014730Z           | S122228002                                  |
| B0461 | EU | Mercedes | SLR Class      | 2004/04-2015/12 |        | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | A0055422318                                 | 532207001             | RDE001                                      |
| B0462 | US | Mercedes | SLR Class      | 2001/01-2007/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Huf/Beru    | A0008223406                                 | 532107001             | RDE004                                      |
| B0463 | US | Mercedes | SLR Class      | 2001/01-2007/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | A0008223306                                 | 532207001             | RDE001                                      |
| B0464 | US | Mercedes | SLR McLaren    | 2005/01-2006/12 | 315MHz | ● | ● | 4   | A   | 315Mhz | Huf/Beru    | A0055422418                                 | 532107001             | RDE004                                      |
| B0465 | US | Mercedes | SLS Class      | 2011/01-2013/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |                       |                                             |
| B0466 | EU | Mercedes | SLS Class      | 2010/01-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |                       |                                             |
| B0467 | US | Mercedes | Sprinter       | 2014/01-2016/12 | 433MHz | ● | ● | 4   | S   | 433Mhz | Schrader    | A0009057200                                 |                       | A 000 905 7200 Q01                          |
| B0468 | EU | Mercedes | Sprinter       | 2011/06-2016/06 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009050030                                 |                       |                                             |
| B0470 | EU | Mercedes | Sprinter Combi | 2011/11-2015/12 |        | ● | ● | 4   | A   | 433Mhz | Schrader    | A0009054100                                 |                       |                                             |
| B0471 | EU | Mercedes | Sprinter Combi | 2006/01-2011/10 |        | ● | ● | 4   | A   | 433Mhz | Continental | A0025408017                                 | S180014730Z           | S122228002                                  |
| B0472 | EU | Mercedes | V Class W447   | 2014/02-2016/12 |        | ● | ● | 4   | S   | 433Mhz | Schrader    | A4479050500                                 |                       | A4479050500                                 |
| B0473 | EU | Mercedes | Viano W639     | 2014/06-2015/12 |        | ● | ● | 4   | S   | 433Mhz | Schrader    | A4479050500                                 |                       | A4479050500                                 |
| B0474 | EU | Mercedes | Viano W639     | 2011/01-2014/05 |        | ● | ● | 4   | A   | 433Mhz | Continental | A0025409517                                 |                       | S122228004                                  |
| B0475 | EU | Mercedes | Vito W639      | 2006/01-2014/06 |        | ● | ● | 4   | A   | 433Mhz | Continental | A0025409517                                 |                       | S122228004                                  |
| B0476 | EU | Mercedes | Vito W640      | 2014/07-2015/12 |        | ● | ● | 4   | S   | 433Mhz | Schrader    | A4479050500                                 |                       | A447 905 0500                               |
| B0477 | EU | Mini     | Cabrio         | 2014/07-2015/12 |        | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | 36106798872                                 | 532207017             | RDE017                                      |
| B0478 | EU | Mini     | Clubman        | 2013/11-2015/12 |        | ○ | ● | 4   |     | 433Mhz | Continental | 36106856209                                 |                       |                                             |
| B0479 | EU | Mini     | Clubman        | 2009/09-2015/12 |        | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | 36106798872                                 | 532207017             | RDE017                                      |
| B0480 | EU | Mini     | Clubman        | 2007/08-2009/08 |        | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | 36236781847                                 | 532207008             | RDE008                                      |
| B0481 | EU | Mini     | Clubvan        | 2012/07-2015/12 |        | ● | ● | 4   |     | 433Mhz | Huf/Beru    | 36106798872                                 | 532207017             | RDE017                                      |
| B0482 | US | Mini     | Cooper         | 2014/03-2016/12 | 433MHz | ● | ● | 4   | A   | 433Mhz | Continental | 36106856209                                 | S180052056Z           | S180052056                                  |
| B0483 | EU | Mini     | Cooper         | 2014/03-2014/12 |        | ● | ● | 4   | A   | 433Mhz | Continental | 36106856209                                 | S180052056Z           | S180052056                                  |
| B0484 | US | Mini     | Cooper         | 2010/01-2014/02 | 433MHz | ● | ● | 4   | A   | 433Mhz | Huf/Beru    | 36106790054                                 | 532207012             | RDE012                                      |

|       |    |         |                 |                 |        |   |   |   |   |        |             |                           |             |                           |
|-------|----|---------|-----------------|-----------------|--------|---|---|---|---|--------|-------------|---------------------------|-------------|---------------------------|
| B0485 | EU | Mini    | Cooper          | 2007/09-2009/09 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847               | 532207008   | RDE008                    |
| B0486 | US | Mini    | Cooper          | 2007/01-2009/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36236781847               | 532207008   | RDE008                    |
| B0487 | EU | Mini    | Cooper S Cabrio | 2014/07-2016/06 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106798872               | 532207017   | RDE017                    |
| B0488 | US | Mini    | Countryman      | 2015/01-2015/12 | 433Mhz | ○ | ● | 4 |   | 433Mhz | Huf/Beru    | 36106798872               |             |                           |
| B0489 | EU | Mini    | Countryman      | 2014/07-2016/06 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106798872               | 532207017   | RDE017                    |
| B0490 | EU | Mini    | Coupe           | 2011/07-2015/08 |        | ● | ● | 4 |   | 433Mhz | Huf/Beru    | 36106798872               | 532207017   | RDE017                    |
| B0491 | EU | Mini    | Hatchback       | 2013/11-2015/12 |        | ○ | ● | 4 |   | 433Mhz | Continental | 36106856209               |             |                           |
| B0492 | EU | Mini    | Mini            | 2014/03-2016/06 |        | ● | ● | 4 | A | 433Mhz | Continental | 36106856209               | S180052056F | S180052056                |
| B0493 | EU | Mini    | Mini            | 2010/01-2013/12 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106790054               | 532207012   | RDE012                    |
| B0494 | US | Mini    | Paceman         | 2015/01-2015/12 | 433Mhz | ○ | ● | 4 |   | 433Mhz | Huf/Beru    | 36106798872               |             |                           |
| B0495 | EU | Mini    | Paceman         | 2012/11-2016/06 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106798872               | 532207017   | RDE017                    |
| B0496 | US | Mini    | Roadster        | 2014/03-2015/12 | 433Mhz | ○ | ● | 4 |   | 433Mhz | Huf/Beru    | 36106798872               |             |                           |
| B0497 | EU | Mini    | Roadster        | 2011/12-2015/12 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106798872               | 532207017   | RDE017                    |
| B0498 | EU | Mini    | SAV Studie      | 2014/07-2014/12 |        | ● | ● | 4 | A | 433Mhz | Huf/Beru    | 36106798872               | 532207017   | RDE017                    |
| B0499 | EU | Peugeot | 1007            | 2005/01-2009/12 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 543093/<br>5430T4         | S180014805Z | S120120001                |
| B0501 | EU | Peugeot | 108             | 2014/08-2015/12 |        | ○ | ● | 4 | S | 433Mhz | Pacific     | 4260742020                | PMV-C210    | PMV-C210                  |
| B0502 | EU | Peugeot | 2008            | 2014/05-2015/12 |        | ○ | ● | 4 | S | 433Mhz | Schrader    | 9802003680/<br>9811536380 |             | 9802003680/<br>9811536380 |
| B0503 | EU | Peugeot | 2008            | 2013/02-2014/04 |        | ○ | ● | 4 |   | 433Mhz | Schrader    | 9802003680/<br>9811536380 |             | 9802003680/<br>9811536380 |
| B0504 | EU | Peugeot | 207             | 2013/10-2016/06 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 9802003680/<br>9811536380 |             | 9802003680/<br>9811536380 |
| B0505 | EU | Peugeot | 207             | 2006/01-2013/09 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 543093/<br>5430T4         | S180014805Z | S120120001                |
| B0506 | EU | Peugeot | 208             | 2015/01-2015/12 |        | ○ | ● | 4 | S | 433Mhz | Schrader    | 9802003680/<br>9811536380 |             | 9802003680/<br>9811536380 |
| B0507 | EU | Peugeot | 208             | 2014/01-2014/12 |        | ● | ● | 4 | S | 433Mhz | Schrader    | 9802003680/<br>9811536380 |             | 9802003680/<br>9811536380 |
| B0508 | EU | Peugeot | 208             | 2012/01-2013/12 |        | ○ | ● | 4 |   | 433Mhz | Schrader    | 9802003680/<br>9811536380 |             | 9802003680/<br>9811536380 |
| B0509 | EU | Peugeot | 3008            | 2013/10-2016/06 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 9802003680/<br>9811536380 |             | 9802003680/<br>9811536380 |
| B0510 | EU | Peugeot | 3008            | 2008/11-2013/09 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 5430W0                    | 90818333    | 9673860880                |
| B0511 | EU | Peugeot | 3008 (LCV)      | 2008/01-2015/12 |        | ● | ● | 4 |   | 433Mhz | Schrader    | 5430W0                    | 90818333    | 9673860880                |
| B0512 | EU | Peugeot | 301             | 2012/10-2015/12 |        | ○ | ● | 4 | S | 433Mhz | Schrader    | 9802003680                |             | 9802003680                |
| B0513 | EU | Peugeot | 307             | 2007/03-2007/12 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 5430W0                    | 90818333    | 9673860880                |
| B0514 | EU | Peugeot | 307             | 2003/12-2007/02 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 543093/<br>5430T4         | S180014805Z | S120120001                |
| B0515 | EU | Peugeot | 308             | 2013/09-2016/06 |        | ○ | ● | 4 | S | 433Mhz | Schrader    | 9802003680                |             | 9802003680                |
| B0516 | EU | Peugeot | 308             | 2007/01-2013/08 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 5430W0                    | 90818333    | 9673860880                |
| B0519 | EU | Peugeot | 407             | 2004/01-2011/08 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 543093/<br>5430T4         | S180014805Z | S120120001                |
| B0520 | EU | Peugeot | 408             | 2014/06-2016/06 |        | ● | ● | 4 | S | 433Mhz | Schrader    | 9802003680                |             | 9802003680                |
| B0521 | EU | Peugeot | 5008            | 2013/10-2016/06 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 9802003680                |             | 9802003680                |
| B0522 | EU | Peugeot | 5008            | 2009/08-2013/09 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 5430W0                    | 90818333    | 9673860880                |
| B0523 | EU | Peugeot | 5008 (LCV)      | 2009/09-2016/06 |        | ● | ● | 4 |   | 433Mhz | Schrader    | 9802003680                |             | 9802003680                |
| B0524 | EU | Peugeot | 508             | 2013/10-2016/06 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 9811536380/<br>9802003680 |             | 9811536380                |
| B0525 | EU | Peugeot | 508             | 2011/01-2013/09 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 5430T4                    | S180014805Z | S120120001                |
| B0526 | EU | Peugeot | 508 (LCV)       | 2010/09-2016/06 |        | ○ | ● | 4 |   | 433Mhz | Schrader    | 9811536380                |             | 9811536380                |
| B0527 | EU | Peugeot | 607             | 2004/10-2010/10 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 543093/<br>5430T4         | S180014805Z | S120120001                |
| B0528 | EU | Peugeot | 607             | 2000/03-2004/09 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 543002                    |             | 543002                    |
| B0529 | EU | Peugeot | 807             | 2005/10-2015/12 |        | ● | ● | 4 | 0 | 433Mhz | Continental | 5430T4                    | S180014805Z | S120120001                |
| B0530 | EU | Peugeot | 807             | 2002/07-2005/09 |        | ● | ● | 4 | 0 | 433Mhz | Schrader    | 543002                    | 9634866180  | 9634866180                |

|       |    |         |                 |                 |        |   |   |   |           |        |             |                             |             |            |
|-------|----|---------|-----------------|-----------------|--------|---|---|---|-----------|--------|-------------|-----------------------------|-------------|------------|
| B0531 | EU | Peugeot | Boxer Combi     | 2014/01-2016/06 |        | ○ | ● | 4 | A         | 433Mhz | Schrader    | 9802003680                  |             | 9802003680 |
| B0533 | EU | Peugeot | Expert          | 2011/01-2014/05 |        | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 9677130580                  | 70503487    | 9677130580 |
| B0534 | EU | Peugeot | ION             | 2014/01-2016/12 |        | ○ | ● | 4 | S         | 433Mhz | Continental | 1612477080                  | S180052094Z | S180052094 |
| B0536 | EU | Peugeot | Partner         | 2008/01-2014/05 |        | ● | ● | 4 | O         | 433Mhz | Schrader    | 5430W0                      | 90818333    | 9673860880 |
| B0537 | EU | Peugeot | RCZ             | 2013/10-2016/12 |        | ● | ● | 4 | O         | 433Mhz | Schrader    | 9802003680                  |             | 9802003680 |
| B0538 | EU | Peugeot | RCZ             | 2010/02-2013/09 |        | ● | ● | 4 | O         | 433Mhz | Schrader    | 5430W0                      | 90818333    | 9673860880 |
| B0539 | US | Porsche | 911             | 2012/02-2015/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602120                 | 532207011   | RDE011     |
| B0540 | US | Porsche | 911             | 2005/02-2008/04 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 95560602301                 |             |            |
| B0541 | US | Porsche | 911             | 2008/05-2012/10 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602120                 | 532207011   | RDE011     |
| B0542 | US | Porsche | 911             | 2005/02-2008/04 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602101                 | 532207001   | RDE001     |
| B0545 | US | Porsche | 911 Carrera     | 2009/01-2011/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 99760602321                 |             |            |
| B0548 | US | Porsche | 911 Carrera 4S  | 2012/01-2015/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 7PP907275G                  |             |            |
| B0557 | US | Porsche | 911 Turbo       | 2007/01-2009/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602101                 | 532207001   | RDE001     |
| B0560 | EU | Porsche | 911(991)        | 2015/09-2016/12 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru    | 5Q0907275                   | 532207018   | RDE018     |
| B0561 | EU | Porsche | 911(991)        | 2011/12-2015/08 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 7PP907275F                  | 532207011   | RDE011     |
| B0564 | EU | Porsche | 911(997)        | 2008/04-2011/11 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602120                 | 532207011   | RDE011     |
| B0565 | EU | Porsche | 911(997)        | 2004/07-2008/03 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602101                 | 532207001   | RDE001     |
| B0566 | EU | Porsche | 918 Spyder      | 2013/01-2015/12 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 7PP907275F                  | 532207011   | RDE011     |
| B0567 | US | Porsche | 918 Spyder      | 2013/01-2015/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 7PP907275F                  | 532207011   | RDE011     |
| B0568 | EU | Porsche | Boxster         | 2013/09-2016/06 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 7PP907275F                  | 532207011   | RDE011     |
| B0569 | US | Porsche | Boxster         | 2012/01-2016/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 95836166100                 | 532207011   | RDE011     |
| B0570 | US | Porsche | Boxster         | 2009/01-2012/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 99760602321                 |             |            |
| B0571 | US | Porsche | Boxster         | 2009/01-2011/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602120                 | 532207011   | RDE011     |
| B0572 | EU | Porsche | Boxster         | 2008/11-2014/01 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602120                 | 532207011   | RDE011     |
| B0573 | US | Porsche | Boxster         | 2005/02-2008/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602101                 | 532207001   | RDE001     |
| B0574 | EU | Porsche | Boxster         | 2005/02-2008/10 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602101                 | 532207001   | RDE001     |
| B0575 | US | Porsche | Boxster         | 2005/02-2008/10 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 95560602301                 |             |            |
| B0576 | US | Porsche | Boxster Base    | 2013/01-2014/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 7PP907275G                  |             |            |
| B0577 | US | Porsche | Boxster S       | 2013/01-2014/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 7PP907275G                  |             |            |
| B0578 | US | Porsche | Carrera GT      | 2003/09-2011/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602101                 | 532207001   | RDE001     |
| B0579 | EU | Porsche | Carrera GT      | 2003/09-2006/12 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602101                 | 532207001   | RDE001     |
| B0580 | US | Porsche | Cayenne         | 2015/01-2016/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 5Q0907275                   | 532207018   | RDE018     |
| B0581 | EU | Porsche | Cayenne         | 2014/05-2016/06 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 5Q0907275                   | 532207018   | RDE018     |
| B0582 | US | Porsche | Cayenne         | 2013/01-2014/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 95836166100                 | 532207011   | RDE011     |
| B0583 | EU | Porsche | Cayenne         | 2011/01-2014/04 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 95836166100                 | 532207011   | RDE011     |
| B0584 | US | Porsche | Cayenne         | 2011/01-2012/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 7P0907275A                  |             |            |
| B0585 | US | Porsche | Cayenne         | 2011/01-2012/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 95836166100                 | 532207011   | RDE011     |
| B0586 | EU | Porsche | Cayenne         | 2007/01-2010/12 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 95560602100                 | 532207011   | RDE011     |
| B0587 | US | Porsche | Cayenne         | 2007/01-2010/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 95560602301                 |             |            |
| B0588 | US | Porsche | Cayenne         | 2007/01-2010/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 95560602100                 | 532207011   | RDE011     |
| B0589 | EU | Porsche | Cayenne         | 2002/01-2006/12 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 95536166100                 | 532207005   | RDE005     |
| B0590 | US | Porsche | Cayenne         | 2002/01-2006/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602101                 | 532207001   | RDE001     |
| B0591 | US | Porsche | Cayenne Base    | 2008/01-2009/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 7PP907275G                  |             |            |
| B0592 | US | Porsche | Cayenne M/T GTS | 2008/01-2009/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 7PP907275G                  |             |            |
| B0593 | US | Porsche | Cayenne S       | 2008/01-2009/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 7PP907275G                  |             |            |
| B0594 | US | Porsche | Cayenne Turbo   | 2008/01-2009/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 7PP907275G                  |             |            |
| B0595 | US | Porsche | Cayenne Turbo S | 2009/01-2009/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 7PP907275G                  |             |            |
| B0596 | US | Porsche | Cayman          | 2013/04-2016/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 95836166100                 | 532207011   | RDE011     |
| B0597 | US | Porsche | Cayman          | 2009/01-2014/03 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602120                 | 532207011   | RDE011     |
| B0598 | US | Porsche | Cayman          | 2009/01-2012/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru    | 99760602321                 |             |            |
| B0599 | US | Porsche | Cayman          | 2005/01-2008/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 99760602101/<br>99760602100 | 532207001   | RDE001     |
| B0600 | EU | Porsche | Cayman 981      | 2013/04-2015/12 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 7PP907275F                  | 532207011   | RDE011     |
| B0601 | EU | Porsche | Cayman 987      | 2009/01-2015/12 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru    | 95836166100                 | 532207011   | RDE011     |

|       |    |             |                   |                 |        |   |   |   |           |        |          |                                          |           |                             |
|-------|----|-------------|-------------------|-----------------|--------|---|---|---|-----------|--------|----------|------------------------------------------|-----------|-----------------------------|
| B0602 | EU | Porsche     | Cayman 987        | 2005/01-2008/12 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 99760602101                              | 532207001 | RDE001                      |
| B0603 | US | Porsche     | Cayman Base       | 2014/01-2016/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0604 | US | Porsche     | Cayman GTS        | 2015/01-2016/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0605 | EU | Porsche     | Cayman GTS        | 2014/05-2016/06 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0606 | US | Porsche     | Cayman S          | 2014/01-2016/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0607 | EU | Porsche     | GT3               | 2010/01-2016/06 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 7PP907275F                               | 532207011 | RDE011                      |
| B0608 | US | Porsche     | GT3               | 2010/01-2014/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 99760602120                              | 532207011 | RDE011                      |
| B0609 | US | Porsche     | GT3               | 2010/01-2014/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 99760602120                              | 532207011 | RDE011                      |
| B0610 | US | Porsche     | GT3               | 2007/03-2009/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 99760602100                              | 532207001 | RDE001                      |
| B0611 | EU | Porsche     | GT3               | 2006/03-2009/12 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 99760602100                              | 532207001 | RDE001                      |
| B0612 | EU | Porsche     | Macan             | 2014/01-2016/06 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0613 | US | Porsche     | Macan             | 2014/01-2015/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0614 | US | Porsche     | Macan             | 2014/01-2015/12 | 315MHz | ● | ● | 4 | A         | 315MHz | Huf/Beru | 5Q0907275A                               |           |                             |
| B0615 | US | Porsche     | Panamera          | 2014/01-2016/12 | 433MHz | ● | ● | 4 |           | 433Mhz | Huf/Beru | 5Q0907275                                |           | RDE018                      |
| B0616 | US | Porsche     | Panamera          | 2014/01-2015/12 | 315MHz | ● | ● | 4 | A         | 315MHz | Huf/Beru | 5Q0907275A                               |           |                             |
| B0617 | EU | Porsche     | Panamera          | 2013/07-2015/12 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0618 | US | Porsche     | Panamera          | 2010/01-2013/12 | 433MHz | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 99760602120                              | 532207011 | RDE011                      |
| B0619 | US | Porsche     | Panamera          | 2010/01-2012/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 99760602321                              |           |                             |
| B0620 | EU | Porsche     | Panamera          | 2009/01-2013/06 |        | ● | ● | 4 | A         | 433Mhz | Huf/Beru | 99760602120                              | 532207011 | RDE011                      |
| B0621 | US | Porsche     | Panamera 4        | 2011/01-2013/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0622 | US | Porsche     | Panamera 4S       | 2010/01-2013/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0623 | US | Porsche     | Panamera Base     | 2011/01-2013/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0624 | US | Porsche     | Panamera GTS      | 2013/01-2013/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0625 | US | Porsche     | Panamera S        | 2010/01-2013/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0626 | US | Porsche     | Panamera S Hybrid | 2012/01-2013/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0627 | US | Porsche     | Panamera Turbo    | 2010/01-2013/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0628 | US | Porsche     | Panamera Turbo S  | 2012/01-2013/12 | 315MHz | ● | ● | 4 | A         | 315Mhz | Huf/Beru | 7PP907275G                               |           |                             |
| B0629 | EU | Rolls Royce | Cabrio            | 2009/06-2011/12 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 36236798726                              | 532207008 | RDE008                      |
| B0631 | US | Rolls Royce | Ghost             | 2012/01-2012/12 | 433MHz | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 36106790054                              | 532207012 | RDE012                      |
| B0632 | EU | Rolls Royce | Ghost             | 2010/01-2016/06 |        | ○ | ● | 4 |           | 433Mhz | Huf/Beru | 36106790054                              | 532207012 | RDE012                      |
| B0634 | EU | Rolls Royce | Phantom           | 2012/01-2016/06 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 36106790054                              | 532207012 | RDE012                      |
| B0635 | US | Rolls Royce | Phantom           | 2012/01-2014/12 | 433MHz | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 36106790054                              | 532207012 | RDE012                      |
| B0636 | EU | Rolls Royce | Phantom           | 2007/08-2011/12 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 36236781847                              | 532207008 | RDE008                      |
| B0637 | US | Rolls Royce | Phantom           | 2007/01-2011/12 | 433MHz | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 36236781847                              | 532207008 | RDE008                      |
| B0638 | EU | Rolls Royce | Wraith            | 2013/08-2015/12 |        | ○ | ● | 4 |           | 433Mhz | Huf/Beru | 36106790054                              | 532207012 | RDE012                      |
| B0639 | EU | Skoda       | Citigo            | 2014/05-2016/06 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0640 | EU | Skoda       | Citigo            | 2011/01-2014/04 |        | ○ | ● | 4 |           | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0641 | EU | Skoda       | Fabia             | 2015/01-2016/06 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0642 | EU | Skoda       | Fabia             | 2013/10-2014/12 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0643 | EU | Skoda       | Octavia           | 2015/01-2016/06 |        | ○ | ● | 4 | S         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0644 | EU | Skoda       | Octavia           | 2012/10-2014/12 |        | ○ | ● | 4 | S         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0645 | EU | Skoda       | Rapid             | 2015/05-2016/06 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0646 | EU | Skoda       | Rapid             | 2012/05-2015/04 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0647 | EU | Skoda       | Roomster          | 2006/01-2016/06 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0648 | EU | Skoda       | Superb            | 2015/05-2015/12 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0649 | EU | Skoda       | Superb            | 2008/03-2015/04 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0650 | EU | Skoda       | Yeti              | 2009/06-2016/06 |        | ○ | ● | 4 | A         | 433Mhz | Huf/Beru | 5Q0907275                                | 532207018 | RDE018                      |
| B0651 | EU | Smart       | Forfour           | 2014/07-2016/06 |        | ○ | ● | 4 | Copy only | 433Mhz | Schrader | 407001628R/<br>407009322R/<br>407009987R |           | 407001628R<br>RDE024/RDE026 |
| B0652 | EU | Smart       | Fortwo            | 2014/10-2016/06 |        | ○ | ● | 4 | Copy only | 433Mhz | Schrader | 407001628R/<br>407009322R/<br>407009987R |           | 407001628R                  |

|       |    |            |                     |                 |        |   |   |     |           |        |             |                                             |             |                                             |
|-------|----|------------|---------------------|-----------------|--------|---|---|-----|-----------|--------|-------------|---------------------------------------------|-------------|---------------------------------------------|
| B0653 | EU | Smart      | Fortwo              | 2014/03-2016/06 |        | ○ | ● | 4   | Copy only | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R    |             | 407001628R                                  |
| B0654 | US | Smart      | Fortwo              | 2009/01-2015/12 | 433MHz | ○ | ● | 4   | A         | 433Mhz | Schrader    | A0035400217/<br>A0009057200                 |             |                                             |
| B0655 | EU | Smart      | Fortwo              | 2007/01-2014/02 |        | ○ | ● | 4   | A         | 433Mhz | Schrader    | A0009054100                                 | 90518384    | A0025409017/<br>A0035400217/<br>A0009054100 |
| B0656 | US | Smart      | Fortwo (SCH)        | 2008/01-2008/12 | 433MHz | ○ | ● | 4   | A         | 433Mhz | Schrader    | A0035400217                                 |             | A 003 540 02 17                             |
| B0658 | US | Volkswagen | Beetle              | 2007/01-2011/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0659 | EU | Volkswagen | Caravelle           | 2012/01-2015/12 |        | ● | ● | 4   |           | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0660 | US | Volkswagen | CC                  | 2012/01-2016/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Huf/Beru    | 3AA907275                                   | 532207013   | RDE013                                      |
| B0661 | EU | Volkswagen | CC                  | 2012/01-2016/06 |        | ● | ● | 4   | S         | 433Mhz | Huf/Beru    | 3AA907275                                   | 532207013   | RDE013                                      |
| B0662 | US | Volkswagen | CC                  | 2009/01-2011/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0663 | EU | Volkswagen | Crafter             | 2006/04-2016/06 |        | ● | ● | 4   | A         | 433Mhz | Schrader    | A0009054100/<br>A0009057200/<br>A0009050030 |             | A0025409017/<br>A0035400217/<br>A0009054100 |
| B0664 | US | Volkswagen | EOS                 | 2007/01-2016/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0665 | EU | Volkswagen | EOS                 | 2006/02-2015/12 |        | ● | ● | 4   | A         | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0666 | US | Volkswagen | GLI                 | 2008/01-2011/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0667 | US | Volkswagen | Golf                | 2010/01-2012/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0668 | EU | Volkswagen | Golf                | 2009/01-2015/12 |        | ● | ● | 4   | S         | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0669 | US | Volkswagen | GTI                 | 2006/01-2012/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0670 | US | Volkswagen | GTI (0-ring Hex)    | 2006/01-2007/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253E                                  |             |                                             |
| B0671 | US | Volkswagen | Jetta               | 2013/01-2015/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0672 | EU | Volkswagen | Jetta               | 2010/07-2015/12 |        | ● | ● | 4   | A         | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0673 | US | Volkswagen | Jetta               | 2006/01-2012/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0674 | EU | Volkswagen | New Beetle          | 2011/08-2015/12 |        | ● | ● | 4   | S         | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0675 | EU | Volkswagen | New Beetle          | 2006/01-2011/07 |        | ● | ● | 4   | A         | 433Mhz | Continental | 1K0907253C                                  | S180014701Z | C122215002                                  |
| B0676 | EU | Volkswagen | Passat              | 2014/09-2016/06 |        | ● | ● | 4   |           | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0677 | EU | Volkswagen | Passat              | 2010/09-2014/08 |        | ● | ● | 4   | A         | 433Mhz | Huf/Beru    | 3AA907275D                                  | 532207013   | RDE013                                      |
| B0678 | US | Volkswagen | Passat              | 2006/01-2011/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D/<br>1K0907255C                   | S122215001C |                                             |
| B0679 | EU | Volkswagen | Passat              | 2006/01-2010/08 |        | ● | ● | 4   | A         | 433Mhz | Continental | 1K0907253C                                  | S180014701Z | C122215002                                  |
| B0680 | EU | Volkswagen | Passat CC           | 2014/09-2015/12 |        | ● | ● | 4   |           | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0681 | EU | Volkswagen | Passat CC           | 2008/03-2014/08 |        | ● | ● | 4   | A         | 433Mhz | Huf/Beru    | 3AA907275D                                  | 532207013   | RDE013                                      |
| B0682 | US | Volkswagen | Passat (0-ring Hex) | 2006/01-2008/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253E                                  |             |                                             |
| B0683 | US | Volkswagen | Phaeton             | 2011/01-2011/12 | 433MHz | ● | ● | 4/5 | S         | 433Mhz | Huf/Beru    | 4F0907275D                                  | 532207011   | RDE011                                      |
| B0684 | EU | Volkswagen | Phaeton             | 2010/06-2016/06 |        | ● | ● | 4   | A         | 433Mhz | Huf/Beru    | 4F0907275E                                  | 532207011   | RDE011                                      |
| B0685 | US | Volkswagen | Phaeton             | 2007/06-2010/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Huf/Beru    | 4F0907275B                                  | 532207011   | RDE011                                      |
| B0686 | EU | Volkswagen | Phaeton             | 2007/06-2010/05 |        | ● | ● | 4   | A         | 433Mhz | Huf/Beru    | 4F0907275D                                  | 532207011   | RDE011                                      |
| B0687 | US | Volkswagen | Phaeton             | 2003/01-2007/05 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Huf/Beru    | 4D0907275A                                  | 532107001   | RDE004                                      |
| B0688 | US | Volkswagen | Phaeton             | 2003/01-2007/05 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Huf/Beru    | 4D0907275C                                  | 532207001   | RDE001                                      |
| B0689 | EU | Volkswagen | Phaeton             | 2002/01-2007/05 |        | ● | ● | 4   | A         | 433Mhz | Huf/Beru    | 4D0907275                                   | 532207001   | RDE001                                      |
| B0690 | US | Volkswagen | R32                 | 2008/01-2011/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0691 | US | Volkswagen | Rabbit              | 2006/01-2009/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0692 | US | Volkswagen | Rabbit (0-ring Hex) | 2006/01-2007/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253E                                  |             |                                             |
| B0693 | US | Volkswagen | Routan              | 2011/01-2015/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Schrader    | A0025400217                                 |             | 25400217                                    |
| B0694 | US | Volkswagen | Routan              | 2009/01-2010/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Continental | 7B0907253A                                  |             |                                             |
| B0695 | EU | Volkswagen | Scirocco            | 2008/01-2015/12 |        | ● | ● | 4   |           | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0696 | EU | Volkswagen | Sharan              | 2008/01-2015/12 |        | ● | ● | 4   |           | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |
| B0697 | US | Volkswagen | Tiguan              | 2012/01-2015/12 | 433MHz | ● | ● | 4/5 | A         | 433Mhz | Huf/Beru    | 3AA907275                                   | 532207013   | RDE013                                      |
| B0698 | EU | Volkswagen | Tiguan              | 2011/05-2016/12 |        | ● | ● | 4   | A         | 433Mhz | Huf/Beru    | 3AA907275                                   | 532207013   | RDE013                                      |
| B0699 | US | Volkswagen | Tiguan              | 2009/01-2011/12 | 315MHz | ● | ● | 4/5 | A         | 315Mhz | Continental | 1K0907253D                                  | S122215001C |                                             |
| B0700 | EU | Volkswagen | Touareg             | 2014/08-2016/12 |        | ● | ● | 4   | A         | 433Mhz | Huf/Beru    | 5Q0907275                                   | 532207018   | RDE018                                      |

|       |    |            |              |                 |        |   |   |     |   |        |             |                                    |             |            |
|-------|----|------------|--------------|-----------------|--------|---|---|-----|---|--------|-------------|------------------------------------|-------------|------------|
| B0701 | EU | Volkswagen | Touareg      | 2010/01-2014/07 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275E                         | 532207011   | RDE011     |
| B0702 | EU | Volkswagen | Touareg      | 2007/01-2009/12 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 4F0907275D                         | 532207011   | RDE011     |
| B0703 | EU | Volkswagen | Touareg      | 2002/02-2006/12 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 7L0907275B                         | 532207005   | RDE005     |
| B0704 | US | Volkswagen | Touareg      | 2002/01-2006/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Huf/Beru    | 7L0907275                          | 532207005   | RDE005     |
| B0705 | US | Volkswagen | Touareg 2    | 2012/01-2015/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Huf/Beru    | 4F0907275D                         | 532207011   | RDE011     |
| B0706 | US | Volkswagen | Touareg 2    | 2007/01-2011/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Huf/Beru    | 4F0907275B                         | 532207011   | RDE011     |
| B0707 | EU | Volkswagen | Touran       | 2015/01-2016/06 |        | ● | ● | 4   |   | 433Mhz | Huf/Beru    | 5Q0907275                          | 532207018   | RDE018     |
| B0708 | EU | Volkswagen | Touran (LCV) | 2010/07-2016/06 |        | ● | ● | 4   | A | 433Mhz | Huf/Beru    | 3AA907275D                         | 532207013   | RDE013     |
| B0709 | EU | Volkswagen | Transporter  | 2012/01-2016/06 |        | ● | ● | 4   |   | 433Mhz | Huf/Beru    | 5Q0907275                          | 532207018   | RDE018     |
| B0710 | EU | Volvo      | C30          | 2012/01-2013/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0711 | US | Volvo      | C30          | 2012/01-2013/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0712 | EU | Volvo      | C30          | 2011/01-2011/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0713 | US | Volvo      | C30          | 2011/01-2011/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0714 | EU | Volvo      | C30          | 2010/01-2010/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0715 | US | Volvo      | C30          | 2010/01-2010/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0716 | EU | Volvo      | C30          | 2009/01-2009/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0717 | US | Volvo      | C30          | 2009/01-2009/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0718 | EU | Volvo      | C30          | 2008/01-2008/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0719 | US | Volvo      | C30          | 2008/01-2008/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0720 | EU | Volvo      | C30          | 2007/01-2007/12 |        | ○ | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0721 | US | Volvo      | C30          | 2006/01-2007/12 | 433MHz | ○ | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0722 | EU | Volvo      | C30 Electric | 2010/12-2013/12 |        | ○ | ● | 4   | A | 433Mhz | Continental | 31341893/<br>31341171              | S180052050Z | S180052050 |
| B0723 | EU | Volvo      | C70          | 2012/01-2014/06 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0724 | US | Volvo      | C70          | 2012/01-2013/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0725 | EU | Volvo      | C70          | 2011/01-2011/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0726 | US | Volvo      | C70          | 2011/01-2011/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0727 | EU | Volvo      | C70          | 2010/01-2010/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0728 | US | Volvo      | C70          | 2010/01-2010/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0729 | EU | Volvo      | C70          | 2009/01-2009/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0730 | US | Volvo      | C70          | 2009/01-2009/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0731 | EU | Volvo      | C70          | 2008/01-2008/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0732 | US | Volvo      | C70          | 2008/01-2008/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0733 | US | Volvo      | C70          | 2007/01-2007/12 | 433MHz | ○ | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0734 | EU | Volvo      | C70          | 2006/01-2007/12 |        | ○ | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0735 | EU | Volvo      | S40          | 2012/01-2014/06 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0736 | US | Volvo      | S40          | 2012/01-2012/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0737 | EU | Volvo      | S40          | 2011/01-2011/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0738 | US | Volvo      | S40          | 2011/01-2011/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0739 | EU | Volvo      | S40          | 2010/01-2010/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0740 | US | Volvo      | S40          | 2010/01-2010/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0741 | EU | Volvo      | S40          | 2009/01-2009/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0742 | US | Volvo      | S40          | 2009/01-2009/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0743 | EU | Volvo      | S40          | 2008/01-2008/12 |        | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0744 | US | Volvo      | S40          | 2008/01-2008/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0745 | US | Volvo      | S40          | 2007/01-2007/12 | 433MHz | ○ | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0746 | EU | Volvo      | S40          | 2004/01-2007/12 |        | ○ | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |
| B0747 | US | Volvo      | S60          | 2015/01-2015/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189 |             |            |
| B0748 | EU | Volvo      | S60          | 2014/07-2015/12 |        | ○ | ● | 4   | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189 | S180052050Z | S180052050 |
| B0749 | US | Volvo      | S60          | 2012/01-2014/12 | 433MHz | ● | ○ | 4   | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020 |

|       |    |       |        |                 |        |   |   |   |   |        |             |                                          |             |                       |
|-------|----|-------|--------|-----------------|--------|---|---|---|---|--------|-------------|------------------------------------------|-------------|-----------------------|
| B0750 | US | Volvo | S60    | 2011/01-2011/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0751 | EU | Volvo | S60    | 2010/03-2014/06 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0752 | US | Volvo | S60    | 2010/01-2010/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Schrader    | 31200923                                 |             | 31200923              |
| B0753 | US | Volvo | S60    | 2009/01-2009/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923                                 |             | 31200923              |
| B0754 | US | Volvo | S60    | 2008/01-2008/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923                                 |             | 31200923              |
| B0755 | EU | Volvo | S60    | 2007/01-2010/02 |        | ● | ● | 4 | A | 433Mhz | Schrader    | 31329981/<br>30748354                    | 90518149    | 30748354              |
| B0756 | US | Volvo | S60    | 2007/01-2007/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0757 | US | Volvo | S60    | 2006/01-2006/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0758 | US | Volvo | S60    | 2005/01-2005/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0759 | US | Volvo | S60    | 2004/01-2004/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0760 | EU | Volvo | S60    | 2000/07-2006/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | 31329981/<br>30748354                    | 90518149    | 30748354              |
| B0761 | US | Volvo | S80    | 2015/01-2015/12 | 433MHz | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189       |             |                       |
| B0762 | EU | Volvo | S80    | 2014/07-2016/06 |        | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189       | S180052050Z | S180052050            |
| B0763 | US | Volvo | S80    | 2012/01-2014/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0764 | EU | Volvo | S80    | 2012/01-2014/06 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0765 | EU | Volvo | S80    | 2011/01-2011/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0766 | US | Volvo | S80    | 2011/01-2011/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0767 | EU | Volvo | S80    | 2010/01-2010/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0768 | US | Volvo | S80    | 2010/01-2010/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0769 | EU | Volvo | S80    | 2009/01-2009/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0770 | US | Volvo | S80    | 2009/01-2009/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0771 | EU | Volvo | S80    | 2008/01-2008/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0772 | US | Volvo | S80    | 2008/01-2008/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0773 | EU | Volvo | S80    | 2007/01-2007/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0774 | US | Volvo | S80    | 2007/01-2007/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0775 | US | Volvo | S80    | 2006/01-2007/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0776 | EU | Volvo | S80    | 2006/01-2006/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0777 | US | Volvo | S80    | 2005/01-2005/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0778 | US | Volvo | S80    | 2004/01-2004/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0779 | EU | Volvo | V40    | 2014/01-2016/06 |        | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171                    | S180052050Z | S180052050            |
| A0001 | EU | Dacia | Dokker | 2014/01-2016/06 |        | ○ | ● | 4 | C | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |             | 56029398AB            |
| B0781 | US | Volvo | V50    | 2012/01-2012/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0782 | EU | Volvo | V50    | 2011/01-2011/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0783 | US | Volvo | V50    | 2011/01-2011/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0784 | EU | Volvo | V50    | 2010/01-2010/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0785 | US | Volvo | V50    | 2010/01-2010/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0786 | EU | Volvo | V50    | 2009/01-2009/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0787 | US | Volvo | V50    | 2009/01-2009/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0788 | EU | Volvo | V50    | 2008/01-2008/12 |        | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0789 | US | Volvo | V50    | 2008/01-2008/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0790 | US | Volvo | V50    | 2007/01-2007/12 | 433MHz | ○ | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |

|       |    |       |                         |                 |        |   |   |   |   |        |             |                                    |             |                       |
|-------|----|-------|-------------------------|-----------------|--------|---|---|---|---|--------|-------------|------------------------------------|-------------|-----------------------|
| B0791 | EU | Volvo | V50                     | 2004/01-2007/12 |        | ○ | ○ | 4 | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020            |
| B0792 | EU | Volvo | V60                     | 2014/07-2016/06 |        | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189 | S180052050Z | S180052050            |
| B0793 | EU | Volvo | V60                     | 2012/01-2014/06 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0794 | EU | Volvo | V60                     | 2011/01-2011/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0795 | EU | Volvo | V60                     | 2010/09-2010/12 |        | ○ | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0796 | US | Volvo | V60 Cross Country Wagon | 2015/01-2016/12 | 433Mhz | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189 | S180052050Z | S180052050            |
| B0797 | EU | Volvo | V70                     | 2014/07-2016/06 |        | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189 | S180052050Z | S180052050            |
| B0798 | EU | Volvo | V70                     | 2012/01-2014/06 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0799 | EU | Volvo | V70                     | 2011/01-2011/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0800 | US | Volvo | V70                     | 2010/01-2014/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020            |
| B0801 | EU | Volvo | V70                     | 2010/01-2010/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0802 | EU | Volvo | V70                     | 2009/01-2009/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0803 | US | Volvo | V70                     | 2009/01-2009/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020            |
| B0804 | EU | Volvo | V70                     | 2008/01-2008/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0805 | US | Volvo | V70                     | 2008/01-2008/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020            |
| B0806 | EU | Volvo | V70                     | 2007/01-2007/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | 31329981/<br>30748354              | 90518149    | 30748354              |
| B0807 | US | Volvo | V70                     | 2007/01-2007/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991              |             | 31200923/<br>30748991 |
| B0808 | EU | Volvo | V70                     | 2006/03-2006/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | 31329981/<br>30748354              | 90518149    | 30748354              |
| B0809 | US | Volvo | V70                     | 2006/01-2006/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991              |             | 31200923/<br>30748991 |
| B0810 | US | Volvo | V70                     | 2005/01-2005/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991              |             | 31200923/<br>30748991 |
| B0811 | US | Volvo | V70                     | 2004/01-2004/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991              |             | 31200923/<br>30748991 |
| B0812 | US | Volvo | XC60                    | 2015/01-2016/12 | 433Mhz | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189 | S180052050Z | S180052050            |
| B0813 | EU | Volvo | XC60                    | 2014/07-2016/06 |        | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189 | S180052050Z | S180052050            |
| B0814 | US | Volvo | XC60                    | 2012/01-2014/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020            |
| B0815 | EU | Volvo | XC60                    | 2012/01-2014/06 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0816 | EU | Volvo | XC60                    | 2011/01-2011/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0817 | US | Volvo | XC60                    | 2011/01-2011/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                           | S180052020  | S180052020            |
| B0818 | EU | Volvo | XC60                    | 2010/01-2010/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0819 | US | Volvo | XC60                    | 2010/01-2010/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923                           |             | 31200923              |
| B0820 | EU | Volvo | XC60                    | 2009/01-2009/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893              | S180052020  | S180052020            |
| B0821 | US | Volvo | XC60                    | 2009/01-2009/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923                           |             | 31200923              |

|       |    |        |                 |                 |        |   |   |   |   |        |             |                                          |             |                       |
|-------|----|--------|-----------------|-----------------|--------|---|---|---|---|--------|-------------|------------------------------------------|-------------|-----------------------|
| B0822 | EU | Volvo  | XC60            | 2008/05-2008/12 |        | ○ | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893                    | S180052020  | S180052020            |
| B0823 | US | Volvo  | XC70            | 2015/01-2016/12 | 433Mhz | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189       | S180052050Z | S180052050            |
| B0824 | EU | Volvo  | XC70            | 2014/07-2016/06 |        | ○ | ● | 4 | A | 433Mhz | Continental | 31341893/<br>31341171/<br>31414189       | S180052050Z | S180052050            |
| B0825 | US | Volvo  | XC70            | 2012/01-2014/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0826 | EU | Volvo  | XC70            | 2012/01-2014/06 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893                    | S180052020  | S180052020            |
| B0827 | EU | Volvo  | XC70            | 2011/01-2011/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893                    | S180052020  | S180052020            |
| B0828 | US | Volvo  | XC70            | 2011/01-2011/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0829 | EU | Volvo  | XC70            | 2010/01-2010/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893                    | S180052020  | S180052020            |
| B0830 | US | Volvo  | XC70            | 2010/01-2010/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0831 | EU | Volvo  | XC70            | 2009/01-2009/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893                    | S180052020  | S180052020            |
| B0832 | US | Volvo  | XC70            | 2009/01-2009/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0833 | EU | Volvo  | XC70            | 2008/01-2008/12 |        | ● | ● | 4 | A | 433Mhz | Continental | 31302096/<br>31341893                    | S180052020  | S180052020            |
| B0834 | US | Volvo  | XC70            | 2008/01-2008/12 | 433MHz | ● | ○ | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0835 | EU | Volvo  | XC70            | 2007/02-2007/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | 31329981/<br>30748354                    | 90518149    | 30748354              |
| B0836 | US | Volvo  | XC70            | 2007/01-2007/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0837 | US | Volvo  | XC70            | 2006/01-2006/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0838 | US | Volvo  | XC70            | 2005/01-2005/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0839 | US | Volvo  | XC70            | 2004/01-2004/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Schrader    | 31200923/<br>30748991                    |             | 31200923/<br>30748991 |
| B0840 | US | Volvo  | XC90            | 2015/01-2016/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Schrader    | 50662193                                 |             |                       |
| B0841 | US | Volvo  | XC90            | 2009/01-2014/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923                                 |             | 31200923              |
| B0842 | US | Volvo  | XC90            | 2008/01-2008/12 | 433MHz | ● | ● | 4 | A | 433Mhz | Continental | 31302096                                 | S180052020  | S180052020            |
| B0843 | EU | Volvo  | XC90            | 2007/01-2010/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | 31329981/<br>30748354                    | 90518149    | 30748354              |
| B0844 | US | Volvo  | XC90            | 2007/01-2007/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923                                 |             | 31200923              |
| B0845 | EU | Volvo  | XC90            | 2006/01-2006/12 |        | ● | ● | 4 | A | 433Mhz | Schrader    | 31329981/<br>30748354                    | 90518149    | 30748354              |
| B0846 | US | Volvo  | XC90            | 2006/01-2006/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923                                 |             | 31200923              |
| B0847 | US | Volvo  | XC90            | 2004/01-2005/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Schrader    | 31200923                                 |             | 31200923              |
| A0002 | EU | Dacia  | Duster          | 2010/02-2016/06 |        | ○ | ● | 4 | C | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |             | 407001628R-B          |
| A0003 | EU | Dacia  | Lodgy           | 2012/01-2016/06 |        | ○ | ● | 4 | C | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |             | 407001628R-B          |
| A0004 | EU | Dacia  | Logan           | 2012/11-2015/10 |        | ○ | ● | 4 | C | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |             | 407001628R-B          |
| A0006 | EU | Dacia  | Sandero         | 2012/10-2016/06 |        | ○ | ● | 4 | C | 433Mhz | Schrader    | 407001628R/<br>407009322R/<br>407009987R |             | 407001628R-B          |
| C0001 | EU | Abarth | 4A Grande Punto | 2007/01-2010/12 |        | ○ | ● | 4 | A | 433Mhz | TRW         | 51839114                                 |             | 51839114              |
| C0002 | EU | Abarth | 4B Punto EVO    | 2010/01-2012/12 |        | ○ | ● | 4 | A | 433Mhz | TRW         | 51839114                                 |             | 51839114              |
| C0003 | EU | Abarth | 81 Nuova Punto  | 2012/01-2013/12 |        | ○ | ● | 4 | A | 433Mhz | TRW         | 51839114                                 |             | 51839114              |

|       |    |            |                |                 |        |   |   |     |           |        |             |                                    |             |                           |
|-------|----|------------|----------------|-----------------|--------|---|---|-----|-----------|--------|-------------|------------------------------------|-------------|---------------------------|
| C0004 | EU | Alfa Romeo | 159            | 2005/07-2011/12 |        | ○ | ● | 4   |           | 433Mhz | TRW         | 51839114                           |             | 51839114                  |
| C0005 | EU | Alfa Romeo | 4C             | 2013/06-2016/06 |        | ○ | ● | 4   | A         | 433Mhz | Schrader    | 05154876AA                         |             | 670002790                 |
| C0006 | EU | Alfa Romeo | Alfa 8C        | 2006/12-2010/12 |        | ○ | ● | 4   | S         | 433Mhz | Huf/Beru    | 185189                             | 532207001   | RDE001                    |
| C0007 | EU | Alfa Romeo | Brera          | 2005/11-2010/12 |        | ○ | ● | 4   |           | 433Mhz | TRW         | 51839114                           |             | 51839114                  |
| C0008 | EU | Alfa Romeo | Giulietta      | 2014/01-2016/12 |        | ○ | ● | 4   |           | 433Mhz | Schrader    | 53104671                           |             |                           |
| C0009 | EU | Alfa Romeo | Giulietta      | 2010/01-2013/12 |        | ○ | ● | 4   | A         | 433Mhz | TRW         | 51839114                           |             | 51839114                  |
| C0010 | EU | Alfa Romeo | MiTo           | 2013/08-2016/06 |        | ○ | ● | 4   |           | 433Mhz | Schrader    | 53104671                           |             | 53104671                  |
| C0011 | EU | Alfa Romeo | MiTo           | 2008/06-2013/07 |        | ○ | ● | 4   |           | 433Mhz | TRW         | 51839114                           |             | 51839114                  |
| C0012 | EU | Alfa Romeo | Spider         | 2006/06-2010/12 |        | ○ | ● | 4   |           | 433Mhz | TRW         | 51839114                           |             | 51839114                  |
| C0013 | EU | Buick      | Park avenue    | 1997/01-2005/12 |        | ○ | ● | 4   | S         | 433Mhz | Schrader    | 25789964                           | 90518185    | 25789964                  |
| C0014 | US | Buick      | Rainier        | 2007/01-2007/12 | 433MHz | ● | ● | 4   | S         | 433Mhz | Schrader    | 25774007                           | 90518110    | 25774007                  |
| C0015 | EU | Cadillac   | ATS            | 2014/01-2015/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 20925925                           | 60518416    | 20925925                  |
| C0016 | EU | Cadillac   | ATS            | 2012/01-2013/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 20925925                           | 60518416    | 20925925                  |
| C0017 | EU | Cadillac   | ATS-V          | 2016/01-2016/12 |        | ○ | ● | 4   |           | 433Mhz | Schrader    | 20925925                           | 60518416    | 20925925                  |
| C0018 | EU | Cadillac   | CTS            | 2008/01-2016/06 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 20922901                           | 90518390    | 20922901                  |
| C0019 | EU | Cadillac   | CTS            | 2006/01-2007/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 25774007                           | 90518110    | 25774007                  |
| C0021 | EU | Cadillac   | Escalade       | 2013/01-2016/06 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0022 | EU | Cadillac   | Escalade       | 2012/01-2012/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0023 | EU | Cadillac   | Escalade       | 2009/01-2011/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0024 | EU | Cadillac   | Escalade       | 2007/01-2008/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0025 | EU | Cadillac   | Escalade       | 2005/12-2006/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| A0009 | EU | Honda      | Accord         | 2014/01-2016/06 |        | ● | ● | 4   | 0         | 433Mhz | Continental | 42753TLOG52                        | S180052059Z | S180052059                |
| C0027 | EU | Cadillac   | STS            | 2005/01-2011/04 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 25758221                           | 90518046    | 25758221                  |
| C0028 | EU | Cadillac   | XLR            | 2004/01-2009/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 25758221                           | 90518046    | 25758221                  |
| C0029 | EU | Cadillac   | XTS            | 2012/05-2016/06 |        | ● | ● | 4   |           | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0030 | EU | Chevrolet  | Aveo           | 2011/11-2016/06 |        | ● | ● | 4   |           | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0031 | EU | Chevrolet  | Camaro         | 2016/01-2016/12 |        | ○ | ● | 4   |           | 433Mhz | Schrader    | 20925925                           | 60518416    | 20925925                  |
| C0032 | EU | Chevrolet  | Camaro         | 2009/01-2015/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 20925925                           | 60518416    | 20925925                  |
| C0033 | EU | Chevrolet  | Captiva        | 2006/06-2016/06 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 25789964/<br>22853740/<br>13581561 | 90518185    | 25789964                  |
| C0034 | EU | Chevrolet  | Cobalt         | 2013/02-2015/12 |        | ● | ● | 4   |           | 433Mhz | Schrader    | 25789964/<br>22853740/<br>13581561 | 90518185    | 22853740                  |
| C0035 | EU | Chevrolet  | Colorado       | 2014/06-2015/12 |        | ● | ● | 4   | Copy only | 433Mhz | Schrader    | 20925925                           | 60518416    | 20925925                  |
| C0036 | EU | Chevrolet  | Colorado (LCV) | 2013/01-2015/12 |        | ● | ● | 4   |           | 433Mhz | Schrader    | 25758221                           | 90518046    | 25758221                  |
| C0037 | EU | Chevrolet  | Corvette       | 2010/02-2013/01 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 20925925                           | 60518416    | 20925925                  |
| C0038 | EU | Chevrolet  | Corvette       | 2004/07-2010/01 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 25758221                           | 90518046    | 25758221                  |
| C0040 | EU | Chevrolet  | Cruze          | 2008/10-2016/06 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0041 | EU | Chevrolet  | Express        | 2002/07-2016/06 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0042 | EU | Chevrolet  | Malibu         | 2014/07-2016/06 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 13581561                           | 90518185    | 13581561                  |
| C0043 | EU | Chevrolet  | Malibu         | 2011/07-2014/06 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0044 | EU | Chevrolet  | Matiz          | 2014/06-2016/06 |        | ○ | ● | 4   | Copy only | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0045 | EU | Chevrolet  | Orlando        | 2010/09-2016/06 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0046 | EU | Chevrolet  | Spark          | 2009/07-2016/06 |        | ● | ● | 4   | Copy only | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0047 | EU | Chevrolet  | Suburban       | 2006/03-2008/07 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                  |
| C0048 | EU | Chevrolet  | Trailblazer    | 2007/01-2008/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 25774007                           | 90518110    | 25774007                  |
| C0049 | EU | Chevrolet  | Trax           | 2012/03-2016/06 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 20922901                           | 90518390    | 20922901                  |
| C0050 | EU | Chevrolet  | Volt           | 2010/11-2015/12 |        | ● | ● | 4   | S         | 433Mhz | Schrader    | 13348393                           | 90518352    | 13348393                  |
| C0052 | EU | Chrysler   | 300            | 2011/01-2016/06 |        | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029400AC/<br>56029400AD          | 90518291    | 56029400AC/<br>56029400AD |
| C0053 | EU | Chrysler   | 300            | 2009/01-2010/12 |        | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029400AC/<br>56029400AD          | 90518291    | 56029400AC/<br>56029400AD |

|       |    |          |                |                 |  |   |   |     |     |        |             |                           |                       |                                                   |
|-------|----|----------|----------------|-----------------|--|---|---|-----|-----|--------|-------------|---------------------------|-----------------------|---------------------------------------------------|
| C0054 | EU | Chrysler | 300C           | 2005/06-2010/05 |  | ● | ● | 4/5 | A/O | 433Mhz | Continental | 56053031AD                | 90518155/<br>90518434 | 56029359AA-AB/<br>56053031AC-AD/<br>56029481AA-AB |
| C0055 | EU | Chrysler | 300C(18 inch)  | 2010/06-2015/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029398AB                |                       | 56029398AB                                        |
| C0056 | EU | Chrysler | 300C(20 inch)  | 2010/06-2015/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029400AB                |                       | 56029400AB/<br>56029400AD                         |
| C0057 | EU | Chrysler | Delta          | 2013/02-2016/12 |  | ● | ● | 4/5 | O   | 433Mhz | TRW         | 51839114                  |                       | 51839114                                          |
| C0058 | EU | Chrysler | Grand Voyager  | 2011/01-2016/12 |  | ● | ● | 4/5 | S   | 433Mhz | Schrader    | 56029398AB                |                       | 56029398AB                                        |
| C0059 | EU | Chrysler | Grand Voyager  | 2007/01-2010/12 |  | ● | ● | 4/5 | S   | 433Mhz | Schrader    | 56029359AC                |                       | 56029359AC                                        |
| C0060 | EU | Chrysler | Pacifica       | 2004/01-2005/12 |  | ● | ● | 4/5 | S   | 433Mhz | Schrader    | 52088990AC                |                       | 52088990AD/<br>52088990AC/<br>52088990AE          |
| C0061 | EU | Chrysler | Sebring        | 2006/06-2015/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029359AA                |                       | 56029359AC/<br>56029359AB/<br>56029359AA          |
| C0063 | EU | Chrysler | Town & Country | 2011/04-2016/06 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 53104671                  | 90518358              | 53104671                                          |
| C0064 | EU | Chrysler | Town & Country | 2007/01-2011/03 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029359AC                |                       | 56029359AC/<br>56029359AB/<br>56029359AA/         |
| C0065 | EU | Chrysler | Viper          | 2012/09-2016/06 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 53104671                  | 90518358              | 53104671                                          |
| C0066 | EU | Chrysler | Voyager        | 2011/01-2016/06 |  | ● | ● | 4/5 | S   | 433Mhz | Schrader    | 56029398AA/<br>56029398AB | 90518358              | 56029398AA/<br>56029398AB                         |
| C0067 | EU | Chrysler | Voyager        | 2007/07-2010/12 |  | ● | ● | 4/5 | A   | 433Mhz | Continental | 68001698AB                | 90518155/<br>90518434 | 56029359AA-AB/<br>56053031AC/<br>56029481AA-AB    |
| C0068 | EU | Chrysler | Ypsilon        | 2011/04-2016/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029398AB                |                       | 56029398AA/<br>56029398AB                         |
| C0069 | EU | Dodge    | Avenger        | 2006/01-2013/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029359AC                | 90518155/<br>90518434 | 56029359AC/<br>56029359AB/<br>56029359AA/         |
| C0070 | EU | Dodge    | Caliber        | 2006/01-2011/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029359AC                | 90518155/<br>90518434 | 56029359AC/<br>56029359AB/<br>56029359AA/         |
| C0071 | EU | Dodge    | Caravan        | 2011/06-2016/12 |  | ● | ● | 4/5 |     | 433Mhz | Schrader    | 56029398AB                |                       | 56029398AB                                        |
| C0072 | EU | Dodge    | Challenger     | 2008/01-2016/06 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029400AD                | 90518291              | 56029400AD/<br>56029398AB/<br>56029359AC          |
| C0073 | EU | Dodge    | Charger        | 2014/10-2016/06 |  | ● | ● | 4/5 | O   | 433Mhz | Schrader    | 68241067AA                | 90518358              | 68241067AA                                        |
| C0074 | EU | Dodge    | Charger        | 2010/01-2014/09 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029398AB                | 90518358              | 56029398AB                                        |
| C0075 | EU | Dodge    | Charger        | 2009/01-2009/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029400AB                | 90518291/<br>90518358 | 56029400AB/<br>56029400AC                         |
| C0076 | EU | Dodge    | Dakota         | 2009/01-2015/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029359AC                | 90518155/<br>90518434 | 56029359AA-AC/<br>56053031AC/<br>56029481AA-AB    |
| C0077 | EU | Dodge    | Durango        | 2011/01-2016/06 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029398AB                | 90518358              | 56029398AA/<br>56029398AB                         |
| C0078 | EU | Dodge    | Grand Caravan  | 2011/01-2015/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029398AB                | 90518358              | 56029398AA/<br>56029398AB                         |
| C0079 | EU | Dodge    | Journey        | 2011/01-2016/06 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029398AB                | 90518358              | 56029398AA/<br>56029398AB                         |
| C0080 | EU | Dodge    | Journey        | 2009/01-2010/12 |  | ● | ● | 4/5 | A   | 433Mhz | Continental | 68001698AA/<br>68001698AB |                       | 68001698AA/<br>68001698AB                         |
| C0081 | EU | Dodge    | Nitro          | 2007/01-2011/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029359AC                | 90518155/<br>90518434 | 56029359AA-AC/<br>56053031AC/<br>56029481AA-AB    |
| C0082 | EU | Dodge    | Ram            | 2014/01-2015/12 |  | ● | ● | 4/5 | A   | 433Mhz | TRW         | 68157568AB/<br>68239720AA |                       | 68239720AA/<br>68157568AB                         |
| C0083 | EU | Dodge    | Ram            | 2010/01-2013/12 |  | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029398AB                | 90518358              | 56029398AA/<br>56029398AB                         |

|       |    |         |                 |                 |  |   |   |     |           |        |             |                                              |             |                             |
|-------|----|---------|-----------------|-----------------|--|---|---|-----|-----------|--------|-------------|----------------------------------------------|-------------|-----------------------------|
| C0084 | EU | Dodge   | Viper           | 2013/01-2015/12 |  | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029400AC                                   | 90518358    | 56029400AC                  |
| C0085 | EU | Ferrari | 458 Italia      | 2009/01-2015/12 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 228887                                       | 532207011   | RDE011                      |
| C0086 | EU | Ferrari | 550 Maranello   | 2002/03-2006/12 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 224549                                       | 532207001   | RDE001                      |
| C0087 | EU | Ferrari | 575 M-Maranello | 2002/09-2006/02 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 224549                                       | 532207001   | RDE001                      |
| C0088 | EU | Ferrari | 599 GTB         | 2006/04-2012/06 |  | ○ | ○ | 4   | A         | 433Mhz | Huf/Beru    | 224549                                       | 532207001   | RDE001                      |
| C0089 | EU | Ferrari | 612 Scaglietti  | 2004/03-2011/01 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 224549                                       | 532207001   | RDE001                      |
| C0090 | EU | Ferrari | California      | 2008/10-2016/06 |  | ○ | ● | 4   | S         | 433Mhz | Huf/Beru    | 228887                                       | 532207011   | RDE011                      |
| C0091 | EU | Ferrari | Enzo            | 2003/01-2006/11 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 193867                                       | 532207005   | RDE005                      |
| C0092 | EU | Ferrari | F12 Berlinetta  | 2012/10-2015/12 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 282189                                       | 532207011   | RDE011                      |
| C0093 | EU | Ferrari | F430            | 2007/07-2009/10 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 282189                                       | 532207011   | RDE011                      |
| C0094 | EU | Ferrari | F430            | 2004/09-2007/06 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 224549                                       | 532207001   | RDE001                      |
| C0095 | EU | Ferrari | FF              | 2011/06-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 282189                                       | 532207011   | RDE011                      |
| C0096 | EU | Ferrari | FXX             | 2005/07-2006/12 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 193867                                       | 532207005   | RDE005                      |
| C0097 | EU | Fiat    | 500             | 2007/01-2016/12 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 53104671                                     | 90518358    | 53104671                    |
| C0098 | EU | Fiat    | 500L            | 2007/01-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 56029398AB                                   | 90518358    | 56029398AB                  |
| C0099 | EU | Fiat    | 500X            | 2015/01-2015/12 |  | ○ | ● | 4   | A         | 433Mhz | Continental | 53305555                                     |             |                             |
| C0100 | EU | Fiat    | Bravo           | 2007/01-2014/09 |  | ○ | ● | 4   | A         | 433Mhz | TRW         | 51839114                                     |             | 51839114                    |
| C0101 | EU | Fiat    | Croma           | 2005/01-2011/03 |  | ○ | ● | 4   | A         | 433Mhz | TRW         | 51839114                                     |             | 51839114                    |
| C0102 | EU | Fiat    | Doblo           | 2012/12-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 53104671                                     | 90518358    | 53104671                    |
| C0103 | EU | Fiat    | Ducato          | 2014/06-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 05154876AA                                   |             | 670002790                   |
| C0104 | EU | Fiat    | Freemont        | 2014/07-2015/09 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 68241067AA                                   | 90518358    | 68241067AA                  |
| C0105 | EU | Fiat    | Freemont        | 2011/03-2014/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 56029398AB                                   | 90518358    | 56029398AB                  |
| C0106 | EU | Fiat    | Grande Punto    | 2012/01-2015/12 |  | ○ | ● | 4   | A         | 433Mhz | TRW         | 51839114                                     |             | 51839114                    |
| C0108 | EU | Fiat    | Linea           | 2007/03-2015/12 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 53104671                                     | 90518358    | 53104671                    |
| C0109 | EU | Fiat    | Punto           | 2005/09-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | TRW         | 51839114                                     |             | 51839114                    |
| C0110 | EU | Fiat    | Punto Evo       | 2009/01-2012/12 |  | ○ | ● | 4   | A         | 433Mhz | TRW         | 51839114                                     |             | 51839114                    |
| C0111 | EU | Fiat    | Qubo            | 2007/10-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 53104671                                     | 90518358    | 53104671                    |
| C0112 | EU | Fiat    | Scudo           | 2014/10-2016/06 |  | ○ | ● | 4   |           | 433Mhz | Schrader    | 9811764480                                   |             | 9811764480                  |
| C0113 | EU | Fiat    | Scudo           | 2011/01-2013/10 |  | ○ | ● | 4   |           | 433Mhz | Schrader    | 9677130580                                   |             | 9677130580                  |
| C0114 | EU | Fiat    | Strada          | 2012/01-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 53104671                                     | 90518358    | 53104671                    |
| C0115 | EU | Fiat    | Ulysse          | 2005/10-2010/12 |  | ○ | ● | 4   | Copy only | 433Mhz | Continental | 9681102280/<br>9673198580                    | S180014805Z | S120123004                  |
| C0116 | EU | Fiat    | Ulysse          | 2002/06-2005/09 |  | ○ | ● | 4   | Copy only | 433Mhz | Schrader    | 9634866180                                   | 9634866180  |                             |
| C0117 | EU | Ford    | B-MAX           | 2014/06-2016/06 |  | ○ | ● | 4   | S         | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A150CB/<br>EV6T1A180DB  |             | EV6T-1A180-CB               |
| C0118 | EU | Ford    | C-MAX           | 2014/04-2016/06 |  | ○ | ● | 4   | S         | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A150CB/<br>EV6T1A180DB  |             | EV6T-1A180-CB               |
| C0119 | EU | Ford    | Ecosport        | 2014/10-2016/06 |  | ○ | ● | 4   | S         | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A150CB/<br>EV6T1A180DB  |             | EV6T-1A180-CB               |
| C0120 | EU | Ford    | Ecosport        | 2012/07-2014/09 |  | ○ | ● | 4   | S         | 433Mhz | Schrader    | DR3V1A180BB                                  |             |                             |
| C0121 | EU | Ford    | Edge            | 2015/01-2016/06 |  | ○ | ● | 4   | A/S       | 433Mhz | Schrader    | F2GT1A180CB/<br>F2GT1A150CB                  |             | F2GT1A180CB/<br>F2GT1A150CB |
| C0122 | EU | Ford    | Escape          | 2012/05-2015/12 |  | ● | ● | 4   | S         | 433Mhz | Schrader    | BB5T1A180AA                                  |             |                             |
| C0123 | EU | Ford    | Explorer        | 2011/01-2016/06 |  | ● | ● | 4   | S         | 433Mhz | Schrader    | BB5T1A180AA                                  | 90518346    | BB5T1A180AA                 |
| C0124 | EU | Ford    | Fiesta          | 2014/05-2016/06 |  | ○ | ● | 4   | S         | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A150CB/<br>EV6T1A180DB/ |             | EV6T-1A180-CB               |
| C0125 | EU | Ford    | Fiesta ST       | 2014/01-2016/06 |  | ○ | ● | 4   | S         | 433Mhz | Schrader    | DR3V1A180DA/<br>BB5T1A180AA/<br>DV6T1A180AA  | 90518346    | DR3V-1A180-DA               |
| C0126 | EU | Ford    | Focus           | 2010/12-2016/06 |  | ● | ● | 4   | S         | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A150CB/<br>EV6T1A180DB  |             | EV6T-1A180-CB               |

|       |    |        |                 |                 |  |   |   |   |     |        |             |                                             |             |                                    |
|-------|----|--------|-----------------|-----------------|--|---|---|---|-----|--------|-------------|---------------------------------------------|-------------|------------------------------------|
| C0127 | EU | Ford   | Focus RS        | 2015/08-2016/12 |  | ○ | ● | 4 |     | 433Mhz | Schrader    | DR3V1A180DA                                 |             | DR3V-1A180-DA                      |
| C0128 | EU | Ford   | Focus ST        | 2014/05-2016/06 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | DR3V1A180DA                                 | 90518346    | DR3V-1A180-DA                      |
| C0130 | EU | Ford   | F-Series        | 2010/01-2015/12 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | BB5T1A180AA                                 |             |                                    |
| C0131 | EU | Ford   | F-Series        | 2008/09-2009/12 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | BB5T1A180AA                                 |             |                                    |
| C0132 | EU | Ford   | Galaxy          | 2015/01-2016/06 |  | ○ | ● | 4 | A/S | 433Mhz | Schrader    | F2GT1A180CB/<br>F2GT1A150CB                 |             | F2GT1A180CB/<br>F2GT1A150CB        |
| C0133 | EU | Ford   | Galaxy          | 2006/01-2014/12 |  | ● | ● | 4 | S   | 433Mhz | Continental | 8G921A159AC/<br>8G921A189KB                 | S180084730Z | S180052020                         |
| C0135 | EU | Ford   | Ka              | 2008/09-2013/12 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | 56029398AB                                  |             | 56029398AA/<br>56029398AB          |
| C0136 | EU | Ford   | Kuga            | 2012/11-2016/06 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A150CB/<br>EV6T1A180DB |             | EV6T-1A180-CB                      |
| C0137 | EU | Ford   | Mondeo          | 2014/10-2016/06 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A150CB/<br>EV6T1A180DB |             | EV6T-1A180-CB                      |
| C0138 | EU | Ford   | Mondeo          | 2007/03-2014/09 |  | ● | ● | 4 | S   | 433Mhz | Continental | 8G921A159AC/<br>8G921A189KB                 | S180084730Z | S180052020                         |
| C0139 | EU | Ford   | Mustang         | 2015/01-2016/06 |  | ○ | ● | 4 | A/S | 433Mhz | Schrader    | F2GT1A180CB/<br>F2GT1A150CB                 |             | F2GT1A180CB/<br>F2GT1A150CB        |
| C0140 | EU | Ford   | Mustang S197    | 2004/09-2015/12 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | DR3V1A180BB                                 |             |                                    |
| C0141 | EU | Ford   | Mustang S550    | 2014/05-2015/12 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | EV6T1A180CB                                 |             |                                    |
| C0142 | EU | Ford   | Ranger          | 2015/01-2015/12 |  | ○ | ● | 4 |     | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A150CB                 |             |                                    |
| C0143 | EU | Ford   | S-Max           | 2015/01-2016/06 |  | ○ | ● | 4 | A/S | 433Mhz | Schrader    | F2GT1A180CB/<br>F2GT1A150CB                 |             | F2GT1A180CB/<br>F2GT1A150CB        |
| C0144 | EU | Ford   | S-Max           | 2006/05-2014/12 |  | ● | ● | 4 | S   | 433Mhz | Continental | 8G921A159AC/<br>8G921A189KB                 | S180084730Z | S180052020                         |
| C0145 | EU | Ford   | Tourneo Connect | 2013/10-2014/04 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A180DB/<br>DR3V1A180DA |             | BB5T1A180AA/<br>DV6T1A180AA        |
| C0146 | EU | Ford   | Tourneo Courier | 2014/10-2016/06 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A180DB/<br>DR3V1A180DA |             | BB5T1A180BA/<br>BB5T1A180AA        |
| C0147 | EU | Ford   | Tourneo Courier | 2014/03-2014/09 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | DR3V1A180BB                                 |             |                                    |
| C0149 | EU | Ford   | Transit         | 2014/03-2016/06 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | BB5T1A180AA                                 | 90518346    | BB5T1A180AA/<br>BB5T1A180BA        |
| C0150 | EU | Ford   | Transit         | 2013/01-2014/03 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | BB5T1A180AA                                 | 90518346    | BB5T1A180AA/<br>BB5T1A180BA        |
| C0152 | EU | Ford   | Transit Connect | 2014/05-2016/06 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | EV6T1A180CB/<br>EV6T1A180DB/<br>DR3V1A180DA |             | BB5T1A180AA/<br>DV6T1A180AA        |
| C0153 | EU | Ford   | Transit Courier | 2014/02-2016/06 |  | ○ | ● | 4 | S   | 433Mhz | Schrader    | DR3V1A180BB/<br>EV6T1A180CB                 |             |                                    |
| C0155 | EU | GMC    | Sierra          | 2013/04-2019/06 |  | ● | ● | 4 |     | 433Mhz | Schrader    | 22853740                                    | 90518185    | 22853740                           |
| C0156 | EU | GMC    | Yukon           | 2005/01-2015/12 |  | ● | ● | 4 | S   | 433Mhz | Schrader    | 22853740                                    | 90518185    | 22853740                           |
| C0157 | EU | Holden | WM Caprice      | 2007/01-2015/12 |  | ○ | ● | 4 |     | 433Mhz | Schrader    | 25789964                                    | 90518185    | 25789964/<br>22853740/<br>13581561 |
| C0158 | EU | HSV    | ClubSport GXP   | 2010/01-2010/12 |  | ○ | ● | 4 |     | 433Mhz | Schrader    | 25789964/<br>22853740/<br>13581561          | 90518185    | 25789964/<br>22853740/<br>13581561 |
| C0159 | EU | HSV    | Gange           | 2007/01-2012/12 |  | ○ | ● | 4 |     | 433Mhz | Schrader    | 25789964                                    | 90518185    | 25789964/<br>22853740/<br>13581561 |
| C0160 | EU | HSV    | GTS             | 2007/01-2012/12 |  | ○ | ● | 4 |     | 433Mhz | Schrader    | 25789964                                    | 90518185    | 25789964/<br>22853740/<br>13581561 |

|       |    |          |                |                 |  |   |   |     |           |        |             |                                    |                       |                                                |
|-------|----|----------|----------------|-----------------|--|---|---|-----|-----------|--------|-------------|------------------------------------|-----------------------|------------------------------------------------|
| C0161 | EU | HSV      | Maloo GXP      | 2010/01-2010/12 |  | ○ | ● | 4   |           | 433Mhz | Schrader    | 25789964                           | 90518185              | 25789964/<br>22853740/<br>13581561             |
| C0162 | EU | HSV      | R8             | 2007/01-2012/12 |  | ○ | ● | 4   |           | 433Mhz | Schrader    | 25789964                           | 90518185              | 25789964/<br>22853740/<br>13581561             |
| C0163 | EU | HSV      | Senator        | 2007/01-2012/12 |  | ○ | ● | 4   |           | 433Mhz | Schrader    | 25789964                           | 90518185              | 25789964/<br>22853740/<br>13581561             |
| C0164 | EU | Hummer   | H2             | 2002/01-2008/12 |  | ○ | ● | 4   | S         | 433Mhz | Schrader    | 25789964/<br>22853740/<br>13581561 | 90518185              | 25789964/<br>22853740/<br>13581561             |
| C0165 | EU | Hummer   | H3             | 2007/01-2012/12 |  | ● | ● | 4   | S         | 433Mhz | Schrader    | 25789964/<br>22853740/<br>13581561 | 90518185              | 25789964/<br>22853740/<br>13581561             |
| C0166 | EU | Hummer   | H3             | 2005/03-2006/12 |  | ● | ● | 4   | S         | 433Mhz | Schrader    | 25789964/<br>22853740/<br>13581561 | 90518185              | 25789964/<br>22853740/<br>13581561             |
| C0167 | EU | Jeep     | Cherokee       | 2007/01-2013/12 |  | ● | ● | 4/5 |           | 433Mhz | Schrader    | 56029359AC                         |                       | 56029359AC                                     |
| C0168 | EU | Jeep     | Cherokee       | 2014/01-2016/06 |  | ● | ● | 4/5 | A/O       | 433Mhz | TRW         | 68157568AA/<br>68157568AB          |                       | 68239720AA/<br>68157568AB                      |
| C0169 | EU | Jeep     | Commander      | 2006/01-2010/12 |  | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029359AC                         | 90518155/<br>90518434 | 56029359AA-AC/<br>56053031AC/<br>56029481AA-AB |
| C0170 | EU | Jeep     | Compass        | 2011/01-2016/12 |  | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029481AB                         | 90518434              | 56029481AB                                     |
| C0171 | EU | Jeep     | Grand Cherokee | 2011/01-2016/06 |  | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029398AB                         | 90518358              | 56029398AB                                     |
| C0172 | EU | Jeep     | Grand Cherokee | 2006/06-2010/12 |  | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029359AC                         | 90518155/<br>90518434 | 56029359AA-AC/<br>56053031AC/<br>56029481AA-AB |
| C0173 | EU | Jeep     | Liberty        | 2007/01-2015/12 |  | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029481AB                         | 90518434              | 56029481AB                                     |
| C0174 | EU | Jeep     | Liberty        | 2005/01-2009/12 |  | ● | ● | 4/5 | A         | 433Mhz | Continental | 56053031AD                         |                       | 56053031AD                                     |
| C0175 | EU | Jeep     | Patriot        | 2006/12-2016/06 |  | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029481AB                         | 90518434              | 56029481AB                                     |
| C0176 | EU | Jeep     | Renegade       | 2015/01-2016/06 |  | ● | ● | 4/5 | A/O       | 433Mhz | Continental | 53305555                           | S180150008B           | S180150008                                     |
| C0177 | EU | Jeep     | Wrangler       | 2010/09-2016/06 |  | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029398AB                         | 90518358              | 56029398AB                                     |
| C0178 | EU | Jeep     | Wrangler       | 2007/07-2010/08 |  | ● | ● | 4/5 | A         | 433Mhz | Schrader    | 56029359AC                         | 90518155/<br>90518434 | 56029359AA-AC/<br>56053031AC/<br>56029481AA-AB |
| C0179 | EU | Lancia   | Delta          | 2008/01-2014/05 |  | ○ | ● | 4   |           | 433Mhz | TRW         | 51839114                           |                       | 51839114                                       |
| C0180 | EU | Lancia   | Flavia         | 2012/01-2013/12 |  | ○ | ● | 4   | A         | 433Mhz | Continental | 68078768AA                         |                       |                                                |
| C0181 | EU | Lancia   | Flavia         | 2010/10-2011/12 |  | ○ | ● | 4   | Copy only | 433Mhz | Continental | 68078768AA                         |                       |                                                |
| C0183 | EU | Lancia   | Phedra         | 2005/10-2010/12 |  | ○ | ● | 4   |           | 433Mhz | Continental | 9681102280                         | S180014805Z           | S120123004                                     |
| C0184 | EU | Lancia   | Phedra         | 2002/06-2005/09 |  | ○ | ● | 4   | S         | 433Mhz | Schrader    | 9634866180                         | 9634866180            | 9634866180                                     |
| C0185 | EU | Lancia   | Thema          | 2011/01-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 53104671                           | 90518358              | 53104671                                       |
| C0186 | EU | Lancia   | Voyager        | 2011/01-2015/12 |  | ○ | ● | 4   | Copy only | 433Mhz | Schrader    | 53104671                           | 90518358              | 53104671                                       |
| C0187 | EU | Lancia   | Voyager        | 2007/07-2010/12 |  | ○ | ● | 4   |           | 433Mhz | Continental | 68001698AB                         | 90518155/<br>90518434 | 56029359AA-AB/<br>56053031AC/<br>56029481AA-AB |
| C0188 | EU | Lincoln  | Navigator      | 2011/01-2014/12 |  | ● | ● | 4   | S         | 433Mhz | Schrader    | BB5T1A180AA                        | 90518346              | BB5T1A180AA                                    |
| C0189 | EU | Lotus    | Elise          | 2008/01-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 13227143                           | 90518150/<br>90518408 | 13227143/<br>12825085                          |
| C0190 | EU | Lotus    | Evora          | 2010/01-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 13227143                           | 90518150/<br>90518408 | 13227143/<br>12825085                          |
| C0191 | EU | Lotus    | Exige          | 2008/01-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 13227143                           | 90518150/<br>90518408 | 13227143/<br>12825085                          |
| C0192 | EU | Maserati | Coupe          | 2009/07-2013/12 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 228887                             | 532207011             | RDE011                                         |
| C0193 | EU | Maserati | Coupe          | 2002/01-2009/06 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 185189                             | 532207001             | RDE001                                         |
| C0194 | EU | Maserati | Ghibli         | 2013/11-2016/06 |  | ○ | ● | 4   | A         | 433Mhz | Schrader    | 05154876AA                         |                       | 670002790                                      |
| C0195 | EU | Maserati | Grand Cabrio   | 2010/06-2015/12 |  | ○ | ● | 4   | A         | 433Mhz | Huf/Beru    | 282189                             | 532207011             | RDE011                                         |

|       |    |               |                    |                 |  |   |   |   |           |        |             |                             |             |                                    |
|-------|----|---------------|--------------------|-----------------|--|---|---|---|-----------|--------|-------------|-----------------------------|-------------|------------------------------------|
| C0196 | EU | Maserati      | GranTurismo        | 2011/01-2013/12 |  | ○ | ● | 4 | A         | 433Mhz | Huf/Beru    | 282189                      | 532207011   | RDE011                             |
| C0197 | EU | Maserati      | GranTurismo        | 2008/01-2010/12 |  | ○ | ● | 4 | A         | 433Mhz | Huf/Beru    | 224549                      | 532207001   | RDE001                             |
| C0198 | EU | Maserati      | Quattroporte       | 2013/01-2016/06 |  | ○ | ● | 4 |           | 433Mhz | Schrader    | 05154876AA                  |             | 670002790                          |
| C0199 | EU | Maserati      | Quattroporte       | 2010/01-2015/12 |  | ○ | ● | 4 | A         | 433Mhz | Huf/Beru    | 248887                      | 532207011   | RDE011                             |
| C0200 | EU | Maserati      | Quattroporte       | 2004/04-2009/12 |  | ○ | ● | 4 | A         | 433Mhz | Huf/Beru    | 185189                      | 532207001   | RDE001                             |
| C0201 | EU | Mazda         | BT-50              | 2011/05-2016/06 |  | ○ | ● | 4 |           | 433Mhz | Schrader    | BB5T1A180AA/<br>DV6T1A180AA |             |                                    |
| C0202 | EU | Mazda         | CX-3               | 2014/10-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Continental | BBP337140B/<br>BHB637140    |             | S180052018H/<br>S180052054A        |
| C0203 | EU | Mazda         | CX-5               | 2011/11-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Continental | BBP337140B/<br>BHB637140    | S180084720Z | S180052018H/<br>S180052054A        |
| C0204 | EU | Mazda         | CX-7               | 2009/10-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Continental | BBP337140B/<br>BHB637140    | S180084720Z | S180052018H/<br>S180052054A        |
| C0205 | EU | Mazda         | CX-9               | 2006/10-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Continental | BBP337140B/<br>BHB637140    | S180084720Z | S180052018H/<br>S180052054A        |
| C0206 | EU | Mazda         | Mazda 2            | 2007/12-2016/06 |  | ○ | ● | 4 | A         | 433Mhz | Continental | BBP337140B/<br>BHB637140    | S180084720Z | S180052018H/<br>S180052054A        |
| C0207 | EU | Mazda         | Mazda 3            | 2009/06-2014/03 |  | ● | ● | 4 | A         | 433Mhz | Continental | BBP337140B/<br>BHB637140    | S180084720Z | S180052018H/<br>S180052054A        |
| C0208 | EU | Mazda         | Mazda 5            | 2010/01-2016/06 |  | ● | ● | 4 | A         | 433Mhz | Continental | BBP337140B/<br>BHB637140    | S180084720Z | S180052018H/<br>S180052054A        |
| C0209 | EU | Mazda         | Mazda 6            | 2008/02-2016/06 |  | ● | ● | 4 | A         | 433Mhz | Continental | BBP337140B/<br>BHB637140    | S180084720Z | S180052018H/<br>S180052054A        |
| C0210 | EU | Mazda         | MX-5               | 2005/06-2015/03 |  | ● | ● | 4 | A         | 433Mhz | Continental | BBP337140B/<br>BHB637140    | S180084720Z | S180052018H/<br>S180052054A        |
| A0010 | EU | Honda         | Civic              | 2015/01-2015/12 |  | ● | ● | 4 |           | 433Mhz | Continental | 42753TLOG52                 |             |                                    |
| C0216 | EU | Opel/Vauxhall | Adam               | 2015/01-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 13581561                    |             | 13581561                           |
| C0217 | EU | Opel/Vauxhall | Adam S & Rocks S   | 2015/01-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 13581560                    |             | 13581560                           |
| A0011 | EU | Honda         | Jazz               | 2014/11-2016/06 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 42753TLOG52                 | S180052059Z | S180052059                         |
| C0221 | EU | Opel/Vauxhall | Antara             | 2016/01-2016/12 |  | ○ | ● | 4 | 0/S       | 433Mhz | Schrader    | 13598773                    |             | 13589601/<br>13598773              |
| C0223 | EU | Opel/Vauxhall | Antara             | 2010/11-2014/05 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 20922901                    | 90518390    | 20922901                           |
| C0224 | EU | Opel/Vauxhall | Antara             | 2006/01-2010/10 |  | ○ | ● | 4 |           | 433Mhz | Schrader    | 25789964                    |             | 25789964                           |
| C0225 | EU | Opel/Vauxhall | Astra H            | 2004/01-2009/09 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 13354312                    |             | 13354312                           |
| C0226 | EU | Opel/Vauxhall | Astra J            | 2015/01-2015/09 |  | ○ | ● | 4 | 0/S       | 433Mhz | Schrader    | 13581560                    |             | 13581560                           |
| C0227 | EU | Opel/Vauxhall | Astra J            | 2014/06-2014/12 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 13581560                    |             | 13581560                           |
| A0012 | EU | Hyundai       | Accent             | 2014/03-2016/06 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 529331J000                  | S180084710Z | S180052012                         |
| A0013 | EU | Hyundai       | Azera              | 2011/01-2016/06 |  | ● | ● | 4 | 0         | 433Mhz | TRW         | 529333V100                  |             | 52933-3V100                        |
| C0230 | EU | Opel/Vauxhall | Astra K            | 2015/10-2016/12 |  | ○ | ● | 4 | 0/S       | 433Mhz | Schrader    | 13506028                    |             |                                    |
| A0014 | EU | Hyundai       | Elantra            | 2014/01-2016/12 |  | ● | ● | 4 | 0         | 433Mhz | TRW         | 529333X305/<br>529333X306   |             | 52933-3X305                        |
| A0016 | EU | Hyundai       | Equus              | 2014/01-2016/06 |  | ● | ● | 4 | 0         | 433Mhz | TRW         | 529333M000                  |             | 52933-3M000                        |
| C0234 | EU | Opel/Vauxhall | Combo D(15 inch)   | 2011/03-2016/12 |  | ○ | ● | 4 |           | 433Mhz | Schrader    | 53104671                    |             | 53104671                           |
| C0235 | EU | Opel/Vauxhall | Combo D(16 inch)   | 2011/03-2016/12 |  | ○ | ● | 4 |           | 433Mhz | Schrader    | 05154876AA                  |             | 670002790                          |
| C0236 | EU | Opel/Vauxhall | Corsa D            | 2006/01-2014/10 |  | ○ | ● | 4 | A         | 433Mhz | Schrader    | 13581560                    |             | 13581560                           |
| C0237 | EU | Opel/Vauxhall | Corsa E(Non Turbo) | 2014/11-2016/06 |  | ○ | ● | 4 | Copy only | 433Mhz | Schrader    | 13581561                    |             | 13581561                           |
| C0238 | EU | Opel/Vauxhall | Corsa E(Turbo)     | 2014/11-2016/06 |  | ○ | ● | 4 | 0/S       | 433Mhz | Schrader    | 13581560                    |             | 13581560                           |
| A0018 | EU | Hyundai       | Genesis            | 2014/01-2016/06 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 529333N100                  | S180052092Z | S180052092                         |
| A0019 | EU | Hyundai       | Grand SantaFe      | 2013/05-2016/06 |  | ● | ● | 4 | 0         | 433Mhz | Continental | 529333N100                  | S180052092Z | S180052092                         |
| C0243 | EU | Opel/Vauxhall | Karl/Viva          | 2015/01-2016/12 |  | ○ | ● | 4 | 0/S       | 433Mhz | Schrader    | 13589601/<br>13598773       |             |                                    |
| C0244 | EU | Opel/Vauxhall | Meriva B           | 2014/08-2015/12 |  | ○ | ● | 4 | 0/S       | 433Mhz | Schrader    | 13581561                    |             | 13581561                           |
| C0246 | EU | Opel/Vauxhall | Mokka              | 2015/09-2016/06 |  | ● | ● | 4 | 0/S       | 433Mhz | Schrader    | 13598773                    |             |                                    |
| C0247 | EU | Opel/Vauxhall | Mokka              | 2012/01-2015/08 |  | ● | ● | 4 | 0/S       | 433Mhz | Schrader    | 22853740                    |             | 22853740/<br>25789964/<br>13581561 |
| A0021 | EU | Hyundai       | Grandeur           | 2012/01-2016/06 |  | ● | ● | 4 | 0         | 433Mhz | TRW         | 529333V100                  |             | 52933-3V100                        |

|       |    |               |               |                 |        |   |   |   |     |        |             |                                    |                       |                                    |
|-------|----|---------------|---------------|-----------------|--------|---|---|---|-----|--------|-------------|------------------------------------|-----------------------|------------------------------------|
| C0251 | EU | Opel/Vauxhall | Signum        | 2002/08-2009/08 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | PA66CF35                           | 13172567/<br>24437708 | 13172567/<br>24437708              |
| C0252 | EU | Opel/Vauxhall | Vectra        | 2002/08-2008/08 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | PA66CF35                           | 13172567/<br>24437708 | 13172567/<br>24437708              |
| C0253 | EU | Opel/Vauxhall | Vectra Estate | 2009/08-2014/01 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | PA66CF35                           | 13172567<br>/24437708 | 13172567/<br>24437708              |
| C0254 | EU | Opel/Vauxhall | Vectra Estate | 2002/10-2009/07 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | PA66CF35                           | 13172567/<br>24437708 | 13172567/<br>24437708              |
| C0257 | EU | Opel/Vauxhall | Zafira B      | 2014/06-2014/12 |        | ○ | ● | 4 | A/O | 433Mhz | Schrader    | 13581560                           |                       | 13581560                           |
| C0258 | EU | Opel/Vauxhall | Zafira B      | 2004/01-2014/05 |        | ○ | ● | 4 | A/O | 433Mhz | Schrader    | 13354312                           |                       | 13354312                           |
| A0023 | EU | Hyundai       | i10           | 2013/11-2016/06 |        | ● | ● | 4 | O   | 433Mhz | Schrader    | 52933B2100                         | 90518481              | 52933-B2100                        |
| A0024 | EU | Hyundai       | i20           | 2008/09-2014/05 |        | ● | ● | 4 | O   | 433Mhz | Continental | 529331J000                         | S180084710Z           | S180052012                         |
| C0266 | EU | Saab          | 9月3日          | 2009/06-2012/12 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | 13327259                           | 90518407/<br>90515382 | 13348393/<br>13327259              |
| C0267 | EU | Saab          | 9月3日          | 2006/10-2009/05 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | 13227143                           | 90518150/<br>90518408 | 13227143/<br>12825085              |
| C0268 | EU | Saab          | 9月3日          | 2003/01-2006/09 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | 13172567                           | 24437708/<br>13172567 | 13172567                           |
| C0269 | EU | Saab          | 9-4X          | 2011/03-2014/01 |        | ○ | ● | 4 | S   | 433Mhz | Schrader    | 20922901                           | 90518390              | 20922901                           |
| C0270 | EU | Saab          | 9月5日          | 2009/10-2012/12 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | 13327259                           | 90518407/<br>90515382 | 13348393/<br>13327259              |
| C0271 | EU | Saab          | 9月5日          | 2006/11-2009/09 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | 13227143                           | 90518150/<br>90518408 | 13227143/<br>12825085              |
| C0272 | EU | Saab          | 9月5日          | 2003/01-2006/10 |        | ○ | ● | 4 | A   | 433Mhz | Schrader    | 13172567                           | 24437708/<br>13172567 | 13172567                           |
| C0273 | EU | Saab          | 9-7X          | 2007/01-2008/12 |        | ○ | ● | 4 | S   | 433Mhz | Schrader    | 25774007                           | 90518110              | 25774007                           |
| C0274 | EU | Tesla         | Model S       | 2014/10-2016/06 |        | ○ | ● | 4 | A   | 433Mhz | Continental | 103460200A                         | S180052068Z           | S180052068                         |
| C0275 | EU | Tesla         | Model S       | 2013/01-2014/09 |        | ○ | ● | 4 | A   | 433Mhz | Baolong     | FS15I1                             |                       | FS15I1                             |
| C0276 | EU | Tesla         | Roadster      | 2008/03-2010/12 |        | ○ | ● | 4 | A   | 433Mhz | Huf/Beru    | 2000680                            | 532207011             | RDE011                             |
| C0277 | US | Alfa Romeo    | 4C            | 2015/01-2015/12 | 433Mhz | ○ | ● | 4 | A   | 433Mhz | Schrader    | 05154876AA                         |                       | 670002790                          |
| C0278 | US | Alfa Romeo    | Giulia        | 2016/01-2016/12 | 433Mhz | ○ | ● | 4 | A   | 433Mhz | Continental | 68105280AF                         |                       |                                    |
| C0279 | US | Buick         | Allure        | 2011/01-2011/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |                       | 12768826/<br>20922900/<br>22854866 |
| C0280 | US | Buick         | Allure        | 2010/01-2010/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |                       | 12768826/<br>20922900/<br>22854866 |
| C0281 | US | Buick         | Allure        | 2009/01-2009/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |                       | 12768826/<br>20922900/<br>22854866 |
| C0282 | US | Buick         | Allure        | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Continental | 15921013                           | S120123009A           |                                    |
| C0283 | US | Buick         | Allure        | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Continental | 15921013                           | S120123009A           |                                    |
| C0285 | US | Buick         | Enclave       | 2009/01-2015/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 25920615                           |                       | 25920615                           |
| C0286 | US | Buick         | Enclave       | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Continental | 15921013                           | S120123009A           |                                    |
| C0287 | US | Buick         | Encore        | 2013/01-2016/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 22854866                           |                       | 22854866                           |
| C0288 | US | Buick         | Envision      | 2015/01-2016/12 | 315MHz | ○ | ● | 4 |     | 315Mhz | Schrader    | 13589597                           |                       | 13589597                           |
| C0290 | US | Buick         | Excelle 15N   | 2015/01-2016/12 | 433MHz | ○ | ● | 4 | S   | 433Mhz | DIAS        | 26267197                           |                       | 26267197                           |
| C0291 | US | Buick         | Excelle 18T   | 2015/01-2016/12 | 433MHz | ○ | ● | 4 | S   | 433Mhz | Baolong     | FS43X0L0                           |                       | FS43X0L0                           |
| C0292 | US | Buick         | LaCrosse      | 2016/01-2016/12 | 315MHz | ○ | ● | 4 |     | 315Mhz | Schrader    | 13589597                           |                       | 13589597                           |
| C0293 | US | Buick         | LaCrosse      | 2014/01-2015/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |                       | 12768826/<br>20922900/<br>22854866 |
| C0294 | US | Buick         | LaCrosse      | 2013/01-2013/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |                       | 12768826/<br>20922900/<br>22854866 |
| C0295 | US | Buick         | LaCrosse      | 2012/01-2012/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |                       | 12768826/<br>20922900/<br>22854866 |

|       |    |          |                   |                 |        |   |   |   |   |        |             |                                    |             |                                    |
|-------|----|----------|-------------------|-----------------|--------|---|---|---|---|--------|-------------|------------------------------------|-------------|------------------------------------|
| C0296 | US | Buick    | LaCrosse          | 2011/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 12768826/<br>20922900/<br>22854866 |
| C0297 | US | Buick    | LaCrosse          | 2010/01-2010/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 12768826/<br>20922900/<br>22854866 |
| C0298 | US | Buick    | LaCrosse          | 2009/01-2009/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 12768826/<br>20922900/<br>22854866 |
| C0299 | US | Buick    | LaCrosse          | 2007/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0300 | US | Buick    | LeSabre           | 2007/01-2007/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader    | 25799331                           |             | 25799331                           |
| C0302 | US | Buick    | Lucerne           | 2011/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615                           |
| C0303 | US | Buick    | Lucerne           | 2010/01-2010/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615                           |
| C0304 | US | Buick    | Lucerne           | 2009/01-2009/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615                           |
| C0305 | US | Buick    | Lucerne           | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615                           |
| C0306 | US | Buick    | Lucerne           | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615                           |
| C0307 | US | Buick    | Rainier(Clamp in) | 2006/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25774006                           |             | 25774006                           |
| C0308 | US | Buick    | Rainier(Snap in)  | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25799331                           |             | 25799331                           |
| C0309 | US | Buick    | Regal             | 2016/01-2016/12 | 315MHz | ○ | ● | 4 |   | 315Mhz | Schrader    | 13589597                           |             | 13589597                           |
| C0310 | US | Buick    | Regal             | 2013/01-2015/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 12768826/<br>20922900/<br>22854866 |
| C0311 | US | Buick    | Regal             | 2011/01-2012/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 12768826/<br>20922900/<br>22854866 |
| C0314 | US | Buick    | Verano            | 2016/01-2016/12 | 315MHz | ○ | ● | 4 |   | 315Mhz | Schrader    | 13589597                           |             | 13589597                           |
| C0315 | US | Buick    | Verano            | 2012/01-2015/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 12768826/<br>20922900/<br>22854866 |
| C0317 | US | Cadillac | ATS               | 2014/01-2015/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 13581558                           |             | 13581558                           |
| C0318 | US | Cadillac | ATS               | 2013/01-2013/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Continental | 22959744                           |             |                                    |
| C0319 | US | Cadillac | ATS Sport         | 2014/01-2015/12 | 315MHz | ○ | ○ | 4 | S | 315Mhz | Schrader    | 15268606                           |             | 15268606                           |
| C0322 | US | Cadillac | CT6               | 2016/01-2016/12 | 433MHz | ○ | ● | 4 |   | 433Mhz | Schrader    | 13598773                           | 90518185    |                                    |
| C0324 | US | Cadillac | CTS               | 2015/01-2015/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 13581558                           |             | 13581558                           |
| C0325 | US | Cadillac | CTS               | 2013/01-2014/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615                           |
| C0326 | US | Cadillac | CTS               | 2012/01-2012/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615                           |
| C0327 | US | Cadillac | CTS               | 2009/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615/<br>20923680              |
| C0328 | US | Cadillac | CTS               | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615/<br>20923680              |
| C0329 | US | Cadillac | CTS               | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25774006                           |             | 25774006                           |
| C0330 | US | Cadillac | CTS               | 2006/01-2006/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25774006                           |             | 25774006                           |
| C0331 | US | Cadillac | CTS               | 2004/01-2005/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader    | 25774006                           |             | 25774006                           |
| C0333 | US | Cadillac | CTS-V             | 2009/01-2015/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader    | 15268606                           |             | 15268606                           |
| C0336 | US | Cadillac | CTS-V(Sport)      | 2014/01-2014/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader    | 15268606                           |             | 15268606                           |
| C0338 | US | Cadillac | Deville           | 2005/01-2005/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                           |
| C0339 | US | Cadillac | Deville           | 2004/01-2004/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                           |
| C0340 | US | Cadillac | Deville           | 2001/01-2003/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                           |
| C0345 | US | Cadillac | DTS               | 2009/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615/<br>20923680              |
| C0346 | US | Cadillac | DTS               | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615/<br>20923680              |
| C0347 | US | Cadillac | DTS               | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615/<br>20923680              |
| C0348 | US | Cadillac | DTS               | 2006/01-2006/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader    | 15268606                           |             | 15268606                           |
| A0025 | EU | Hyundai  | i20               | 2014/01-2016/06 | GB/IB  | ● | ● | 4 | 0 | 433Mhz | Schrader    | 52933C1100/<br>52933C8000          |             |                                    |

|       |    |           |           |                 |          |   |   |   |   |        |             |                                    |             |                                   |
|-------|----|-----------|-----------|-----------------|----------|---|---|---|---|--------|-------------|------------------------------------|-------------|-----------------------------------|
| C0353 | US | Cadillac  | Escalade  | 2014/01-2016/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 13581558                           |             | 13581558                          |
| C0354 | US | Cadillac  | Escalade  | 2013/01-2013/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 22853741/<br>25799331              |             |                                   |
| C0355 | US | Cadillac  | Escalade  | 2012/01-2012/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 13586335/<br>25799331              |             |                                   |
| C0356 | US | Cadillac  | Escalade  | 2009/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25799331                           |             | 25799331                          |
| C0357 | US | Cadillac  | Escalade  | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25799331                           |             | 25799331                          |
| C0358 | US | Cadillac  | Escalade  | 2007/01-2007/12 | Clamp in | ● | ● | 4 | S | 315Mhz | TRW         | 15825475                           |             |                                   |
| A0026 | EU | Hyundai   | i30       | 2007/01-2012/12 | FD/CW    | ● | ● | 4 | 0 | 433Mhz | Continental | 529332L600/<br>529332L000          | S180014820Z | S180030002                        |
| C0360 | US | Cadillac  | Escalade  | 2005/01-2006/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 15114379                           |             | 15114379                          |
| C0361 | US | Cadillac  | Escalade  | 2004/01-2004/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 15136883                           |             | 15136883                          |
| C0370 | US | Cadillac  | Seville   | 2004/01-2004/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                          |
| C0371 | US | Cadillac  | Seville   | 2001/01-2003/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                          |
| C0377 | US | Cadillac  | SLS       | 2006/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                          |
| C0378 | US | Cadillac  | SRX       | 2016/01-2016/12 | 315MHz   | ○ | ● | 4 |   | 315Mhz | Schrader    | 13589597                           |             | 13589597                          |
| C0379 | US | Cadillac  | SRX       | 2015/01-2015/12 | 433MHz   | ● | ● | 4 | S | 433Mhz | Schrader    | 13581561                           |             | 13581561                          |
| C0380 | US | Cadillac  | SRX       | 2012/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826                           |             | 12768826                          |
| C0381 | US | Cadillac  | SRX       | 2010/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826                           |             | 12768826                          |
| C0382 | US | Cadillac  | SRX       | 2009/01-2009/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25799331                           |             | 25799331                          |
| C0383 | US | Cadillac  | SRX       | 2007/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25799331                           |             | 25799331                          |
| C0384 | US | Cadillac  | SRX       | 2004/01-2006/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25774006                           |             | 25774006                          |
| C0386 | US | Cadillac  | STS       | 2010/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 20923680                           |             | 20923680                          |
| C0387 | US | Cadillac  | STS       | 2009/01-2009/12 | Clamp in | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615                          |
| C0388 | US | Cadillac  | STS       | 2009/01-2009/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                           |             | 25920615                          |
| C0389 | US | Cadillac  | STS       | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                          |
| C0390 | US | Cadillac  | STS       | 2005/01-2007/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                          |
| C0393 | US | Cadillac  | XLR       | 2010/01-2011/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                          |
| C0394 | US | Cadillac  | XLR       | 2006/01-2009/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                          |
| C0395 | US | Cadillac  | XLR       | 2004/01-2005/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                          |
| C0397 | US | Cadillac  | XTS       | 2016/01-2016/12 | 315MHz   | ○ | ● | 4 |   | 315Mhz | Schrader    | 13589597                           |             | 13589597                          |
| C0398 | US | Cadillac  | XTS       | 2015/01-2015/12 | 433MHz   | ● | ● | 4 | S | 433Mhz | Schrader    | 22853740                           | 90518185    | 22853740                          |
| C0399 | US | Cadillac  | XTS       | 2013/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 22854866/<br>20922900/<br>12768826 |             | 22854866<br>20922900/<br>12768826 |
| C0405 | US | Chevrolet | Avalanche | 2012/01-2013/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/20923680                 |
| C0406 | US | Chevrolet | Avalanche | 2009/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/20923680                 |
| C0407 | US | Chevrolet | Avalanche | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/20923680                 |
| C0408 | US | Chevrolet | Avalanche | 2007/01-2007/12 | Clamp in | ● | ● | 4 | S | 315Mhz | TRW         | 15825475                           |             |                                   |
| C0409 | US | Chevrolet | Avalanche | 2007/01-2007/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/20923680                 |
| C0410 | US | Chevrolet | Avalanche | 2005/01-2006/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader    | 15114379                           |             | 15114379                          |
| C0411 | US | Chevrolet | Avalanche | 2004/01-2004/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader    | 15136883                           |             | 15136883                          |
| C0413 | US | Chevrolet | Aveo      | 2008/01-2011/12 | 315MHz   | ● | ● | 4 | A | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/20923680                 |
| C0414 | US | Chevrolet | Aveo      | 2007/01-2007/12 | 315MHz   | ○ | ● | 4 | A | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/20923680                 |
| C0416 | US | Chevrolet | Camaro    | 2016/01-2016/12 | 315MHz   | ○ | ● | 4 |   | 315Mhz | Schrader    | 13589597                           |             | 13589597                          |
| C0417 | US | Chevrolet | Camaro    | 2014/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 22854866<br>20922900/<br>12768826 |
| C0418 | US | Chevrolet | Camaro    | 2012/01-2013/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 22854866<br>20922900/<br>12768826 |

|       |    |           |                 |                 |          |   |   |   |   |        |             |                                    |             |                                    |
|-------|----|-----------|-----------------|-----------------|----------|---|---|---|---|--------|-------------|------------------------------------|-------------|------------------------------------|
| C0419 | US | Chevrolet | Camaro          | 2011/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 22854866<br>20922900/<br>12768826  |
| C0420 | US | Chevrolet | Camaro          | 2010/01-2010/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 22854866<br>20922900/<br>12768826  |
| C0421 | US | Chevrolet | Camaro ZL1      | 2012/01-2016/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader    | 20964159                           |             | 20964159                           |
| C0423 | US | Chevrolet | Caprice         | 2014/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 13581559                           |             | 13581559                           |
| C0424 | US | Chevrolet | Caprice         | 2011/01-2013/12 | 315MHz   | ○ | ○ | 4 | S | 315Mhz | Schrader    | 15268606                           |             | 15268606                           |
| C0428 | US | Chevrolet | Captiva sport   | 2013/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 20964159/<br>22959748              |             | 20964159/<br>22959748              |
| C0429 | US | Chevrolet | Captiva sport   | 2012/01-2012/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 20964159/<br>22959748              |             | 20964159/<br>22959748              |
| C0431 | US | Chevrolet | Cheyenne        | 2014/01-2014/12 | Snap in  | ● | ● | 4 |   | 315Mhz | Schrader    | 13581558                           |             | 13581558                           |
| C0436 | US | Chevrolet | Cobalt          | 2010/01-2010/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 22854866/<br>20922900/<br>12768826 |             | 22854866<br>20922900/<br>12768826  |
| C0437 | US | Chevrolet | Cobalt          | 2009/01-2009/12 | Clamp in | ● | ● | 4 | S | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0438 | US | Chevrolet | Cobalt          | 2009/01-2009/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/20923680                  |
| C0439 | US | Chevrolet | Cobalt          | 2008/01-2008/12 | Clamp in | ● | ● | 4 | S | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0440 | US | Chevrolet | Cobalt          | 2008/01-2008/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/20923680                  |
| C0441 | US | Chevrolet | Colorado        | 2015/01-2016/12 | Snap in  | ○ | ● | 4 | S | 315Mhz | Schrader    | 13581558                           |             | 13581558                           |
| C0442 | US | Chevrolet | Colorado        | 2012/01-2012/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 15122618                           |             | 15122618                           |
| C0443 | US | Chevrolet | Colorado        | 2011/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 15122618                           |             | 15122618                           |
| C0444 | US | Chevrolet | Colorado        | 2007/01-2010/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 15122618                           |             | 15122618                           |
| C0445 | US | Chevrolet | Corvette        | 2014/01-2016/12 | 433MHz   | ● | ● | 4 | A | 433Mhz | Schrader    | 13581560                           |             | 13581560                           |
| C0446 | US | Chevrolet | Corvette        | 2013/01-2013/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 20925924                           |             | 20925924                           |
| C0447 | US | Chevrolet | Corvette        | 2012/01-2012/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 20925924                           |             | 20925924                           |
| C0448 | US | Chevrolet | Corvette        | 2010/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 15268606                           |             | 15268606                           |
| C0449 | US | Chevrolet | Corvette        | 2006/01-2009/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                           |
| C0450 | US | Chevrolet | Corvette        | 2005/01-2005/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                           |
| C0451 | US | Chevrolet | Corvette        | 2003/01-2004/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                           |
| C0452 | US | Chevrolet | Corvette        | 2001/01-2002/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                           |
| C0453 | US | Chevrolet | Corvette        | 1997/01-2000/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader    | 10438853                           |             | 10438853                           |
| C0454 | US | Chevrolet | Corvette C5     | 2003/01-2004/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                           |
| C0455 | US | Chevrolet | Corvette C5     | 2001/01-2002/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                           |
| C0456 | US | Chevrolet | Corvette C6     | 2005/01-2009/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                           |
| C0457 | US | Chevrolet | Corvette Z06    | 2012/01-2012/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 20925924                           |             | 20925924                           |
| C0458 | US | Chevrolet | Corvette Z06    | 2010/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 15268606                           |             | 15268606                           |
| C0459 | US | Chevrolet | Corvette Z06    | 2005/01-2009/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25758220                           |             | 25758220                           |
| C0460 | US | Chevrolet | Corvette Z06    | 2003/01-2004/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                           |
| C0461 | US | Chevrolet | Corvette Z06    | 2001/01-2002/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25773946                           |             | 25773946                           |
| C0462 | US | Chevrolet | Cruze           | 2012/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 20922900/<br>12768826/<br>22854866 |             | 20922900                           |
| C0463 | US | Chevrolet | Cruze           | 2011/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 20922900/<br>12768826/<br>22854866 |             | 20922900                           |
| C0465 | US | Chevrolet | Cruze (Limited) | 2016/01-2016/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader    | 13589597                           |             | 13589597                           |
| C0466 | US | Chevrolet | Equinox         | 2016/01-2016/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader    | 13589597                           |             | 13589597                           |
| C0467 | US | Chevrolet | Equinox         | 2012/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 12768826/<br>20922900/<br>22854866 |

|       |    |           |                |                 |          |   |   |   |   |        |             |                                                              |             |                                    |
|-------|----|-----------|----------------|-----------------|----------|---|---|---|---|--------|-------------|--------------------------------------------------------------|-------------|------------------------------------|
| C0468 | US | Chevrolet | Equinox        | 2010/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866                           |             | 12768826/<br>20922900/<br>22854866 |
| C0469 | US | Chevrolet | Equinox        | 2009/01-2009/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Continental | 15921013                                                     | S120123009A |                                    |
| C0470 | US | Chevrolet | Equinox        | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Continental | 15921013                                                     | S120123009A |                                    |
| C0471 | US | Chevrolet | Equinox        | 2007/01-2007/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Continental | 15921013                                                     | S120123009A |                                    |
| C0472 | US | Chevrolet | Express Series | 2012/01-2016/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680/<br>13586335                           |             | 25920615/<br>20923680/<br>13586335 |
| C0473 | US | Chevrolet | Express Series | 2010/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680/<br>13586335                           |             | 25920615/<br>20923680/<br>13586335 |
| C0474 | US | Chevrolet | Express Series | 2009/01-2009/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Continental | 20923680/<br>25920615/<br>15921013                           | S120123009A |                                    |
| C0475 | US | Chevrolet | Express Series | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Continental | 20923680/<br>25920615/<br>15921013                           | S120123009A |                                    |
| C0476 | US | Chevrolet | G Series       | 2008/01-2011/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Continental | 15921013                                                     | S120123009A |                                    |
| C0478 | US | Chevrolet | HHR            | 2010/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615                                                     |             | 25920615                           |
| C0479 | US | Chevrolet | HHR            | 2009/01-2009/12 | Clamp in | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>13586335                                        |             | 25920615/<br>13586335              |
| C0480 | US | Chevrolet | HHR            | 2009/01-2009/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader    | 20923680/<br>25920615/<br>13586335/<br>15254101/<br>25799331 |             | 20923680                           |
| C0481 | US | Chevrolet | HHR            | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>13586335                                        |             | 25920615/<br>13586335              |
| C0484 | US | Chevrolet | Impala         | 2016/01-2016/12 | 315MHz   | ○ | ● | 4 |   | 315Mhz | Schrader    | 13589597                                                     |             | 13589597                           |
| C0485 | US | Chevrolet | Impala         | 2014/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680                                        |             | 25920615/<br>20923680              |
| C0486 | US | Chevrolet | Impala         | 2013/01-2013/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680                                        |             | 25920615/<br>20923680              |
| C0487 | US | Chevrolet | Impala         | 2012/01-2012/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680                                        |             | 25920615/<br>20923680              |
| C0488 | US | Chevrolet | Impala         | 2009/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680                                        |             | 25920615/<br>20923680              |
| C0489 | US | Chevrolet | Impala         | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680                                        |             | 25920615/<br>20923680              |
| C0490 | US | Chevrolet | Impala         | 2007/01-2007/12 | Clamp in | ● | ● | 4 | S | 315Mhz | Schrader    | 15268606                                                     |             | 15268606                           |
| C0491 | US | Chevrolet | Impala         | 2007/01-2007/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680/<br>13586335                           |             | 25920615/<br>20923680/<br>13586335 |
| C0492 | US | Chevrolet | Impala         | 2006/01-2006/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 15268606                                                     |             | 20923680                           |
| C0494 | US | Chevrolet | Malibu         | 2016/01-2016/12 | 315MHz   | ○ | ● | 4 |   | 315Mhz | Schrader    | 13589597                                                     |             | 13589597                           |
| C0495 | US | Chevrolet | Malibu         | 2014/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 22854866/<br>20922900/<br>12768826                           |             | 22854866/<br>20922900/<br>12768826 |
| C0496 | US | Chevrolet | Malibu         | 2012/01-2013/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 22854866/<br>20922900/<br>12768826                           |             | 22854866/<br>20922900/<br>12768826 |
| C0497 | US | Chevrolet | Malibu         | 2010/01-2011/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680                                        |             | 25920615/<br>20923680              |
| C0498 | US | Chevrolet | Malibu         | 2009/01-2009/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680                                        |             | 25920615/<br>20923680              |
| C0499 | US | Chevrolet | Malibu         | 2008/01-2008/12 | Clamp in | ● | ● | 4 | S | 315Mhz | Continental | 15921013                                                     | S120123009A |                                    |
| C0500 | US | Chevrolet | Malibu         | 2008/01-2008/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680                                        |             | 25920615/<br>20923680              |

|       |    |           |             |                 |          |   |   |   |   |        |          |                                                              |  |                                    |
|-------|----|-----------|-------------|-----------------|----------|---|---|---|---|--------|----------|--------------------------------------------------------------|--|------------------------------------|
| C0504 | US | Chevrolet | Monte Carlo | 2007/01-2007/12 | Clamp in | ● | ● | 4 | S | 315Mhz | Schrader | 15268606                                                     |  | 15268606                           |
| C0505 | US | Chevrolet | Monte Carlo | 2007/01-2007/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader | 20923680/<br>25920615/<br>13586335/<br>15254101/<br>25799331 |  | 20923680                           |
| C0507 | US | Chevrolet | Monte Carlo | 2006/01-2006/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 15268606                                                     |  | 15268606                           |
| C0510 | US | Chevrolet | Orlando     | 2012/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 22854866/<br>20922900/<br>12768826                           |  | 22854866<br>20922900/<br>12768826  |
| C0511 | US | Chevrolet | Silverado   | 2014/01-2016/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 13581558                                                     |  | 13581558                           |
| C0512 | US | Chevrolet | Silverado   | 2009/01-2013/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 25920615/<br>20923680                                        |  | 25920615/<br>20923680              |
| C0513 | US | Chevrolet | Silverado   | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 25920615/<br>20923680                                        |  | 25920615/<br>20923680              |
| C0514 | US | Chevrolet | Silverado   | 2007/01-2007/12 | Clamp in | ● | ● | 4 | S | 315Mhz | TRW      | 15825475                                                     |  |                                    |
| C0515 | US | Chevrolet | Silverado   | 2007/01-2007/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader | 20923680/<br>25920615/<br>13586335/<br>15254101/<br>25799331 |  | 20923680                           |
| C0516 | US | Chevrolet | Silverado   | 2005/01-2006/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 15114379                                                     |  | 15114379                           |
| C0517 | US | Chevrolet | Silverado   | 2004/01-2004/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 15136883                                                     |  | 15136883                           |
| C0520 | US | Chevrolet | Sonic       | 2012/01-2016/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 12768826/<br>20922900/<br>22854866                           |  | 12768826/<br>20922900/<br>22854866 |
| C0521 | US | Chevrolet | Spark       | 2016/01-2016/12 | 315MHz   | ○ | ● | 4 |   | 315Mhz | Schrader | 13589597                                                     |  | 13589597                           |
| C0522 | US | Chevrolet | Spark       | 2013/01-2016/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 22854866/<br>20922900/<br>12768826                           |  | 22854866<br>20922900/<br>12768826  |
| C0525 | US | Chevrolet | SS          | 2014/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 20964159                                                     |  | 20964159                           |
| C0526 | US | Chevrolet | SSR         | 2006/01-2007/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader | 25774006                                                     |  | 25774006                           |
| C0527 | US | Chevrolet | Suburban    | 2016/01-2016/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader | 13581558                                                     |  | 13581558                           |
| C0528 | US | Chevrolet | Suburban    | 2014/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 25920615/<br>20923680                                        |  | 25920615/<br>20923680              |
| C0529 | US | Chevrolet | Suburban    | 2009/01-2013/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 25920615/<br>20923680                                        |  | 25920615/<br>20923680              |
| C0530 | US | Chevrolet | Suburban    | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 25920615/<br>20923680                                        |  | 25920615/<br>20923680              |
| C0531 | US | Chevrolet | Suburban    | 2007/01-2007/12 | Clamp in | ● | ● | 4 | S | 315Mhz | TRW      | 15825475                                                     |  |                                    |
| C0532 | US | Chevrolet | Suburban    | 2007/01-2007/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader | 20923680/<br>25920615/<br>13586335/<br>15254101/<br>25799331 |  | 20923680                           |
| C0533 | US | Chevrolet | Suburban    | 2005/01-2006/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader | 15114379                                                     |  | 15114379                           |
| C0534 | US | Chevrolet | Suburban    | 2004/01-2004/12 | 315MHz   | ○ | ● | 4 | S | 315Mhz | Schrader | 15136883                                                     |  | 15136883                           |
| C0536 | US | Chevrolet | Tahoe       | 2014/01-2015/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 25920615/<br>20923680                                        |  | 25920615/<br>20923680              |
| C0537 | US | Chevrolet | Tahoe       | 2009/01-2013/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 25920615/<br>20923680                                        |  | 25920615/<br>20923680              |
| C0538 | US | Chevrolet | Tahoe       | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S | 315Mhz | Schrader | 25920615/<br>20923680                                        |  | 25920615/<br>20923680              |
| C0539 | US | Chevrolet | Tahoe       | 2007/01-2007/12 | Clamp in | ● | ● | 4 | S | 315Mhz | TRW      | 15825475                                                     |  |                                    |
| C0540 | US | Chevrolet | Tahoe       | 2007/01-2007/12 | Snap in  | ● | ● | 4 | S | 315Mhz | Schrader | 20923680/<br>25920615/<br>13586335/<br>15254101/<br>25799331 |  | 20923680                           |

|       |    |           |             |                 |        |   |   |     |     |        |             |                                                              |  |                                                         |
|-------|----|-----------|-------------|-----------------|--------|---|---|-----|-----|--------|-------------|--------------------------------------------------------------|--|---------------------------------------------------------|
| C0541 | US | Chevrolet | Tahoe       | 2005/01-2006/12 | 315MHz | ○ | ● | 4   | S   | 315Mhz | Schrader    | 15114379                                                     |  | 15114379                                                |
| C0542 | US | Chevrolet | Tahoe       | 2004/01-2004/12 | 315MHz | ○ | ● | 4   | S   | 315Mhz | Schrader    | 15136883                                                     |  | 15136883                                                |
| C0545 | US | Chevrolet | Trailblazer | 2007/01-2015/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Schrader    | 25774006                                                     |  | 25774006                                                |
| C0546 | US | Chevrolet | Trailblazer | 2006/01-2006/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Schrader    | 25774006                                                     |  | 25774006                                                |
| C0547 | US | Chevrolet | Traverse    | 2016/01-2016/12 | 315MHz | ○ | ● | 4   | S   | 315Mhz | Schrader    | 13581558                                                     |  | 13581558                                                |
| C0548 | US | Chevrolet | Traverse    | 2014/01-2015/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Schrader    | 25920615/<br>20923680                                        |  | 25920615/<br>20923680                                   |
| C0549 | US | Chevrolet | Traverse    | 2009/01-2013/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Schrader    | 25920615/<br>20923680                                        |  | 25920615/20923680                                       |
| C0550 | US | Chevrolet | Trax        | 2016/01-2016/12 | 315MHz | ○ | ● | 4   |     | 315Mhz | Schrader    | 13589597                                                     |  | 13589597                                                |
| C0551 | US | Chevrolet | Trax        | 2013/01-2015/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Schrader    | 22854866                                                     |  | 22854866                                                |
| C0552 | US | Chevrolet | Uplander    | 2008/01-2009/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Schrader    | 15268606                                                     |  | 15268606                                                |
| C0553 | US | Chevrolet | Volt        | 2016/01-2016/12 | 315MHz | ○ | ● | 4   |     | 315Mhz | Schrader    | 13589597                                                     |  | 13589597                                                |
| C0554 | US | Chevrolet | Volt        | 2014/01-2016/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866/                          |  | 12768826/<br>20922900/<br>22854866/                     |
| C0555 | US | Chevrolet | Volt        | 2012/01-2013/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866/                          |  | 12768826/<br>20922900/<br>22854866/                     |
| C0556 | US | Chevrolet | Volt        | 2011/01-2011/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866/                          |  | 12768826/<br>20922900/<br>22854866/                     |
| C0557 | US | Chevrolet | Volt        | 2010/01-2010/12 | 315MHz | ○ | ● | 4   | S   | 315Mhz | Schrader    | 20923680/<br>25920615/<br>13586335/<br>15254101/<br>25799331 |  | 20923680                                                |
| C0558 | US | Chrysler  | 200         | 2015/01-2015/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Continental | 68193586AC                                                   |  | 68193586AC                                              |
| C0559 | US | Chrysler  | 200         | 2011/01-2014/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 68001696AB                                                   |  | 68001696AA/<br>68001696AB                               |
| C0560 | US | Chrysler  | 300         | 2011/01-2015/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029400AB                                                   |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0561 | US | Chrysler  | 300         | 2010/01-2010/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029400AB                                                   |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0562 | US | Chrysler  | 300         | 2009/01-2009/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029400AB                                                   |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0563 | US | Chrysler  | 300         | 2008/01-2008/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Continental | 68001698AB                                                   |  |                                                         |
| C0564 | US | Chrysler  | 300         | 2007/01-2007/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 68111696AA                                                   |  |                                                         |
| C0565 | US | Chrysler  | 300         | 2007/01-2007/12 | 433MHz | ● | ● | 4/5 | A/O | 433Mhz | Continental | 68078768AA                                                   |  |                                                         |
| C0566 | US | Chrysler  | 300         | 2005/01-2006/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 68111696AA                                                   |  |                                                         |
| C0567 | US | Chrysler  | 300 SRT     | 2010/01-2014/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029400AE                                                   |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0568 | US | Chrysler  | 300C        | 2014/01-2015/12 | 433MHz | ● | ● | 4/5 | S   | 433Mhz | Schrader    | 56029400AE                                                   |  | 56029400AE                                              |
| C0569 | US | Chrysler  | 300M        | 2002/01-2004/12 | 433MHz | ● | ● | 4/5 | S   | 433Mhz | Schrader    | 52088990AC/<br>52088990AD                                    |  | 52088990AD/<br>52088990AC                               |
| C0570 | US | Chrysler  | Aspen       | 2008/01-2011/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Schrader    | 56029465AB                                                   |  | 56029465AB                                              |
| C0571 | US | Chrysler  | Aspen       | 2007/01-2007/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 68001696AB                                                   |  | 68001696AA/<br>68001696AB                               |
| C0572 | US | Chrysler  | Concorde    | 2002/01-2004/12 | 433MHz | ● | ● | 4/5 | S   | 433Mhz | Schrader    | 52088990AC/<br>52088990AD                                    |  | 52088990AD/<br>52088990AC                               |

|       |    |          |                |                 |        |   |   |     |   |        |             |                           |  |                                                         |
|-------|----|----------|----------------|-----------------|--------|---|---|-----|---|--------|-------------|---------------------------|--|---------------------------------------------------------|
| C0573 | US | Chrysler | Crossfire      | 2005/01-2011/12 | 315MHz | ● | ● | 4/5 | 0 | 315Mhz | Continental | 68001696AB                |  | 68001696AA/<br>68001696AB                               |
| C0574 | US | Chrysler | Crossfire      | 2005/01-2011/12 | 433MHz | ● | ● | 4/5 | 0 | 433Mhz | Schrader    | 52088990AD                |  | 52088990AD                                              |
| C0575 | US | Chrysler | Crossfire      | 2004/01-2004/12 | 433MHz | ● | ● | 4/5 | 0 | 433Mhz | Schrader    | 52088990AC/<br>52088990AD |  | 52088990AD/<br>52088990AC                               |
| C0576 | US | Chrysler | Intrepid       | 2002/01-2004/12 | 433MHz | ● | ● | 4/5 | S | 433Mhz | Schrader    | 52088990AC/<br>52088990AD |  | 52088990AD/<br>52088990AC                               |
| C0577 | US | Chrysler | Pacifica       | 2006/01-2008/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AA/<br>68001696AB |  | 68001696AA/<br>68001696AB                               |
| C0578 | US | Chrysler | Pacifica       | 2004/01-2005/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 04727392AB/<br>5127335AE  |  |                                                         |
| C0579 | US | Chrysler | Pacifica       | 2004/01-2004/12 | 433MHz | ● | ● | 4/5 | S | 433Mhz | Schrader    | 52088990AC                |  | 52088990AC                                              |
| C0580 | US | Chrysler | Pacifica       | 2003/01-2003/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 52088990AD                |  | 52088990AD/<br>52088990AE                               |
| C0581 | US | Chrysler | Prowler        | 2002/01-2002/12 | 433MHz | ● | ● | 4/5 | 0 | 433Mhz | Schrader    | 52088990AC/<br>52088990AD |  | 52088990AD/<br>52088990AC                               |
| C0582 | US | Chrysler | PT Cruiser     | 2008/01-2010/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AA/<br>68001696AB |  | 68001696AA/<br>68001696AB                               |
| C0583 | US | Chrysler | Sebring        | 2008/01-2011/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AB                |  | 68001696AA/<br>68001696AB                               |
| C0584 | US | Chrysler | Sebring        | 2008/01-2009/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Continental | 68078768AA                |  |                                                         |
| C0585 | US | Chrysler | Sebring        | 2007/01-2007/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AB                |  | 68001696AA/<br>68001696AB                               |
| C0586 | US | Chrysler | Town & Country | 2011/01-2015/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AB                |  | 56029398AB                                              |
| C0588 | US | Chrysler | Town & Country | 2008/01-2010/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Continental | 68078768AA                |  |                                                         |
| C0589 | US | Chrysler | Town & Country | 2006/01-2008/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AB                |  | 68001696AA/<br>68001696AB                               |
| C0590 | US | Chrysler | Town & Country | 2004/01-2005/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 04727392AB                |  | 04727392AB/<br>5127335AE                                |
| C0591 | US | Chrysler | Town & Country | 2002/01-2003/12 | 433MHz | ● | ● | 4/5 | S | 433Mhz | Schrader    | 52088990AC                |  | 52088990AD/<br>52088990AC                               |
| C0592 | US | Chrysler | Voyager        | 2002/01-2003/12 | 433MHz | ● | ● | 4/5 | S | 433Mhz | Schrader    | 52088990AC/<br>52088990AD |  | 52088990AD/<br>52088990AC                               |
| C0593 | US | Dodge    | Avenger        | 2007/01-2014/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 56053030AB                |  | 56053030AC/<br>56053030AB                               |
| C0594 | US | Dodge    | C/V            | 2013/01-2014/12 | 433MHz | ○ | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AB                |  | 56029398AB                                              |
| C0595 | US | Dodge    | C/V            | 2012/01-2012/12 | 433MHz | ○ | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AA                |  | 56029398AA                                              |
| C0596 | US | Dodge    | Caliber        | 2011/01-2012/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 56053030AB                |  | 56053030AC/<br>56053030AB                               |
| C0597 | US | Dodge    | Caliber        | 2010/01-2010/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 56053030AB                |  | 56053030AC/<br>56053030AB                               |
| C0598 | US | Dodge    | Caliber        | 2008/01-2009/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 56053030AB                |  | 56053030AC/<br>56053030AB                               |
| C0599 | US | Dodge    | Caliber        | 2007/01-2007/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 56053030AB                |  | 56053030AC/<br>56053030AB                               |
| C0600 | US | Dodge    | Caravan        | 2006/01-2007/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 56053030AB/<br>56053030AC |  | 56053030AC/<br>56053030AB                               |
| C0601 | US | Dodge    | Caravan        | 2004/01-2005/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 04727392AB/<br>5127335AE  |  |                                                         |
| C0602 | US | Dodge    | Caravan        | 2002/01-2003/12 | 433MHz | ● | ● | 4/5 | S | 433Mhz | Schrader    | 52088990AC/<br>52088990AD |  | 52088990AD/<br>52088990AC                               |
| C0603 | US | Dodge    | Challenger     | 2011/01-2015/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AA                |  | 56029398AA                                              |
| C0604 | US | Dodge    | Challenger     | 2010/01-2010/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AA                |  | 56029398AA                                              |
| C0605 | US | Dodge    | Challenger     | 2009/01-2009/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AA                |  | 56029398AA                                              |
| C0606 | US | Dodge    | Challenger     | 2008/01-2008/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029400AD                |  | 56029400AD                                              |
| C0607 | US | Dodge    | Charger        | 2011/01-2015/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029400AE                |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |

|       |    |       |               |                 |         |   |   |     |   |        |             |                           |  |                                                         |
|-------|----|-------|---------------|-----------------|---------|---|---|-----|---|--------|-------------|---------------------------|--|---------------------------------------------------------|
| C0608 | US | Dodge | Charger       | 2010/01-2010/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029400AE                |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0609 | US | Dodge | Charger       | 2009/01-2009/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029400AE                |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0610 | US | Dodge | Charger       | 2008/01-2008/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Continental | 68001698AB                |  |                                                         |
| C0611 | US | Dodge | Charger       | 2007/01-2007/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AB                |  | 68001696AA/<br>68001696AB                               |
| C0612 | US | Dodge | Charger       | 2005/01-2006/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AB                |  | 68001696AA/<br>68001696AB                               |
| C0614 | US | Dodge | Charger SRT   | 2010/01-2010/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029400AE                |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0615 | US | Dodge | Charger SRT   | 2009/01-2009/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029400AE                |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0616 | US | Dodge | Dakota        | 2011/01-2011/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Schrader    | 56029479AA                |  | 56029479AA                                              |
| C0617 | US | Dodge | Dakota        | 2008/01-2010/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Schrader    | 56029319AC                |  | 56029319AC/<br>56029319AB/<br>56029319AA                |
| C0618 | US | Dodge | Dart          | 2012/10-2015/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Continental | 68105280AD/<br>68193586AA |  |                                                         |
| C0619 | US | Dodge | Durango       | 2011/01-2015/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AB/<br>56029398AA |  | 56029398AB/<br>56029398AA                               |
| C0620 | US | Dodge | Durango       | 2009/01-2010/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Schrader    | 56029465AB                |  | 56029465AB                                              |
| C0621 | US | Dodge | Durango       | 2007/01-2008/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Continental | 56053030AC                |  | 56053030AC/<br>56053030AB                               |
| C0622 | US | Dodge | Grand Caravan | 2011/01-2015/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AB/<br>56029398AA |  | 56029398AB/<br>56029398AA                               |
| C0623 | US | Dodge | Grand Caravan | 2008/01-2010/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Continental | 68078768AA                |  | 68078768AA                                              |
| C0624 | US | Dodge | Grand Caravan | 2006/01-2007/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Continental | 56053030AC                |  | 56053030AC/<br>56053030AB                               |
| C0625 | US | Dodge | Grand Caravan | 2004/01-2005/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Continental | 04727392AB/<br>5127335AE  |  |                                                         |
| C0626 | US | Dodge | Grand Caravan | 2002/01-2003/12 | 433MHz  | ● | ● | 4/5 | S | 433Mhz | Schrader    | 52088990AC/<br>52088990AD |  | 52088990AD/<br>52088990AC                               |
| C0627 | US | Dodge | Intrepid      | 2002/01-2004/12 | 433MHz  | ● | ● | 4/5 | S | 433Mhz | Schrader    | 52088990AC/<br>52088990AD |  | 52088990AD/<br>52088990AC                               |
| C0628 | US | Dodge | Journey       | 2011/01-2015/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AB/<br>56029398AA |  | 56029398AB/<br>56029398AA                               |
| C0629 | US | Dodge | Journey       | 2010/01-2010/12 | Lo Line | ● | ● | 4/5 | A | 433Mhz | Continental | 68001698AB                |  | 68001698AB                                              |
| C0630 | US | Dodge | Journey       | 2010/01-2010/12 | Hi line | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AA                |  | 56029398AA                                              |
| C0631 | US | Dodge | Journey       | 2009/01-2009/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Continental | 68001698AB                |  | 68001698AB                                              |
| C0632 | US | Dodge | Magnum        | 2011/01-2011/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 68241067AB                |  | 68241067AB                                              |
| C0633 | US | Dodge | Magnum        | 2010/01-2010/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 68241067AB                |  | 68241067AB                                              |
| C0634 | US | Dodge | Magnum        | 2009/01-2009/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029400AE                |  | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0635 | US | Dodge | Magnum        | 2008/01-2008/12 | 433MHz  | ● | ● | 4/5 | A | 433Mhz | Continental | 68001698AB                |  |                                                         |
| C0636 | US | Dodge | Magnum        | 2007/01-2007/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AB                |  | 68001696AA/<br>68001696AB                               |
| C0637 | US | Dodge | Magnum        | 2005/01-2006/12 | 315MHz  | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AB                |  | 68001696AA/<br>68001696AB                               |

|       |    |         |                |                 |        |   |   |     |   |        |             |                                          |                                          |                                                         |
|-------|----|---------|----------------|-----------------|--------|---|---|-----|---|--------|-------------|------------------------------------------|------------------------------------------|---------------------------------------------------------|
| C0638 | US | Dodge   | Nitro          | 2009/01-2012/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Schrader    | 56029465AB                               |                                          | 56029465AB                                              |
| C0639 | US | Dodge   | Nitro          | 2007/01-2008/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AB                               |                                          | 68001696AA/<br>68001696AB                               |
| C0641 | US | Dodge   | Ram            | 2014/01-2015/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | TRW         | 68157568AB/<br>68239720AB/<br>68239720AA | 231008-109/<br>231008-109/<br>231008-101 | 68239720AA/<br>68157568AB                               |
| C0642 | US | Dodge   | Ram            | 2011/01-2013/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AB/<br>56029398AA                |                                          | 56029398AB/<br>56029398AA                               |
| C0643 | US | Dodge   | Ram            | 2010/01-2010/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029398AB/<br>56029398AA                |                                          | 56029398AB/<br>56029398AA                               |
| C0644 | US | Dodge   | Ram            | 2009/01-2009/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029359AC                               |                                          | 56029359AC/<br>56029359AB/<br>56029359AA/               |
| C0645 | US | Dodge   | Ram            | 2008/01-2009/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Schrader    | 56029319AC                               |                                          | 56029319AC/<br>56029319AB/<br>56029319AA                |
| C0646 | US | Dodge   | Ram 2500       | 2009/01-2009/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Schrader    | 56029319AC                               |                                          | 56029319AC/<br>56029319AB/<br>56029319AA                |
| C0647 | US | Dodge   | Ram Cargo      | 2015/01-2015/12 | 433Mhz | ○ | ● | 4/5 |   | 433Mhz | Schrader    | 56029398AB                               |                                          |                                                         |
| C0648 | US | Dodge   | Ram Pro Master | 2014/01-2016/12 | 433MHz | ○ | ● | 4/5 | A | 433Mhz | Schrader    | 05154876AA                               |                                          |                                                         |
| C0649 | US | Dodge   | Sprinter       | 2007/01-2013/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 68038945AA                               |                                          |                                                         |
| C0650 | US | Dodge   | Stratus        | 2007/01-2007/12 | 315MHz | ● | ● | 4/5 | A | 315Mhz | Continental | 68001696AB                               |                                          | 68001696AA/<br>68001696AB                               |
| C0651 | US | Dodge   | viper          | 2013/01-2015/12 | 433MHz | ● | ● | 4/5 | A | 433Mhz | Schrader    | 56029400AE                               |                                          | 56029400AE/<br>56029400AD/<br>56029400AC/<br>56029400AB |
| C0652 | US | Dodge   | Viper          | 2003/01-2010/12 | 433MHz | ● | ● | 4/5 | 0 | 433Mhz | Schrader    | 52088990AC/<br>52088990AD                |                                          | 52088990AD/<br>52088990AC                               |
| C0653 | US | Ferrari | 458            | 2010/01-2015/12 | 433Mhz | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 282189                                   | 532207011                                | RDE011                                                  |
| C0654 | US | Ferrari | 550 Maranello  | 2010/01-2012/12 | 433MHz | ○ | ● | 4   |   | 433Mhz | Huf/Beru    | 224549                                   | 532207001                                | RDE001                                                  |
| C0655 | US | Ferrari | 599            | 2004/01-2011/12 | 433MHz | ○ | ● | 4   | S | 433Mhz | Huf/Beru    | 224549                                   | 532207001                                | RDE001                                                  |
| C0656 | US | Ferrari | 612 Scaglietti | 2004/01-2011/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 224549                                   | 532207001                                | RDE001                                                  |
| C0657 | US | Ferrari | California     | 2015/01-2016/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 282189                                   | 532207011                                | RDE011                                                  |
| C0658 | US | Ferrari | California     | 2008/01-2014/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 248887                                   | 532207011                                | RDE011                                                  |
| C0659 | US | Ferrari | Enzo           | 2003/01-2003/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 224551                                   | 532207005                                | RDE005                                                  |
| C0660 | US | Ferrari | F12 Berlinetta | 2012/10-2015/12 | 433Mhz | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 282189                                   | 532207011                                | RDE011                                                  |
| C0661 | US | Ferrari | FF             | 2011/06-2015/12 | 433Mhz | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 282189                                   | 532207011                                | RDE011                                                  |
| C0662 | US | Ferrari | Spider         | 2002/01-2009/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Huf/Beru    | 224549                                   | 532207001                                | RDE001                                                  |
| C0663 | US | Fiat    | 500            | 2011/01-2015/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Schrader    | 56029398AB/<br>56029398AA                |                                          | 56029398AB/<br>56029398AA                               |
| C0664 | US | Fiat    | 500C           | 2015/01-2015/12 | 433MHz | ○ | ● | 4   |   | 433Mhz | Schrader    | 68241067AB                               |                                          | 68241067AB                                              |
| C0665 | US | Fiat    | 500E           | 2015/01-2015/12 | 433MHz | ○ | ● | 4   |   | 433Mhz | Schrader    | 68241067AB                               |                                          | 68241067AB                                              |
| C0666 | US | Fiat    | 500L           | 2014/01-2015/12 | 433MHz | ○ | ● | 4   | A | 433Mhz | Schrader    | 56029398AB                               |                                          | 56029398AB                                              |
| C0667 | US | Ford    | C-Max          | 2013/01-2016/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Schrader    | CM5T1A150AA                              |                                          | CM5T-1A180-AA/<br>CM5T-1A150-AA                         |
| C0668 | US | Ford    | Crown Victoria | 2011/01-2011/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Lear        | 6F2Z1A189A                               |                                          |                                                         |
| C0669 | US | Ford    | Crown Victoria | 2010/01-2010/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Lear        | 6F2Z1A189A                               |                                          |                                                         |
| C0670 | US | Ford    | Crown Victoria | 2009/01-2009/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Lear        | 6F2Z1A189A                               |                                          |                                                         |
| C0671 | US | Ford    | Crown Victoria | 2008/01-2008/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Lear        | 6F2Z1A189A                               |                                          |                                                         |
| C0672 | US | Ford    | Crown Victoria | 2007/01-2007/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Lear        | 6F2Z1A189A                               |                                          |                                                         |
| C0673 | US | Ford    | Crown Victoria | 2006/01-2006/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Lear        | 6F2Z1A189A                               |                                          |                                                         |
| C0674 | US | Ford    | E-150          | 2010/01-2016/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Schrader    | CM5T1A150AA                              |                                          | CM5T-1A180-AA/<br>CM5T-1A150-AA                         |
| C0675 | US | Ford    | E-150          | 2009/01-2009/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Lear        | 8C2Z1A189A                               |                                          |                                                         |
| C0676 | US | Ford    | E-150          | 2008/01-2008/12 | 315MHz | ● | ● | 4   | S | 315Mhz | Lear        | 8C2Z1A189A                               |                                          |                                                         |

|       |    |          |            |                 |              |   |   |   |   |        |          |                             |  |                                 |
|-------|----|----------|------------|-----------------|--------------|---|---|---|---|--------|----------|-----------------------------|--|---------------------------------|
| C0677 | US | Ford     | E-150      | 2007/01-2007/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 8C2Z1A189A                  |  |                                 |
| C0678 | US | Ford     | E-250      | 2010/01-2016/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0679 | US | Ford     | E-250      | 2009/01-2009/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 8C2Z1A189A                  |  |                                 |
| C0680 | US | Ford     | E-250      | 2008/01-2008/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 8C2Z1A189A                  |  |                                 |
| C0681 | US | Ford     | E-250      | 2007/01-2007/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 8C2Z1A189A                  |  |                                 |
| C0682 | US | Ford     | E-350 SD   | 2010/01-2016/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0683 | US | Ford     | E-350 SD   | 2009/01-2009/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 8C2Z1A189A                  |  |                                 |
| C0684 | US | Ford     | E-350 SD   | 2008/01-2008/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 8C2Z1A189A                  |  |                                 |
| C0685 | US | Ford     | E-350 SD   | 2007/01-2007/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 8C2Z1A189A                  |  |                                 |
| C0686 | US | Ford     | Edge       | 2015/01-2016/12 | 315MHz       | ○ | ● | 4 | S | 315Mhz | Schrader | F2GT1A180AB                 |  | F2GT1A180AB                     |
| C0687 | US | Ford     | Edge       | 2013/01-2014/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0688 | US | Ford     | Edge       | 2012/01-2012/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0689 | US | Ford     | Edge       | 2011/01-2011/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0690 | US | Ford     | Edge       | 2007/01-2010/12 | th Chrome ri | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A                  |  |                                 |
| C0691 | US | Ford     | Edge       | 2007/01-2010/12 | o Chrome rim | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A                  |  |                                 |
| C0692 | US | Ford     | Escape     | 2015/01-2015/12 | 315MHz       | ○ | ● | 4 |   | 315Mhz | Schrader | 9L3Z1A189A                  |  | 9L3Z-1A189-A                    |
| C0693 | US | Ford     | Escape     | 2013/01-2014/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0694 | US | Ford     | Escape     | 2012/01-2012/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0695 | US | Ford     | Escape     | 2011/01-2011/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0696 | US | Ford     | Escape     | 2010/01-2010/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0697 | US | Ford     | Escape     | 2009/01-2009/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0698 | US | Ford     | Escape     | 2008/01-2008/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                  |  |                                 |
| C0699 | US | Ford     | Escape     | 2007/01-2007/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                  |  |                                 |
| C0700 | US | Ford     | Escape     | 2006/01-2006/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                  |  |                                 |
| C0701 | US | Ford     | Escape     | 2005/01-2005/12 | 315MHz       | ○ | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                  |  |                                 |
| C0702 | US | Ford     | Expedition | 2012/01-2016/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0352 | US | Cadillac | ELR        | 2014/01-2016/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | 22854866/<br>20922900       |  | 22854866/<br>20922900           |
| C0704 | US | Ford     | Expedition | 2010/01-2010/12 | th Chrome ri | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                  |  |                                 |
| C0705 | US | Ford     | Expedition | 2010/01-2010/12 | o Chrome rim | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A                  |  |                                 |
| C0706 | US | Ford     | Expedition | 2009/01-2009/12 | th Chrome ri | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                  |  |                                 |
| C0707 | US | Ford     | Expedition | 2009/01-2009/12 | o Chrome rim | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A                  |  |                                 |
| C0708 | US | Ford     | Expedition | 2008/01-2008/12 | th Chrome ri | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                  |  |                                 |
| C0709 | US | Ford     | Expedition | 2008/01-2008/12 | o Chrome rim | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A                  |  |                                 |
| C0710 | US | Ford     | Expedition | 2007/01-2007/12 | th Chrome ri | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                  |  |                                 |
| C0711 | US | Ford     | Expedition | 2007/01-2007/12 | o Chrome rim | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A                  |  |                                 |
| C0712 | US | Ford     | Expedition | 2005/01-2006/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | 5L7Z1A150AA                 |  | 5L7Z-1A150-AA                   |
| C0713 | US | Ford     | Expedition | 2004/01-2004/12 | 433MHz       | ● | ● | 4 | S | 433Mhz | Schrader | 4L2T1A150BA/<br>4L2Z1A150BA |  | 4L2T1A150BA/<br>4L2Z1A150BA     |
| C0714 | US | Ford     | Expedition | 2003/01-2003/12 | 433MHz       | ● | ● | 4 | S | 433Mhz | Schrader | 4L2T1A150BA/<br>4L2Z1A150BA |  | 4L2T1A150BA/<br>4L2Z1A150BA     |
| A0030 | EU | Hyundai  | i40        | 2011/01-2013/07 |              | ● | ● | 4 | 0 | 433Mhz | TRW      | 529333V100                  |  | 52933-3V100                     |
| C0717 | US | Ford     | Explorer   | 2012/01-2012/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0718 | US | Ford     | Explorer   | 2011/01-2011/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |

|       |    |      |                     |                 |        |   |   |   |   |        |          |                                             |  |                                                   |
|-------|----|------|---------------------|-----------------|--------|---|---|---|---|--------|----------|---------------------------------------------|--|---------------------------------------------------|
| C0719 | US | Ford | Explorer            | 2010/01-2010/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0720 | US | Ford | Explorer            | 2009/01-2009/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0721 | US | Ford | Explorer            | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0722 | US | Ford | Explorer            | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0723 | US | Ford | Explorer            | 2006/01-2006/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0724 | US | Ford | Explorer            | 2005/01-2005/12 | 433MHz | ● | ● | 4 | S | 433Mhz | Schrader | 4L2Z1A150BB/<br>4L2Z1A150BA/<br>4L2T1A150BA |  | 4L2Z-1A150-BB/<br>4L2Z-1A150-BA/<br>4L2T-1A150-BA |
| C0725 | US | Ford | Explorer            | 2004/01-2004/12 | 433MHz | ● | ● | 4 | S | 433Mhz | Schrader | 4L2Z1A150BB/<br>4L2Z1A150BA/<br>4L2T1A150BA |  | 4L2Z-1A150-BB/<br>4L2Z-1A150-BA/<br>4L2T-1A150-BA |
| C0726 | US | Ford | Explorer            | 2003/01-2003/12 | 433MHz | ● | ● | 4 | S | 433Mhz | Schrader | 4L2Z1A150BB/<br>4L2Z1A150BA/<br>4L2T1A150BA |  | 4L2Z-1A150-BB/<br>4L2Z-1A150-BA/<br>4L2T-1A150-BA |
| C0727 | US | Ford | Explorer            | 2002/01-2002/12 | 433MHz | ● | ● | 4 | S | 433Mhz | Schrader | 4L2Z1A150BB/<br>4L2Z1A150BA/<br>4L2T1A150BA |  | 4L2Z-1A150-BB/<br>4L2Z-1A150-BA/<br>4L2T-1A150-BA |
| C0728 | US | Ford | Explorer Sport Trac | 2010/01-2010/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0729 | US | Ford | Explorer Sport Trac | 2009/01-2009/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0730 | US | Ford | Explorer Sport Trac | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0731 | US | Ford | Explorer Sport Trac | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0732 | US | Ford | Explorer Sport Trac | 2006/01-2006/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0733 | US | Ford | F-150               | 2016/01-2016/12 | 315MHz | ○ | ● | 4 |   | 315Mhz | Schrader | F2GZ1A189A                                  |  | F2GZ1A189A                                        |
| C0734 | US | Ford | F-150               | 2015/01-2015/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader | F2GT1A180AB                                 |  | F2GT1A180AB                                       |
| C0735 | US | Ford | F-150               | 2012/01-2014/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0736 | US | Ford | F-150               | 2011/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0737 | US | Ford | F-150               | 2009/01-2010/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0738 | US | Ford | F-150               | 2007/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0739 | US | Ford | F-150 HD            | 2015/01-2015/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader | F2GT1A180AB                                 |  | F2GT1A180AB                                       |
| C0740 | US | Ford | F-150 HD            | 2011/01-2014/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0741 | US | Ford | F-150 HD            | 2008/01-2010/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Lear     | 8C2Z1A189A                                  |  |                                                   |
| C0742 | US | Ford | F-250 Banded        | 2008/01-2010/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Lear     | 8C2Z1A189A                                  |  |                                                   |
| C0743 | US | Ford | F-250 Snap in       | 2010/01-2016/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0744 | US | Ford | F-350 Banded        | 2008/01-2010/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Lear     | 8C2Z1A189A                                  |  |                                                   |
| C0745 | US | Ford | F-350 Snap in       | 2010/01-2016/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0746 | US | Ford | F-450 SD            | 2016/01-2016/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader | DE8T1A180AA                                 |  | DE8T-1A180-AA/<br>DE8T-1A150-AA                   |
| C0747 | US | Ford | F-450/550           | 2012/01-2014/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0748 | US | Ford | F-450/550           | 2010/01-2011/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0749 | US | Ford | F-450/550           | 2008/01-2009/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Lear     | 8C2Z1A189A                                  |  |                                                   |
| C0750 | US | Ford | Fiesta              | 2011/01-2016/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0751 | US | Ford | Five Hundred        | 2008/01-2009/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0752 | US | Ford | Five Hundred        | 2006/01-2007/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A                                  |  |                                                   |
| C0753 | US | Ford | Flex                | 2016/01-2016/12 | 315MHz | ○ | ● | 4 |   | 315Mhz | Schrader | F2GZ1A189A                                  |  | F2GZ1A189A                                        |
| C0754 | US | Ford | Flex                | 2013/01-2015/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0755 | US | Ford | Flex                | 2012/01-2012/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |

|       |    |      |                     |                 |        |   |   |   |     |        |             |                             |             |                                 |
|-------|----|------|---------------------|-----------------|--------|---|---|---|-----|--------|-------------|-----------------------------|-------------|---------------------------------|
| C0756 | US | Ford | Flex                | 2011/01-2011/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0757 | US | Ford | Flex                | 2009/01-2010/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 7L1Z1A189A                  |             |                                 |
| C0758 | US | Ford | Focus               | 2012/01-2016/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0759 | US | Ford | Focus               | 2010/01-2011/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0760 | US | Ford | Focus               | 2008/01-2009/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 7L1Z1A189A                  |             |                                 |
| C0761 | US | Ford | Focus               | 2007/01-2007/12 | 315MHz | ○ | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0762 | US | Ford | Freestar            | 2006/01-2007/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0763 | US | Ford | Freestar            | 2005/01-2005/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 5L7Z1A150AA                 |             | 5L7Z-1A150-AA                   |
| C0764 | US | Ford | Freestar            | 2004/01-2004/12 | 315MHz | ○ | ● | 4 | S   | 315Mhz | Schrader    | 5L7Z1A150AA                 |             | 5L7Z-1A150-AA                   |
| C0765 | US | Ford | Fusion              | 2012/01-2016/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0766 | US | Ford | Fusion              | 2010/01-2011/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0767 | US | Ford | Fusion              | 2009/01-2009/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0768 | US | Ford | Fusion              | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0769 | US | Ford | Fusion              | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0770 | US | Ford | Mustang             | 2015/01-2016/12 | 315MHz | ○ | ● | 4 | S   | 315Mhz | Schrader    | F2GT1A180AB                 |             | F2GT1A180AB                     |
| C0771 | US | Ford | Mustang             | 2012/01-2014/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0772 | US | Ford | Mustang             | 2010/01-2011/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0773 | US | Ford | Mustang             | 2009/01-2009/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0774 | US | Ford | Mustang             | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0775 | US | Ford | Mustang             | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0776 | US | Ford | Mustang (Euro Spec) | 2015/01-2016/12 | 433MHz | ○ | ● | 4 | A/S | 433Mhz | Schrader    | F2GZ1A189B                  |             | F2GT1A180CB<br>F2GT1A150CB      |
| C0777 | US | Ford | Ranger              | 2008/01-2011/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0778 | US | Ford | Ranger              | 2007/01-2007/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Lear        | 6F2Z1A189A                  |             |                                 |
| C0779 | US | Ford | Shelby GT           | 2013/01-2015/12 | 433MHz | ○ | ● | 4 | A   | 433Mhz | Schrader    | DR3V1A180BA/<br>DR3V1A180BB |             | DR3V1A180BA/<br>DR3V1A180BB     |
| C0780 | US | Ford | Shelby GT           | 2012/01-2012/12 | 315MHz | ○ | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0781 | US | Ford | Taurus              | 2013/01-2016/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0782 | US | Ford | Taurus              | 2012/01-2012/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0783 | US | Ford | Taurus              | 2011/01-2011/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0784 | US | Ford | Taurus              | 2008/01-2010/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 7L1Z1A189A                  |             |                                 |
| C0785 | US | Ford | Taurus X            | 2008/01-2009/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 7L1Z1A189A                  |             |                                 |
| C0786 | US | Ford | Transit 150         | 2016/01-2016/12 | 315MHz | ○ | ● | 4 | S   | 315Mhz | Schrader    | DE8T1A180AA                 |             | DE8T-1A180-AA/<br>DE8T-1A150-AA |
| C0787 | US | Ford | Transit 250         | 2016/01-2016/12 | 315MHz | ○ | ● | 4 | S   | 315Mhz | Schrader    | DE8T1A180AA                 |             | DE8T-1A180-AA/<br>DE8T-1A150-AA |
| C0788 | US | Ford | Transit 350         | 2016/01-2016/12 | 315MHz | ○ | ● | 4 | S   | 315Mhz | Schrader    | DE8T1A180AA                 |             | DE8T-1A180-AA/<br>DE8T-1A150-AA |
| C0789 | US | Ford | Transit connect     | 2012/01-2016/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0790 | US | Ford | Transit connect     | 2010/01-2011/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | CM5T1A150AA                 |             | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0794 | US | GMC  | Acadia              | 2016/01-2016/12 | 433MHz | ○ | ● | 4 | S   | 433Mhz | Schrader    | 22853740                    | 90518185    | 22853740                        |
| C0795 | US | GMC  | Acadia              | 2009/01-2016/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 25920615/<br>20923680       |             | 25920615/<br>20923680           |
| C0796 | US | GMC  | Acadia              | 2007/01-2008/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Continental | 15921013                    | S120123009A |                                 |
| C0800 | US | GMC  | Canyon              | 2015/01-2016/12 | 315MHz | ● | ● | 4 | S   | 315Mhz | Schrader    | 13581558                    |             | 13581558                        |

|       |    |        |                      |                 |              |   |   |     |   |        |             |                                    |                           |                                    |
|-------|----|--------|----------------------|-----------------|--------------|---|---|-----|---|--------|-------------|------------------------------------|---------------------------|------------------------------------|
| C0801 | US | GMC    | Canyon               | 2011/01-2012/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 15122618                           |                           | 15122618                           |
| C0802 | US | GMC    | Canyon               | 2007/01-2010/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 15122618                           |                           | 15122618                           |
| C0803 | US | GMC    | Envoy                | 2006/01-2006/12 | 315MHz       | ○ | ● | 4   | S | 315Mhz | Schrader    | 25774006                           |                           | 25774006                           |
| C0804 | US | GMC    | Envoy                | 2005/01-2005/12 | 315MHz       | ○ | ● | 4   | S | 315Mhz | Schrader    | 25774006                           |                           | 25774006                           |
| C0805 | US | GMC    | Envoy (NO. 15825475) | 2007/01-2007/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | TRW         | 15825475                           |                           | 15825475                           |
| C0806 | US | GMC    | Envoy (NO. 25774006) | 2008/01-2009/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25774006                           |                           | 25774006                           |
| C0807 | US | GMC    | Envoy (NO. 25774006) | 2007/01-2007/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25774006                           |                           | 25774006                           |
| C0808 | US | GMC    | Envoy (NO. 25920615) | 2008/01-2009/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25920615                           |                           | 25920615                           |
| C0809 | US | GMC    | Envoy (NO. 25920615) | 2007/01-2007/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25920615                           |                           | 25920615                           |
| C0814 | US | GMC    | Savana               | 2016/01-2016/12 | 315MHz       | ○ | ● | 4   |   | 315Mhz | Schrader    | 13586335                           |                           | 13586335                           |
| C0815 | US | GMC    | Savana               | 2010/01-2015/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25920615/<br>20923680              |                           | 25920615/20923680                  |
| C0816 | US | GMC    | Savana               | 2008/01-2009/12 | 315MHz       | ○ | ● | 4   | S | 315Mhz | Continental | 15921013                           | S120123009A               |                                    |
| C0817 | US | GMC    | Sierra               | 2014/01-2016/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 13581558                           |                           | 13581558                           |
| C0818 | US | GMC    | Sierra               | 2009/01-2013/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25920615/<br>20923680/<br>13586335 |                           | 25920615/<br>20923680/<br>13586335 |
| C0819 | US | GMC    | Sierra               | 2008/01-2008/12 | TRW clamp in | ● | ● | 4   | S | 315Mhz | Schrader    | 25920615/<br>20923680/<br>13586335 |                           | 25920615/<br>20923680/<br>13586335 |
| C0820 | US | GMC    | Sierra               | 2007/01-2007/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25920615                           |                           | 25920615                           |
| C0821 | US | GMC    | Sierra               | 2005/01-2006/12 | 315MHz       | ○ | ● | 4   | S | 315Mhz | Schrader    | 15114379                           |                           | 15114379                           |
| C0822 | US | GMC    | Sierra               | 2004/01-2004/12 | 315MHz       | ○ | ● | 4   | S | 315Mhz | Schrader    | 15136883                           |                           | 15136883                           |
| C0824 | US | GMC    | Terrain              | 2015/01-2016/12 | 433MHz       | ● | ● | 4   | S | 433Mhz | Schrader    | 13581561/<br>13598773              | 90518185                  |                                    |
| C0825 | US | GMC    | Terrain              | 2012/01-2014/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |                           | 12768826/<br>20922900/<br>22854866 |
| C0826 | US | GMC    | Terrain              | 2010/01-2011/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |                           | 12768826/<br>20922900/<br>22854866 |
| C0828 | US | GMC    | Yukon All            | 2014/01-2016/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25920615/<br>20923680/<br>13586335 |                           | 25920615/<br>20923680/<br>13586335 |
| C0829 | US | GMC    | Yukon All            | 2009/01-2013/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25920615/<br>20923680/<br>13586335 |                           | 25920615/<br>20923680/<br>13586335 |
| C0830 | US | GMC    | Yukon All            | 2008/01-2008/12 | 315MHz       | ● | ● | 4   | S | 315Mhz | Schrader    | 25920615/<br>20923680/<br>13586335 |                           | 25920615/<br>20923680/<br>13586335 |
| C0831 | US | GMC    | Yukon All            | 2007/01-2007/12 | Clamp in     | ● | ● | 4   | S | 315Mhz | TRW         | 15825475                           |                           |                                    |
| C0832 | US | GMC    | Yukon All            | 2007/01-2007/12 | Snap in      | ● | ● | 4   | S | 315Mhz | Schrader    | 20923680/<br>25920615/<br>13586335 |                           | 20923680/<br>25920615/<br>13586335 |
| C0833 | US | GMC    | Yukon All            | 2005/01-2006/12 | 315MHz       | ○ | ● | 4   | S | 315Mhz | Schrader    | 15114379                           |                           | 15114379                           |
| C0834 | US | GMC    | Yukon All            | 2004/01-2004/12 | 315MHz       | ○ | ● | 4   | S | 315Mhz | Schrader    | 15136883                           |                           | 15136883                           |
| C0837 | US | Hummer | H2                   | 2009/01-2010/12 | 315MHz       | ● | ● | 4/5 | S | 315Mhz | Schrader    | 25920615/<br>20923680              |                           | 25920615/<br>20923680              |
| C0838 | US | Hummer | H2                   | 2008/01-2008/12 | 315MHz       | ● | ● | 4/5 | S | 315Mhz | Schrader    | 25920615/<br>20923680              |                           | 25920615/<br>20923680              |
| C0839 | US | Hummer | H3                   | 2007/01-2010/12 | 315MHz       | ● | ● | 4/5 | S | 315Mhz | Schrader    | 20927604/<br>15122618              |                           | 15122618/<br>20927604              |
| C0840 | US | Hummer | H3                   | 2006/01-2006/12 | 315MHz       | ● | ● | 4/5 | S | 315Mhz | Schrader    | 20927604/<br>15122618              |                           | 15122618/<br>20927604              |
| C0841 | US | Hummer | H3T                  | 2006/01-2010/12 | 315MHz       | ○ | ● | 4/5 | S | 315Mhz | Schrader    | 20927604/<br>15122618              |                           | 15122618/<br>20927604              |
| C0842 | US | Jeep   | Cherokee             | 2013/10-2015/12 | 433MHz       | ● | ● | 4/5 | A | 433Mhz | TRW         | 68157568AB/<br>68239720AA          | 231008-109/<br>231008-101 | 68239720AA/<br>68157568AB          |

|       |    |         |                     |                 |        |   |   |     |     |        |             |                                             |  |                                                   |
|-------|----|---------|---------------------|-----------------|--------|---|---|-----|-----|--------|-------------|---------------------------------------------|--|---------------------------------------------------|
| C0843 | US | Jeep    | Commander           | 2008/01-2011/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029359AB                                  |  | 56029359AC/<br>56029359AB/<br>56029359AA/         |
| C0844 | US | Jeep    | Commander           | 2006/01-2007/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Schrader    | 56029465AB                                  |  | 56029465AB                                        |
| C0845 | US | Jeep    | Compass             | 2012/01-2015/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 56029479AA                                  |  | 56029479AA/<br>56029479AB                         |
| C0846 | US | Jeep    | Compass             | 2010/01-2011/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 68001696AA/<br>68001696AB                   |  | 68001696AA/<br>68001696AB                         |
| C0847 | US | Jeep    | Compass             | 2008/01-2009/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 68001696AA/<br>68001696AB                   |  | 68001696AA/<br>68001696AB                         |
| C0848 | US | Jeep    | Compass             | 2007/01-2007/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 68001696AA/<br>68001696AB                   |  | 68001696AA/<br>68001696AB                         |
| C0849 | US | Jeep    | Grand Cherokee      | 2011/01-2015/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029398AB                                  |  | 56029398AA/<br>56029398AB                         |
| C0850 | US | Jeep    | Grand Cherokee      | 2008/01-2010/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029359AC                                  |  | 56029359AC/<br>56029359AB/<br>56029359AA/         |
| C0851 | US | Jeep    | Grand Cherokee      | 2007/01-2007/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Schrader    | 56053036AA                                  |  | 56053036AA                                        |
| C0852 | US | Jeep    | Grand Cherokee      | 2004/05-2006/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 56053030AB/<br>56053030AC                   |  | 56053030AC/<br>56053030AB                         |
| C0853 | US | Jeep    | Grand Cherokee      | 2002/01-2004/12 | 433MHz | ● | ● | 4/5 | S   | 433Mhz | Schrader    | 52088990AD                                  |  | 52088990AD                                        |
| C0854 | US | Jeep    | Grand Cherokee SRT8 | 2012/01-2015/12 | 433MHz | ○ | ● | 4/5 |     | 433Mhz | Schrader    | 56029400AE                                  |  | 56029400AE                                        |
| C0855 | US | Jeep    | Liberty             | 2010/01-2012/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 68001696AA                                  |  | 68001696AA/<br>68001696AB                         |
| C0856 | US | Jeep    | Liberty             | 2009/01-2009/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029359AC                                  |  | 56029359AC/<br>56029359AB/<br>56029359AA/         |
| C0857 | US | Jeep    | Liberty             | 2007/01-2009/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Schrader    | 56029465AB                                  |  | 56029465AB                                        |
| C0858 | US | Jeep    | Liberty             | 2005/01-2006/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Schrader    | 56029465AB                                  |  | 56029465AB                                        |
| C0859 | US | Jeep    | Liberty             | 2004/01-2004/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 52088990AD                                  |  | 52088990AD                                        |
| C0860 | US | Jeep    | Patriot             | 2007/01-2015/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Continental | 68001696AA                                  |  | 68001696AA/<br>68001696AB                         |
| C0861 | US | Jeep    | Renegade            | 2015/01-2015/12 | 433Mhz | ● | ● | 4/5 |     | 433Mhz | Continental | 68105280AF                                  |  |                                                   |
| C0862 | US | Jeep    | Wrangler            | 2013/01-2015/12 | 433MHz | ● | ● | 4/5 | A   | 433Mhz | Schrader    | 56029398AB                                  |  | 56029398AA/<br>56029398AB                         |
| C0864 | US | Jeep    | Wrangler            | 2010/01-2012/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Schrader    | 56029479AA                                  |  | 56029479AA                                        |
| C0865 | US | Jeep    | Wrangler            | 2009/01-2009/12 | 433MHz | ● | ● | 4/5 | A/O | 433Mhz | Schrader    | 56029359AC                                  |  | 56029359AC/<br>56029359AB/<br>56029359AA/         |
| C0866 | US | Jeep    | Wrangler            | 2009/01-2009/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Schrader    | 56029465AB                                  |  | 56029479AA/<br>56029465AB                         |
| C0867 | US | Jeep    | Wrangler            | 2007/01-2008/12 | 315MHz | ● | ● | 4/5 | A   | 315Mhz | Schrader    | 56029465AB                                  |  | 56029465AB                                        |
| C0868 | US | Lincoln | Aviator             | 2004/01-2005/12 | 433MHz | ● | ● | 4   | S   | 433Mhz | Schrader    | 4L2Z1A150BB/<br>4L2Z1A150BA/<br>4L2T1A150BA |  | 4L2Z-1A150-BB/<br>4L2Z-1A150-BA/<br>4L2T-1A150-BA |
| C0869 | US | Lincoln | Aviator             | 2003/01-2003/12 | 433MHz | ● | ● | 4   | S   | 433Mhz | Schrader    | 4L2Z1A150BB/<br>4L2Z1A150BA/<br>4L2T1A150BA |  | 4L2Z-1A150-BB/<br>4L2Z-1A150-BA/<br>4L2T-1A150-BA |
| C0870 | US | Lincoln | Mark LT             | 2015/01-2016/12 | 315MHz | ○ | ● | 4   | S   | 315Mhz | Schrader    | F2GT1A180AB                                 |  | F2GT1A180AB                                       |
| C0871 | US | Lincoln | Mark LT             | 2013/01-2014/12 | 315MHz | ○ | ● | 4   | S   | 315Mhz | Schrader    | DE8T1A180AA                                 |  | DE8T-1A180-AA/<br>DE8T-1A150-AA                   |
| C0872 | US | Lincoln | Mark LT             | 2009/01-2009/12 | 315MHz | ○ | ● | 4   | S   | 315Mhz | Schrader    | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0873 | US | Lincoln | Mark LT             | 2007/01-2008/12 | 315MHz | ● | ● | 4   | S   | 315Mhz | Lear        | 6F2Z1A189A                                  |  |                                                   |
| C0874 | US | Lincoln | MKC                 | 2016/01-2016/12 | 315Mhz | ○ | ● | 4   |     | 315Mhz | Schrader    | 9L3Z1A189A                                  |  | 9L3Z-1A189-A                                      |
| C0875 | US | Lincoln | MKC                 | 2015/01-2015/12 | 315MHz | ○ | ● | 4   | A   | 315Mhz | Schrader    | CM5T1A150AA                                 |  | CM5T-1A180-AA/<br>CM5T-1A150-AA                   |
| C0876 | US | Lincoln | MKS                 | 2016/01-2016/12 | 315MHz | ○ | ● | 4   |     | 315Mhz | Schrader    | F2GZ1A189A                                  |  | F2GZ1A189A                                        |

|       |    |          |              |                 |              |   |   |   |   |        |          |             |           |                                 |
|-------|----|----------|--------------|-----------------|--------------|---|---|---|---|--------|----------|-------------|-----------|---------------------------------|
| C0877 | US | Lincoln  | MKS          | 2013/01-2015/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0878 | US | Lincoln  | MKS          | 2012/01-2012/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0879 | US | Lincoln  | MKS          | 2011/01-2011/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0880 | US | Lincoln  | MKS          | 2009/01-2010/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A  |           |                                 |
| C0881 | US | Lincoln  | MKT          | 2016/01-2016/12 | 315Mhz       | ○ | ● | 4 |   | 315Mhz | Schrader | 9L3Z1A189A  |           | 9L3Z-1A189-A                    |
| C0882 | US | Lincoln  | MKT          | 2016/01-2016/12 | 433Mhz       | ○ | ● | 4 |   | 433Mhz | Schrader | BB5Z1A189A  |           | BB5Z1A189A                      |
| C0883 | US | Lincoln  | MKT          | 2013/01-2015/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0884 | US | Lincoln  | MKT          | 2012/01-2012/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0885 | US | Lincoln  | MKT          | 2011/01-2011/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0886 | US | Lincoln  | MKT          | 2010/01-2010/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A  |           |                                 |
| C0887 | US | Lincoln  | MKX          | 2016/01-2016/12 | 315Mhz       | ○ | ● | 4 |   | 315Mhz | Schrader | 9L3Z1A189A  |           | 9L3Z-1A189-A                    |
| C0888 | US | Lincoln  | MKX          | 2016/01-2016/12 | 433Mhz       | ○ | ● | 4 |   | 433Mhz | Schrader | BB5Z1A189A  |           | BB5Z1A189A                      |
| C0889 | US | Lincoln  | MKX          | 2013/01-2015/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0890 | US | Lincoln  | MKX          | 2012/01-2012/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0891 | US | Lincoln  | MKX          | 2011/01-2011/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0892 | US | Lincoln  | MKX          | 2008/01-2010/12 | th Chrome r  | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A  |           |                                 |
| C0893 | US | Lincoln  | MKX          | 2008/01-2010/12 | o Chrome rim | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A  |           |                                 |
| C0894 | US | Lincoln  | MKX          | 2007/01-2007/12 | th Chrome r  | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A  |           |                                 |
| C0895 | US | Lincoln  | MKX          | 2007/01-2007/12 | o Chrome rim | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A  |           |                                 |
| C0896 | US | Lincoln  | MKZ          | 2016/01-2016/12 | 315Mhz       | ○ | ● | 4 |   | 315Mhz | Schrader | 9L3Z1A189A  |           | 9L3Z-1A189-A                    |
| C0897 | US | Lincoln  | MKZ          | 2012/01-2015/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0898 | US | Lincoln  | MKZ          | 2010/01-2011/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0899 | US | Lincoln  | MKZ          | 2008/01-2009/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A  |           |                                 |
| C0900 | US | Lincoln  | MKZ          | 2007/01-2007/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A  |           |                                 |
| C0901 | US | Lincoln  | Navigator    | 2012/01-2015/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0902 | US | Lincoln  | Navigator    | 2011/01-2011/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0903 | US | Lincoln  | Navigator    | 2008/01-2010/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A  |           |                                 |
| C0904 | US | Lincoln  | Navigator    | 2007/01-2007/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | 7L1Z1A189A  |           |                                 |
| C0905 | US | Lincoln  | Navigator    | 2005/01-2006/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Schrader | 5L1Z1A150AA |           | 5L1Z-1A150-AA                   |
| C0906 | US | Lincoln  | Navigator    | 2004/01-2004/12 | 433MHz       | ● | ● | 4 | S | 433Mhz | Schrader | 4L2Z1A150BA |           | 4L2Z-1A150-BA                   |
| C0907 | US | Lincoln  | Navigator    | 2003/01-2003/12 | 433MHz       | ● | ● | 4 | S | 433Mhz | Schrader | 4L2Z1A150BA |           | 4L2Z-1A150-BA                   |
| C0908 | US | Lincoln  | Town Car     | 2012/01-2012/12 | 315MHz       | ○ | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |           | CM5T-1A180-AA/<br>CM5T-1A150-AA |
| C0909 | US | Lincoln  | Town Car     | 2010/01-2011/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A  |           |                                 |
| C0910 | US | Lincoln  | Town Car     | 2009/01-2009/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A  |           |                                 |
| C0911 | US | Lincoln  | Town Car     | 2008/01-2008/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A  |           |                                 |
| C0912 | US | Lincoln  | Town Car     | 2006/01-2007/12 | 315MHz       | ● | ● | 4 | S | 315Mhz | Lear     | 6F2Z1A189A  |           |                                 |
| C0913 | US | Lotus    | Elise        | 2008/01-2011/12 | 433MHz       | ○ | ● | 4 |   | 433Mhz | Schrader | 13227143    |           | 13227143                        |
| C0914 | US | Lotus    | Evora        | 2010/01-2011/12 | 433MHz       | ○ | ● | 4 |   | 433Mhz | Schrader | 13227143    |           | 13227143                        |
| C0915 | US | Lotus    | Exige        | 2008/01-2011/12 | 433MHz       | ○ | ● | 4 |   | 433Mhz | Schrader | 13227143    |           | 13227143                        |
| C0916 | US | Maserati | Coupe        | 2004/01-2011/12 | 433MHz       | ○ | ● | 4 | A | 433Mhz | Huf/Beru | 282189      | 532207011 | RDE011                          |
| C0917 | US | Maserati | Quattroporte | 2010/01-2011/12 | 433MHz       | ○ | ● | 4 | A | 433Mhz | Huf/Beru | 224549      | 532207001 | RDE001                          |
| C0918 | US | Maserati | Quattroporte | 2004/01-2009/12 | 433MHz       | ○ | ● | 4 | A | 433Mhz | Huf/Beru | 312450      | 532207001 | RDE001                          |
| C0919 | US | Mazda    | B Pickup     | 2009/01-2013/12 | 315MHz       | ○ | ● | 4 | S | 315Mhz | Schrader | ZZDA37140   |           | ZZDA-37-140                     |

|       |    |         |               |                 |        |   |   |   |   |        |             |                           |             |                       |
|-------|----|---------|---------------|-----------------|--------|---|---|---|---|--------|-------------|---------------------------|-------------|-----------------------|
| C0920 | US | Mazda   | B Pickup      | 2007/01-2008/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0921 | US | Mazda   | CX-7          | 2011/01-2012/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0922 | US | Mazda   | CX-7          | 2010/01-2010/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0923 | US | Mazda   | CX-7          | 2007/01-2009/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0924 | US | Mazda   | CX-9          | 2007/01-2015/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B/<br>BHA437140  | S180052019H | S180052019            |
| C0925 | US | Mazda   | Mazda 2       | 2011/01-2014/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0926 | US | Mazda   | Mazda 3       | 2010/01-2014/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0927 | US | Mazda   | Mazda 3       | 2007/01-2009/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0928 | US | Mazda   | Mazda 3       | 2005/01-2006/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0929 | US | Mazda   | Mazda 3       | 2004/01-2004/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B/<br>FE0137140A | S180052019H | S180052019            |
| C0930 | US | Mazda   | Mazda 5       | 2011/01-2015/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0931 | US | Mazda   | Mazda 5       | 2008/01-2010/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0932 | US | Mazda   | Mazda 5       | 2006/01-2007/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0933 | US | Mazda   | Mazda 6       | 2011/01-2014/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0934 | US | Mazda   | Mazda 6       | 2009/01-2010/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0935 | US | Mazda   | Mazda 6       | 2008/01-2008/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0936 | US | Mazda   | Mazda 6       | 2005/01-2007/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0937 | US | Mazda   | MX-5 Miata    | 2006/01-2015/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0938 | US | Mazda   | RX-8          | 2011/01-2015/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Continental | BBM237140B                | S180052019H | S180052019            |
| C0939 | US | Mazda   | RX-8          | 2009/01-2010/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B/<br>GN3A37140B | S180052019H | S180052019            |
| C0940 | US | Mazda   | RX-8          | 2005/01-2008/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | BBM237140B/<br>GN3A37140B | S180052019H | S180052019            |
| C0941 | US | Mazda   | RX-8          | 2004/01-2004/12 | 315MHz | ● | ● | 4 | A | 315Mhz | Continental | FE0137140A                | S180052019H | S180052019            |
| C0942 | US | Mazda   | Speed 3       | 2010/01-2012/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Continental | BBM237140B/<br>GN3A37140B | S180052019H | S180052019            |
| C0943 | US | Mazda   | Speed 6       | 2007/01-2008/12 | 315MHz | ○ | ● | 4 | A | 315Mhz | Continental | GN3A37140B                | S180052019H | S180052019            |
| C0944 | US | Mazda   | Tribute       | 2011/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | ZZDA37140                 |             | ZZDA-37-140           |
| C0945 | US | Mazda   | Tribute       | 2010/01-2010/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | ZZDA37140                 |             | ZZDA-37-140           |
| C0946 | US | Mazda   | Tribute       | 2009/01-2009/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | ZZDA37140                 |             | ZZDA-37-140           |
| C0947 | US | Mazda   | Tribute       | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0948 | US | Mazda   | Tribute       | 2006/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0949 | US | Mercury | Grand Marquis | 2009/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0950 | US | Mercury | Grand Marquis | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0951 | US | Mercury | Grand Marquis | 2006/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0952 | US | Mercury | Mariner       | 2011/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 9L3Z1A189A                |             | 9L3Z-1A189-A          |
| C0953 | US | Mercury | Mariner       | 2010/01-2010/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 9L3Z1A189A                |             | 9L3Z-1A189-A          |
| C0954 | US | Mercury | Mariner       | 2009/01-2009/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 9L3Z1A189A                |             | 9L3Z-1A189-A          |
| C0955 | US | Mercury | Mariner       | 2008/01-2008/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0956 | US | Mercury | Mariner       | 2006/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0957 | US | Mercury | Milan         | 2010/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 9L3Z1A189A                |             | 9L3Z-1A189-A          |
| C0958 | US | Mercury | Milan         | 2008/01-2009/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0959 | US | Mercury | Montego       | 2006/01-2007/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0960 | US | Mercury | Monterey      | 2006/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0961 | US | Mercury | Monterey      | 2005/01-2005/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 5L7Z1A150AA               |             | 5L7Z-1A150-AA         |
| C0962 | US | Mercury | Monterey      | 2004/01-2004/12 | 315MHz | ○ | ● | 4 | S | 315Mhz | Schrader    | 5L7Z1A150AA               |             | 5L7Z-1A150-AA         |
| C0963 | US | Mercury | Mountaineer   | 2008/01-2010/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0964 | US | Mercury | Mountaineer   | 2006/01-2007/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Lear        | 6F2Z1A189A                |             |                       |
| C0965 | US | Mercury | Mountaineer   | 2004/01-2005/12 | 433MHz | ● | ● | 4 | S | 433Mhz | Schrader    | 4L2Z1A150BA               |             | 4L2Z-1A150-BA         |
| C0966 | US | Mercury | Mountaineer   | 2002/01-2003/12 | 433MHz | ● | ● | 4 | S | 433Mhz | Schrader    | 4L2Z1A150BA               |             | 4L2Z-1A150-BA         |
| C0967 | US | Mercury | Sable         | 2008/01-2009/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 7L1Z1A189A                |             |                       |
| C0969 | US | Pontiac | G3            | 2009/01-2010/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader    | 25920615/<br>20923680     |             | 25920615/<br>20923680 |

|       |    |         |                  |                 |          |   |   |   |           |        |             |                                    |             |                                    |
|-------|----|---------|------------------|-----------------|----------|---|---|---|-----------|--------|-------------|------------------------------------|-------------|------------------------------------|
| C0971 | US | Pontiac | G5               | 2009/01-2010/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C0972 | US | Pontiac | G5               | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0973 | US | Pontiac | G6               | 2009/01-2010/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C0974 | US | Pontiac | G6               | 2008/01-2008/12 | Clamp in | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0975 | US | Pontiac | G6               | 2008/01-2008/12 | Snap in  | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C0976 | US | Pontiac | G8               | 2008/01-2009/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C0978 | US | Pontiac | Grand Prix       | 2008/01-2008/12 | Clamp in | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0979 | US | Pontiac | Grand Prix       | 2008/01-2008/12 | Snap in  | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C0980 | US | Pontiac | Grand Prix       | 2007/01-2007/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0981 | US | Pontiac | Montana          | 2008/01-2009/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 15268606                           |             | 15268606                           |
| C0982 | US | Pontiac | Solstice         | 2010/01-2010/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0983 | US | Pontiac | Solstice         | 2009/01-2009/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0984 | US | Pontiac | Solstice         | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C0985 | US | Pontiac | Torrent          | 2009/01-2009/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 10394110                           | S120123007B | S120123007                         |
| C0986 | US | Pontiac | Torrent          | 2007/01-2008/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 10394110                           | S120123007B | S120123007                         |
| C0987 | US | Pontiac | Vibe             | 2008/01-2010/12 | 315MHz   | ● | ● | 4 | Copy only | 315Mhz | Pacific     | 88974915                           | PMV-107J    | 88974915                           |
| C0989 | US | Pontiac | Wave             | 2008/01-2009/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C0990 | US | Saab    | 9月3日             | 2008/01-2012/12 | 433MHz   | ○ | ● | 4 | A         | 433Mhz | Schrader    | 13227143                           |             | 13227143                           |
| C0991 | US | Saab    | 9月3日             | 2004/01-2007/12 | 433MHz   | ○ | ● | 4 | A         | 433Mhz | Schrader    | 13172567                           |             | 13172567                           |
| C0992 | US | Saab    | 9-4X             | 2012/01-2012/12 | 315MHz   | ○ | ● | 4 | S         | 315Mhz | Schrader    | 20922900/<br>22854866/<br>12768826 |             | 20922900                           |
| C0994 | US | Saab    | 9月5日             | 2008/01-2012/12 | 433MHz   | ○ | ● | 4 | A         | 433Mhz | Schrader    | 13227143                           |             | 13227143                           |
| C0995 | US | Saab    | 9月5日             | 2004/01-2007/12 | 433MHz   | ○ | ● | 4 | A         | 433Mhz | Schrader    | 13172567                           |             | 13172567                           |
| C0996 | US | Saab    | 9-7X             | 2008/01-2009/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 25774006                           |             | 25774006                           |
| C0997 | US | Saab    | 9-7X             | 2005/01-2007/12 | 315MHz   | ○ | ● | 4 | S         | 315Mhz | Schrader    | 25774006                           |             | 25774006                           |
| C0998 | US | Saturn  | Astra            | 2010/01-2010/12 | 315MHz   | ○ | ● | 4 | S         | 315Mhz | Schrader    | 12768826/<br>20922900/<br>22854866 |             | 12768826/<br>20922900/<br>22854866 |
| C0999 | US | Saturn  | Astra            | 2008/01-2009/12 | 433MHz   | ○ | ● | 4 | S         | 433Mhz | Schrader    | 13172567                           |             | 13172567                           |
| C1000 | US | Saturn  | Aura             | 2009/01-2010/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C1001 | US | Saturn  | Aura             | 2008/01-2008/12 | Clamp in | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C1002 | US | Saturn  | Aura             | 2008/01-2008/12 | Snap in  | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C1003 | US | Saturn  | Aura             | 2007/01-2007/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C1006 | US | Saturn  | Lambda Crossover | 2007/01-2008/12 | 315MHz   | ○ | ● | 4 | S         | 315Mhz | Schrader    | 15268606                           |             | 15268606                           |
| C1007 | US | Saturn  | Outlook          | 2009/01-2010/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615                           |             | 25920615                           |
| C1008 | US | Saturn  | Outlook          | 2007/01-2008/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C1010 | US | Saturn  | Sky              | 2009/01-2009/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C1011 | US | Saturn  | Sky              | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Continental | 15921013                           | S120123009A |                                    |
| C1012 | US | Saturn  | Vue              | 2009/01-2010/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C1013 | US | Saturn  | Vue              | 2008/01-2008/12 | 315MHz   | ● | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C1014 | US | Saturn  | Vue              | 2007/01-2007/12 | 315MHz   | ○ | ● | 4 | S         | 315Mhz | Schrader    | 25920615/<br>20923680              |             | 25920615/<br>20923680              |
| C1017 | US | Tesla   | Model S          | 2014/10-2015/12 | 433MHz   | ○ | ● | 4 | A         | 433Mhz | Continental | 103460200A                         | S180052068Z | S180052068                         |
| C1018 | US | Tesla   | Model S          | 2014/01-2014/09 | 433MHz   | ○ | ● | 4 | S         | 433Mhz | Baolong     | 101093800B                         |             | FS43X0L3140418                     |
| C1019 | US | Tesla   | Model S          | 2013/01-2013/12 | 433MHz   | ○ | ● | 4 | S         | 433Mhz | Baolong     | FS15I1                             |             | FS15I1                             |
| A0031 | EU | Hyundai | i40              | 2013/08-2016/06 |          | ● | ● | 4 | A/O       | 433Mhz | TRW         | 529333V600                         |             | 52933-3V600                        |

|       |    |      |            |                 |        |   |   |   |   |        |          |             |  |                                 |
|-------|----|------|------------|-----------------|--------|---|---|---|---|--------|----------|-------------|--|---------------------------------|
| C0703 | US | Ford | Expedition | 2011/01-2011/12 | 315MHz | ● | ● | 4 | S | 315Mhz | Schrader | CM5T1A150AA |  | CM5T-1A180-AA/<br>CM5T-1A150-AA |
|-------|----|------|------------|-----------------|--------|---|---|---|---|--------|----------|-------------|--|---------------------------------|